www.drbworld.com





## AUTOMOTIVE

# V-RIBBED BELT

For Japanese Car

DRB



# DRB POWER TRANSMISSION BELT

DRB power transmission belt, essential for transferring power of all automotive, industrial and agricultural machines all over the world, have been accepted by customers as a pronoun for quality and reliability for over half a century. DRB power transmission belt are used as essential tools to transfer power of all machines and equipment used on a wide range of products in all heavy and light industries, including automotive, home and office appliances and equipment, chemicals, machinery, ships and farming equipment.

DRB has steadily improved the product quality and developed products for diverse applications through development of various synthetic rubber, fiber, chemicals and their processing techniques.



## Global Networks



Head Office and Plant



Yangsan Plant



DRB China



DRB America



DRB Slovakia



DRB Japan




DRB Vietnam



DRB Indonesia

# CORPORATE HISTORY

**1945** Established Dongil Chemical Works
**1947** Production of power transmission belt (V-belt) began
**1951** Prodauction of conveyor belt began
**1967** Production of Vehicle Sealing began
**1976** Stock exchanged in Korean Stock Market
**1983** Production of Construction Material began
**1984** Production of rubber track began
**1986** Established R&D Center
**1992** Built Yangsan plant for vehicle sealing
**1995** Obtained ISO9002 (KSA-QA) Certification
**2001** Implemented ERP(SAP) System
**2001** Established Qingdao Dongil Rubber Belt Co., Ltd. in China
**2004** Established Dongil Rubber Belt North America
**2005** Established Fukuoka office in Japan
**2007** Established Jakarta office in Indonesia
**2009** Established Hanoi office in Vietnam
**2010** Built Qingdao Dongil Culture Center
**2012** Divided by spin off into three companies
(DRB Holding Co., Ltd. DRB Industrial Co., Ltd. DRB International Co., Ltd.)







# RAW EDGE BELT

Made of high strength, flexible tension members and heat-resistant rubber compounds, these automotive belt are designed for high-speed and high-temperature conditions in specially designed shapes.

## Features

- Highly flexible and thus suitable for conditions requiring high flexibility and a small pulley diameter.
- Assures uniform performance over the entire belt length for the entire belt life.
- Resistant to heat, oil and abrasion.

## Construction & Materials



Top fabric : Features flexibility and resistance to heat, oil and abrasion.

Tension member : Made of highly strong cords with low stretchability, gives high flexibility and length stability.

Compression rubber : Made of fiber-reinforced rubber compounds. / Features high durability and smooth running.

Base fabric : Made of flexible carcass, it functions to absorb shock and prevent rubber cracks.

## Raw Edge Belt List for Automotive

| TYPE | CROSS SECTION | LENGTH STANDARD | SIZE RANGE(INCH) | MIN. Q'TY(PCS) |
|---|---|---|---|---|
| COGGED CLASSICAL | 9.5X | EOC | 460~3030mm | 85 |
| | 12.5X | EOC | 530~3030mm | 70 |
| | 13X | IC | 530~3030mm | 70 |
| | 15X | IC | 580~3030mm | 60 |
| | 17X | IC | 580~3030mm | 50 |
| | 20X | IC | 580~3030mm | 40 |
| | 22X | IC | 1020~3030mm | 40 |
| | 25X | IC | 1020~3030 mm | 35 |
| COGGED CLASSICAL | MX / ZX | IC | 18~200 | 85 |
| | AX | RMA IC | 21~200 | 70 |
| | BX | RMA IC | 23~200 | 50 |
| | CX | RMA IC | 40~200 | 40 |
| COGGED SAE | 10A | EOC | 18~120 | 85 |
| | 11A | EOC | 18~120 | 80 |
| | 13A | EOC | 21~120 | 70 |
| | 15A | EOC | 21~120 | 50 |
| | 17A | EOC | 23~120 | 50 |
| | 20A | EOC | 40~120 | 40 |
| | 22A | EOC | 40~120 | 40 |
| COGGED MBL / BANDO | 1(M) / 2(B) | EOC | 18~120 | 85 |
| | 6(M) / 3(B) | P.L | 21~120 | 70 |
| | 8(M) / 5(B) | P.L | 23~120 | 50 |
| | 9(M) / 7(B) | P.L | 40~120 | 40 |
| COGGED CLASSICAL (AUTOMOTIVE) | AVX-10X | EOC | 18~120 | 85 |
| | AVX-11X | EOC | 18~120 | 80 |
| | AVX-12X | EOC | 18~120 | 75 |
| | AVX-13X | EOC | 21~120 | 70 |
| | AVX-17X | EOC | 23~120 | 50 |




# V-RIBBED BELT

High flexibility due to unique belt cross-section allows long service life and compact drives. DRB V-Ribbed Belt are suited for high speed drives and high power transmission drives. V-Ribbed Belt is so-called "Poly V-Belt".

## Features

- Designed for excellent flexibility, meets the requirements of small pulley diameters and reverse bending.
- High power transmission efficiency
- Reduced noise
- Smooth running.

## Construction & Materials



- Top fabric : Features flexibility and resistance to heat, oil and abrasion.
- Tension member : Made of highly strong cords with low stretchability, gives high flexibility and length stability.
- Compression rubber : Made of fiber-reinforced rubber compounds. / Features high durability and smooth running.
- Base fabric : Made of flexible carcass, it functions to absorb shock and prevent rubber cracks.

## V-Ribbed Belt List for Automotive

| TYPE | CROSS SECTION | CROSS SECTION | CROSS SECTION |
|---|---|---|---|
| V-RIBBED PK TYPE | 3PK | 20 ~ 120 (510 ~ 3030mm) | 85 |
| | 4PK | | 60 |
| | 5PK | | 50 |
| | 6PK | | 40 |
| | 7PK | | 35 |
| | 8PK | | 30 |
| | 9PK | | 28 |
| | 10PK | | 25 |
| | 11PK | | 20 |
| | 12PK | | 20 |





# TIMING BELT

Timing belts have mainly been used for automotive overhead camshaft(OHC) drives and guarantee variable speed change and high temperature drive conditions. These belts drive offer many advantages over conventional chain and gear drives. Timing belt is so-called "Synchronous belt".

## Features

- Highly flexible and thus suitable for conditions requiring high flexibility and a small pulley diameter.
- Assures uniform performance over the entire belt length for the entire belt life.
- Resistant to heat, oil and abrasion.

## Construction & Materials



Tensile member : Fiberglass cords with high tensile strength, excellent flexibility and which eliminate belt stretching.

Rubber teeth : Excellent heat and oil resistance, adhesion both on tensile member and tooth fabric.

Nylon fabric : Excellent wear-resistant, low friction coefficient facing gives long service life.

## Timing Belt List for Automotive

| TYPE | TYPE | TYPE | TYPE | TYPE | TYPE | TYPE | TYPE |
|---|---|---|---|---|---|---|---|
| Pitch | P=9.525mm | P=8mm | P=9.525mm | P=8mm | P=9.525mm | P=9.525mm | P=8mm |
| NO | Size | Size | Size | Size | Size | Size | Size |
| 1 | 97R | 103Y | 59RU | 65YU | 88ZA | 55ZBS | 65S8M |
| 2 | 104R | 106Y | 70RU | 99YU | 91ZA | 83ZBS | 105S8M |
| 3 | 111R | 111Y | 91RU | 100YU | 111ZA | 92ZBS | 110S8M |
| 4 | 114R | 123Y | 92RU | 101YU | 115ZA | 163ZBS | 137S8M |
| 5 | 125R | 144Y | 93RU | 107YU | 120ZA | | 138S8M |
| 6 | 129R | | 95RU | 145YU | 121ZA | | 146S8M |
| 7 | | | 97RU | 153YU | 124ZA | | 148S8M |
| 8 | | | 101RU | 154YU | | | 150S8M |
| 9 | | | 104RU | 166YU | | | 162S8M |
| 10 | | | 105RU | 168YU | | | 169S8M |
| 11 | | | 108RU | 173YU | | | 173S8M |
| 12 | | | 111RU | 202YU | | | 175S8M |
| 13 | | | 113RU | 207YU | | | |
| 14 | | | 122RU | 211YU | | | |
| 15 | | | 123RU | 219YU | | | |
| 16 | | | 124RU | 226YU | | | |
| 17 | | | 127RU | 251YU | | | |
| 18 | | | 134RU | 259YU | | | |
| 19 | | | 149RU | | | | |
| 20 | | | 151RU | | | | |
| 21 | | | 152RU | | | | |
| 22 | | | 153RU | | | | |
| 23 | | | 154RU | | | | |
| 24 | | | 163RU | | | | |
| 25 | | | 176RU | | | | |

## VEHICLE INDEX


DAIHATSU ..... 08
HONDA ..... 10
ISUZU ..... 17
MAZDA ..... 18
MITSUBISHI ..... 26
NISSAN ..... 34
SUBARU ..... 49
SUZUKI ..... 51
TOYOTA ..... 54


## ABBREVIATION

| | |
|---|---|
| ALT | Alternator |
| FAN | Fan |
| PS | Power Steering |
| PS+AC | Power Steering + Air Conditioner |
| WP | Water Pump |
| ATM | Automatic Transmission |
| MTM | Manual Transmission |
| DSL | Diesel Car |
| SC | Super Charger |
| TB | Turbo |



# DAIHATSU



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| APPLAUSE | A101S, A111S(ATM) | 1600 | HD | 89~95 | FAN | 4PK790 | 90048-31012/3 |
| | | | | | AC | 5PK810 | 88458-87101 |
| | A101S, A111S(MTM) | 1600 | HD | 89~95 | FAN | 4PK775 | 90048-31003/4 |
| | | | | | AC | 5PK810 | 88458-87101 |
| ATRAI | S120V, S130V | 660 | EFZs | 95~99 | FAN | 4PK715 | 90048-32020 |
| | | | | | FAN | 4PK705 | 90048-32021 |
| | S200C, P, V | 660 | EFSE | 98~ | FAN | 4PK765 | 90048-31024 |
| | | | | | PS | 3PK675 | 44318-97502 |
| | | | EFVE | 98~ | FAN | 4PK705 | 90048-31021 |
| | | | | | PS | 3PK780 | 44318-97501 |
| | | | | | AC | 4PK760 | 99364-20751 |
| CHARADE | G100S(SOHC) | 1000 | CB | 90~93 | PS | 3PK765 | 44318-87703 |
| | | | | | AC | 5PK905 | 88458-87702 |
| | | | | | PS+AC | 5PK905 | 88458-87702 |
| | G100S(DOHC) | 1000 | CB | 87~92 | PS | 3PK765 | 44318-87703 |
| | | | | | AC | 5PK810 | 88458-87701 |
| | G101S(ATM) | 1000 | CL (DSL) | 87~93 | AC | 5PK810 | 88458-87701 |
| | G101S(MTM) | 1000 | CL (DSL) | 87~93 | AC | 5PK810 | 88458-87701 |
| | G101S(ATM) | 1000 | CL (DSL) | 87~92 | PS | 3PK765 | 44318-87703 |
| | | | | | PS+AC | 5PK905 | 88458-87702 |
| | G101S(MTM) | 1000 | CL (DSL) | 87~92 | PS | 3PK765 | 44318-87703 |
| | | | | | PS+AC | 5PK905 | 88458-87702 |
| | G101(ATM) | 1000 | CL (DSL) | 87~93 | PS | 3PK765 | 44318-87703 |
| | | | | | PS+AC | 5PK905 | 88458-87702 |
| | G101(MTM) | 1000 | CL (DSL) | 87~ | PS | 3PK765 | 44318-87703 |
| | | | | | PS+AC | 5PK905 | 88458-87702 |
| | G102S, G112S | 1300 | HCF | 89~93 | FAN | 4PK775 | 90048-31003/4 |
| | | | | | PS | 3PK560 | 44318-87704 |
| | | | | | AC | 4PK825 | 88458-87703 |
| | G200S | 1300 | HCE | 93~00 | FAN | 3PK540 | 44318-87707 |
| | G203S(ATM) | 1500 | HEEG | 93~00 | FAN | 3PK540 | 44318-87707 |
| | G213S | 1500 | HEEG | 93~00 | FAN | 3PK540 | 44318-87707 |
| | G201S | 1600 | HDEG | 93~98 | FAN | 4PK790 | 90048-31018 |
| | | | | | PS | 3PK540 | 44318-87706-000 |
| | | | | | AC | 4PK820 | 88458-87710-980 |
| | | | | 93~ | AC | 4PK870 | 88458-87706 |
| DELTA | SR40N, SR50N | 2000 | 3S-FE | 96~01 | FAN | 5PK995 | 90916-02355/6 |
| | | | | | PS | 4PK960 | 99364-30960 |
| | | | | | AC | 5PK1100 | 99365-31100 |
| | CR41J, CR51J(DSL) | 2000 | 2C | 96~98 | PS | 3PK810 | 99363-30810 |
| DELTA WIDE | KB27V | 1500 | 5KJ | 85~88 | FAN | 5PK820 | 99365-50820 |
| | YB20G | 1800 | 2Y | 82~85 | FAN | 5PK820 | 99365-50820 |
| | | | 2YU | 88~92 | FAN+AC | 5PK820 | 99365-50820 |
| | YB25G | 1800 | 2YU | 88~96 | FAN | 5PK820 | 99365-50820 |
| | CB26V(DSL) | 1800 | 1C | 85~88 | PS | 3PK805 | 90916-02122 |
| | YB25V | 1800 | 1C | 88~96 | FAN | 5PK820 | 99365-50820 |
| | | 1800 | 2YJ | 88~96 | FAN | 5PK820 | 99365-50820 |
| | CB21G(DSL) | 2000 | 2C/2CT | 84~93 | FAN | 5PK920 | 99365-00920 |
| | | | | | PS | 3PK805 | 90916-02122 |
| | | | | | AC | 3PK805 | 90916-02122 |
| | CB27V(DSL) | 2000 | 2C | 84~96 | PS | 3PK805 | 90916-02122 |
| | YB21G | 2000 | 3Y-EU | 83~96 | FAN+AC | 5PK820 | 99365-80820 |
| DELTA WIDE VAN · WAGON | YB25V(VAN) | 1800 | 2Y-J | 88~96 | FAN+AC | 5PK820 | 99365-70820 |
| | CB27V(VAN) | 2000 | 2C(DSL) | 88~96 | AC | 3PK795 | 90916-02363 |
| | CB21G(WGN) | 2000 | 2C-T(DSL) | 83~93 | AC | 3PK795 | 90916-02363 |
| | YB21G(WGN) | 2000 | 3Y-EU | 83~96 | FAN+AC | 5PK820 | 99365-70820 |
| HIJET | S100C, V, W | 660 | EFGS/EFZS | 95~99 | FAN | 4PK715 | 90048-31020 |
| | S110P, V, W | 660 | EFGS/EFZS | 95~99 | FAN | 4PK705 | 90048-31021 (EFI) |
| | S200C, P, V | 660 | EFSE | 98~ | FAN | 4PK765 | 90048-31024 |
| | | | | | PS | 3PK675 | 44318-97502 |
| | | | EFVE | 98~ | FAN | 4PK705 | 90048-31021 |
| | | | | | PS | 3PK780 | 44318-97501 |
| | | | | | AC | 4PK760 | 99364-20751 |
| MAX | L950S | 660 | | 01~04 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK525 | 44318-97204 |
| MIDGET II | K100C, P | 660 | EFSE | 99~01 | FAN+AC | 4PK765 | 90048-31024 |

# DAIHATSU

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| MIRA | L500S | 660 | FEEL/EFJL/EFKL | 94~95 | PS | 3PK730 | 44318-87201 |
| | L502S | 660 | JBEL | 94~98 | FAN | 4PK680 | 99364-20681 |
| | L510V | 660 | EFCL | 94~98 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK730 | 44318-87201 |
| | L512S | 660 | JBJL | 94~98 | FAN | 4PK680 | 99364-20681 |
| | L700S, V | 660 | EFVE | 99~ | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK525 | 44318-97204 |
| | | | EFSE | 99~ | FAN | 4PK765 | 90048-31024 |
| | | | | | PS | 3PK575 | 44318-97203 |
| MOVE | L600S, L610S | 660 | EFGL/EFRL/EFZL | 95~98 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK730 | 44318-87201 |
| | L602S | 660 | JBJL | 95~98 | FAN | 4PK680 | 99364-20681 |
| | | | | | PS | 3PK730 | 44318-87201 |
| | L900S, L910S | 660 | EFVE/EFDET | 98~02 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK525 | 44318-97204 |
| | | | EFSE | 98~00 | FAN | 4PK765 | 90048-31024 |
| | | | | | PS | 3PK575 | 44318-97203 |
| | L902S | 660 | JBDET | 98~ | FAN | 4PK685 | 90048-31027 |
| | LA-L152S | 660 | JBDET | 02~04 | AC | 3PK795 | 90048-31043 |
| | | | | | AC | 3PK760 | 90048-31044 |
| NAKED | L750S | 660 | EFDEF | 99~03 | FAN | 4PK715 | 99048-31020 |
| | | | | | FAN | 4PK685 | 90048-31027 |
| | | | | | FAN+AC | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK525 | 44318-97204 |
| OPTI | L300S, L310S | 660 | EFZL | 95~98 | FAN | 4PK715 | 90048-31020 |
| | L800S, L810S | 660 | EFSE | 98~ | FAN | 4PK765 | 90048-31024 |
| | | | | | PS | 3PK575 | 44318-97203 |
| | | | EFVE | 98~ | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK525 | 44318-97204 |
| | L802S | 660 | JB-DET | 98~ | FAN | 4PK685 | 90048-31027 |
| PYZER | G303G(2WD) | 1500 | HEEG | 96~02 | FAN | 4PK790 | 90048-31018 |
| | | | | | PS | 3PK540 | 44318-87706 |
| | | | | | AC | 4PK780 | 90048-31017 |
| | G313G(4WD) | 1500 | HEEG | 96~02 | FAN | 4PK790 | 90048-31018 |
| | | | | | PS | 3PK540 | 44318-87706 |
| | | | | | AC | 4PK810 | 88458-87711 |
| | G301G, G311G | 1600 | HDEP | 97~02 | FAN | 4PK790 | 90048-31013/8 |
| | | | | | PS | 3PK540 | 44318-87706/7 |
| | | | | | AC | 4PK810 | 88458-87711(ATM) |
| | | | | | AC | 4PK780 | 90048-31017/9(MTM) |
| ROCKY | F300S | 1600 | HDE | 90~97 | PS | 5PK975 | 90048-31005 |
| | | | | | AC | 5PK1240 | 90048-31006 |
| | F3 | 3000 | HDE | 90~97 | FAN | 4PK780 | 90048-31010/5/7/9 |
| | | | | | PS | 5PK975 | 90048-31005 |
| | | | | | AC | 5PK1240 | 90048-31006/14 |
| STORIA | M100S, M110S | 1000 | EJDE | 98~04 | FAN | 4PK715 | 90048-31020 |
| TERIOS | J100G | 1300 | CX | 97~00 | FAN | 4PK780 | 90048-31017 |
| | | | | | AC | 4PK1440 | 88458-87401 |
| | | | HCEJ | 97~00 | FAN | 4PK780 | 90048-31017 |
| | | | | | FAN | 4PK1440 | 88458-87401 |
| | J102G | 1300 | K3-VE/VTE | 00~ | PS | 3PK640 | 44318-87403 |
| TERIOS KID | J111G | 660 | EFDE | 98~06 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK600 | 44318-87402 |
| | | | EFDET | 98~02 | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK600 | 44318-87402 |
| | J131G | 660 | EFDET | 00.04- | FAN | 4PK715 | 90048-31020 |
| | | | | | PS | 3PK600 | 44318-87402 |
| YRV | M200G | 1000 | EJVE | 00~02 | FAN | 4PK715 | 90048-31020 |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |
| | | | | | | | |

# HONDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ACCORD | CA1 | 1800 | A18A | 85~89 | FAN | 5PK930 | 31110-PH2-J01/2 |
| | | | | | AC | 4PK910 | 38920-PK3-003/4 |
| | CA2 | 1800 | B18A | 87~89 | FAN | 3PK805 | 31110-PH3-J01/2 |
| | | | | | AC | 4PK910 | 38920-PK3-003/4 |
| | CB1 | 1800 | F18A | 89~91 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J02 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CB2 | 1800 | F18A | 89~91 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CD3 | 1800 | F18B | 93~97 | FAN+AC | 6PK1115 | 38920-P0A-003/4 |
| | | | | | PS | 4PK1060 | 56992-P0A-003/4 |
| | CA3 | 2000 | B20A | 87~89 | FAN | 3PK805 | 31110-PH3-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | CA5 | 2000 | A20A | 87~89 | FAN | 5PK930 | 31110-PH2-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | CA6 | 2000 | A20A3 | 88~90 | FAN | 5PK930 | 31110-PH2-J01/2 |
| | | | | | AC | 4PK900 | 38920-PH4-A52 |
| | CB3 | 2000 | F20A | 89~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CB4 | 2000 | F20A | 89~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CB5 | 2000 | G20A | 89~93 | FAN | 4PK835 | 31110-PV0-003/4 |
| | | | | | PS | 4PK735 | 56992-PV0-003/4 |
| | | | | | AC | 4PK920 | 38920-PV0-003/4 |
| | CB6 | 2000 | F20A | 90~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CD4 | 2000 | F20B | 93~97 | FAN+AC | 6PK1115 | 38920-P0A-003/4 |
| | | | | | PS | 4PK1060 | 56992-P0A-003/4 |
| | CB7, CB9 | 2200 | F22A | 91~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CD5, DC7, CE1 | 2200 | F22B | 93~97 | FAN+AC | 6PK1115 | 38920-P0A-003/4 |
| | | | | | PS | 4PK1060 | 56992-P0A-003/4 |
| | CD6, D8 | 2200 | H22A | 93~97 | FAN+AC | 6PK1045 | 38920-P0F-003/4 |
| | | | | | PS | 4PK1055 | 56992-P0F-003/4 |
| | DX | 2400 | | 05~ | FAN+AC | 7PK7180 | 38920-RAA-A01/2 |
| | | | | | PS+WP | | WITH FAN |
| | EX | 2400 | | 05~ | FAN+AC | 7PK7180 | 38920-RAA-A01/2 |
| | | | | | PS+WP | | WITH FAN |
| | LX | 2400 | | 05~ | FAN+AC | 7PK7180 | 38920-RAA-A01/2 |
| | | | | | PS+WP | | WITH FAN |
| | HYBRID | 3000 | | 05~ | FAN+AC | 7PK7180 | 38920-RCJ-A02 |
| | | | | | PS+WP | | WITH FAN |
| ACCORD WAGON | CF6, CF7 | 2300 | F23A | 97~02 | FAN+AC | 6PK1080 | 38920-PCA-003/4 |
| | CH9 | 2300 | H23A | 98~02 | FAN+AC | 6PK1045 | 38920-P13-J01 |
| ACTY | HH3, HH4 | 660 | E07A | 90~99 | AC | 3PK710 | 38920-PZ3-003/4 |
| | HH5, 6(HORIZONTAL ENGINE) | 660 | E07A | 99~ | FAN+AC | 3PK670 | 31110-PFB-003 |
| | HH5, 6(VERTICAL ENGINE) | 660 | E07A | 99~04 | FAN | 3PK670 | 31110-PFB-003 |
| | | | | | AC | 3PK695 | 38920-PTF-003 |
| | HA6, HA7 | 660 | E07Z | 99~ | FAN+AC | 3PK670 | 31110-PFB-003 |
| | | | | | AC | | WITH FAN |
| ASCOT | CB1, BC2 | 1800 | F18A | 89~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J02 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CB3, BC4 | 2000 | F20A | 89~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | | | | | AC | 5PK1105 | 38920-PT0-003/4 |
| | CE4 | 2000 | G20A | 93~97 | FAN | 5PK820 | 31110-PV3-004/J01 |

# HONDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ASCOT | CE4 | 2000 | G20A | 93~97 | PS | 4PK700 | 56992-PV3-004/J01 |
| | | | | | AC | 5PK920 | 38920-PV3-A02/J01 |
| ASCOT INNOVA | CB3, CB4 | 2000 | F20A | 92~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | FAN+AC | 5PK1105 | 38920-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | CB3, CB4(4WS) | 2000 | F20A | 92~93 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | FAN+AC | 5PK1105 | 38920-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| | CC4 | 2200 | H23A | 92~95 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | FAN+AC | 5PK1105 | 38920-PT0-003/4 |
| | | | | | PS | 4PK1070 | 56992-PT0-J01/2 |
| | CC5 | 2200 | H23A | 92~95 | FAN | 5PK955 | 31110-PT0-003/4 |
| | | | | | FAN+AC | 5PK1105 | 38920-PT0-003/4 |
| | | | | | PS | 4PK1050 | 56992-PT0-003/4 |
| AVANCIER | TA1, TA2 | 2300 | F23A | 99~03 | FAN+AC | 6PK1105 | 38920-PAA-A01 |
| | | | | | PS | 4PK1060 | 56992-PAA-A01 |
| | | | | | PS | 4PK1060 | 56992-P0A-J01 |
| | TA3, TA4 | 3000 | J30A | 99~03 | FAN+AC | 6PK1175 | 38920-P8C-A02/3 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01 |
| BALLADE · CR-X | EF6 | 1500 | D15B | 87~91 | FAN | 3PK760 | 31110-PM3-003/4/5 |
| | | | | | AC | 4PK870 | 38920-PM3-003 |
| | EG1 | 1500 | D15B | 92~96 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK850 | 38920-P04-003/4 |
| | EG2(ATM) | 1600 | B16A | 92~96 | FAN | 4PK770 | 31110-P30-901/2 |
| | | | | | PS | 4PK870 | 56992-P30-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| | EG2(MTM) | 1600 | B16A | 92~96 | FAN | 4PK775 | 31110-P30-003/4 |
| | | | | | PS | 4PK870 | 56992-P30-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| | EF7 | 1600 | ZC | 87~92 | FAN | 3PK760 | 31110-PM3-003/014 |
| | | | | | AC | 4PK870 | 38920-PM3-003/014 |
| | EF8 | 1600 | B16A | 89~92 | FAN | 4PK770 | 31110-PR3-003-4 |
| | | | | | AC | 4PK845 | 38920-PW0-G01/2 |
| | EJ4 | 1600 | D16A | 95~99 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-004 |
| BEAT | PP1 | 660 | E07A | 91~96 | FAN | 3PK635 | 31110-P36-003 |
| CAPA | GA4, GA6 | 1500 | D15B | 98~02 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 3PK890 | 56992-PEJ-004 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | | | | | AC | 4PK820 | 31110-P3F-003 |
| CITY | FA | 1200 | ER | 85~94 | FAN | 3PK950 | 31110-PC0-003/4 |
| | GA2 | 1200 | D13C | 88~94 | FAN | 3PK715 | 31110-PJ7-013/014 |
| | GA1-110 | 1200 | D12A | 88~ | FAN | 3PK715 | 31110-PJ7-013/014 |
| CIVIC | EG3, EG7 | 1300 | D13B | 91~95 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | EK2 | 1300 | D13B | 95~00 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | | | | | AC | 4PK820 | 31110-P3F-003 |
| | EF2, EF4 | 1500 | D15B | 87~91 | FAN | 3PK760 | 31110-PM3-003/4/5 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | | | | | FAN | 3PK760 | 31110-PM3-014 |
| | EG4, EG8 | 1500 | D15B | 91~95 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | EK3 | 1500 | D15B | 95~00 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | | | | | AC | 4PK820 | 31110-P3F-003 |
| | EU1, EU2 ES1, ES2 | 1500 | D15B | 00~ | PS | 4PK1000 | 56992-PLC-004 |
| | EF3, EF5(SOHC) | 1600 | ZC | 87~91 | FAN | 3PK760 | 31110-PM3-003/4/5 |

# HONDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CIVIC | EF3, EF5(SOHC) | 1600 | ZC | 87~91 | AC | 4PK870 | 38920-P08-003/4 |
| | | | | | FAN | 3PK760 | 31110-PM3-014 |
| | EF3, EF5(DOHC) | 1600 | ZC | 89~91 | FAN | 3PK760 | 31110-PM3-003/4/5 |
| | | | | | FAN | 3PK760 | 31110-PM3-014 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | EF9 | 1600 | B16A | 89~91 | FAN | 4PK770 | 31110-PR3-003/4 |
| | | | | | AC | 4PK845 | 38920-PW0-G01/2 |
| | EG6, EG9(ATM) | 1600 | B16A | 91~95 | FAN | 4PK770 | 31110-P30-901/2 |
| | | | | | PS | 4PK870 | 56992-P30-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| | EG6, EG9(MTM) | 1600 | B16A | 91~95 | FAN | 4PK775 | 31110-P30-003/4 |
| | | | | | PS | 4PK870 | 56992-P30-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| | EH1, EJ3(SOHC) | 1600 | ZC | 91~95 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | EH1, EG5(DOHC) | 1600 | ZC | 91~95 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK775 | 56992-P29-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | EJ1 | 1600 | D16A | 94~96 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | EK4 | 1600 | B16A | 95~00 | FAN | 4PK775 | 31110-P2T-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK845 | 38920-P2T-003 |
| | EK5 | 1600 | D16A | 95~00 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | | | | | AC | 4PK820 | 31110-P3F-003 |
| | EK8 | 1600 | D16A | 97~98 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4KP845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | | | | | AC | 4PK820 | 31110-P3F-003 |
| | EK9 | 1600 | B16B | 97~00 | FAN | 4PK745 | 31110-PCT-004 |
| | | | | | PS | 4PK880 | 56992-P2T-004 |
| | | | | | AC | 4PK845 | 38920-P2T-003 |
| | EU3, EU4, ES3 | 1700 | D17A | 00~04 | PS | 4PK1010 | 56992-PLM-003/4 |
| | | | | | AC | 6PK985 | 38920-PLR-003 |
| | | | | | AC | 7PK985 | 38920-PSA-003 |
| | | | | | PS | 4PK1025 | 56992-PSA-003 |
| | TYPE-R | 2000 | | | AC | 7PK1730 | 38920-PND-003 |
| | | | | | AC | 7PK1640 | 38920-PRA-003/013 |
| CIVIC COUPE | EJ7 | 1600 | D16A | 96~00 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| CONCERTO | MA1 | 1500 | D15B | 88~92 | FAN | 3PK760 | 31110-PM3-003/014 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | MA2, MA3 | 1600 | ZC | 88~92 | FAN | 3PK760 | 31110-PM3-003/014 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | MA2, MA3 | 1600 | ZC | 91~92 | FAN | 3PK760 | 31110-PM3-003/014 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| CR-V | RD1 | 2000 | B20B | 95~01 | FAN | 4PK820 | 38920-P2A-003 |
| | | | | | PS | 4PK895 | 56992-P3F-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| | RD2 | 2000 | B20B | 98~01 | FAN | 4PK820 | 31110-P3F-004 |
| | | | | | PS | 4PK895 | 56992-P3F-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| DEL SOL | EG2 | 1600 | B16A | 92~95 | PS | 4PK870 | 56992-P30-003 |
| | | | | | AC | 4PK790 | 38920-P30-M01 |
| | EJ4(MTM) | 1600 | D16A | 92~95 | AC | 4PK820 | 38920-P2A-003 |
| DOMANI | MA7 | 1500 | D15B | 92~96 | FAN | 4PK780 | 31110-P01-003/4 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | MB3 | 1500 | D15B | 97~00 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | MB4 | 1600 | D16A | 97~00 | FAN | 4PK800 | 31110-P2A-003/4 |

# HONDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| DOMANI | MB4 | 1600 | D16A | 97~00 | PS | 4PK815 | 56992-P76-003 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | MB4, MB6 | 1600 | ZC | 92~96 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | MB5 | 1600 | D16A | 97~ | FAN | P4K800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | MA5 | 1800 | B18B | 92~96 | FAN | 4PK790 | 31110-PR4-003/4 |
| | | | | | PS | 4PK870 | 56992-P30-003/4 |
| | | | | | AC | 4PK815 | 38920-P54-003/4 |
| FIT | GD1, GD2 | 1300 | L13A | 01~04 | FAN+AC | 5PK1140 | 38920-PWA-004 |
| HORIZON | UBS25 | 3200 | 6VD1 | 94~98 | FAN | 4PK965 | 8-94382-106-0 |
| | | | | | AC | 4PK805 | 8-94382-107-1 |
| HR-V | GH1, GH2 | 1600 | D16A | 98~03 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| | GH3, GH4 | 1600 | D16A | 99~ | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| INSPIRE · VIGOR | CC3 | 2000 | G20A | 92~92 | FAN | 4PK830 | 31110-PV1-003 |
| | | | | | PS | 4PK735 | 56992-PV0-003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003/4 |
| | CC2 | 2500 | G25A | 92~95 | FAN | 4PK830 | 31110-PV1-003 |
| | | | | | PS | 4PK735 | 56992-PV0-003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003/4 |
| INSPIRE · SABER | UA1 | 2000 | G20A | 95~98 | FAN | 5PK835 | 31110-P1R-003/4 |
| | | | | | PS | 4PK700 | 56992-P1R-003/4 |
| | | | | | AC | 5PK930 | 38920-P1R-003/4 |
| | CB5 | 2000 | G20A | 89~95 | FAN | 4PK835 | 31110-PV0-003/4 |
| | | | | | PS | 4PK735 | 56992-PV0-003/4 |
| | | | | | AC | 4PK920 | 38920-PV0-003/4 |
| | UA2 | 2500 | G25A | 95~98 | FAN | 5PK835 | 31110-P1R-003/4 |
| | | | | | PS | 4PK700 | 56992-P1R-003/4 |
| | | | | | AC | 5PK930 | 38920-P1R-003/4 |
| | UA4 | 2500 | J25A | 99~03 | FAN+AC | 6PK1190 | 38920-P8F-A02 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01 |
| | UA3 | 3200 | G32A | 95~98 | FAN | 5PK935 | 31110-P5G-003 |
| | | | | | PS | 4KP950 | 56992-P5G-003 |
| | | | | | AC | 5PK960 | 38920-PY3-003 |
| | | | | | AC | 5PK960 | 38920-P5G-004 |
| | UA5 | 3200 | J32A | 98~03 | FAN+AC | 6PK1190 | 38920-P8F-A02 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01 |
| INTEGRA | EK3 | 1500 | D15B | 96~01 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | DB6, DB9, DC1 | 1600 | ZC | 93~96 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | PS | 4PK815 | 56992-P76-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | DB7 | 1800 | B18B | 93~95 | FAN | 4PK790 | 31110-P75-004 |
| | | | | | PS | 4PK920 | 56992-P72-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003 |
| | DB8, DC2(ATM) | 1800 | B18C | 93~01 | FAN | 4PK780 | 31110-P72-902 |
| | | | | | PS | 4PK920 | 56992-P72-003/4 |
| | | | | | AC | 4PK835 | 31110-PV0-004 |
| | DB8, DC2(MTM) | 1800 | B18C | 93~01 | FAN | 4PK780 | 31110-P72-902 |
| | | | | | PS | 4PK920 | 56992-P72-003/4 |
| | | | | | AC | 4PK835 | 31110-PV0-004 |
| | DC2-100, 110, 120, 130 | 1800 | B18C | 93~01 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK920 | 56992-P72-003/4 |
| | | | | | AC | 4PK835 | 31110-PV0-004 |
| | DC2-100, 110, 120, 130(TYPER) | 1800 | B18C | 95~01 | FAN | 4PK760 | 31110-P73-004 |
| | | | | | PS | 4PK920 | 56992-P72-003/4 |

# HONDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| INTEGRA | DC2-100, 110, 120, 130(TYPE R) | 1800 | B18C | 95~01 | AC | 4PK810 | 38920-P73-003 |
| | DC5 | 2000 | K20A | 01~ | FAN | 7PK1340 | 31110-PRC-003/4 |
| QUINT INTEGRA | EK3 | 1500 | D15B | 96~00 | FAN | 4PK780 | 31110-P2J-003/004 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003/4 |
| | DA2 | 1500 | EW | 87~89 | FAN | 3PK735 | 31110-PE0-003/4 |
| | AV | 1600 | ZC | 85~89 | FAN | 3PK715 | 31110-PG6-003 |
| | | | | | FAN | 3PK715 | 31110-PJ7-014 |
| | DA1 | 1600 | ZC | 85~93 | FAN | 3PK715 | 31110-PG6-003/4 |
| | | | | | FAN | 3PK715 | 31110-PJ7-014 |
| | DA5 | 1600 | ZC | 89~93 | FAN | 4PK765 | 31110-PR5-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | | | | | AC | 4PK870 | 38920-PM3-003/014 |
| | DA6 | 1600 | B16A | 89~93 | FAN | 4PK770 | 31110-PR3-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| | DA7 | 1600 | ZC | 89~93 | FAN | 4PK765 | 31110-PR5-003/4 |
| | | | | | AC | 4PK870 | 38920-P08-003/4 |
| | DA8 | 1600 | B16A | 89~93 | FAN | 4PK770 | 31110-PR3-003/4 |
| | | | | | AC | 4PK830 | 38920-PR3-003/4 |
| LAGREAT | RL1 | 3500 | J35A | 98~04 | FAN+AC | 6PK1190 | 38920-P8F-A02/3/4 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01/2 |
| LEGEND | KA6 | 2700 | C27A | 88~90 | FAN | 3PK1075 | 31110-PH7-013 |
| | | | | | FAN | 3PK1075 | 31110-PL2-A11 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | KA7, KA8 | 3200 | C32A | 90~96 | FAN | 5PK935 | 31110-PY3-003/4 |
| | | | | | FAN | 6PK945 | 31110-PY3-J01 |
| | | | | | PS | 4PK950 | 56992-PY3-003/4 |
| | | | | | AC | 5PK960 | 38920-PY3-003/4 |
| | KA9 | 3500 | C35A | 96~99 | FAN | 6PK935 | 31110-P5A-J01 |
| | | | | | PS | 4PK950 | 56992-P5G-003 |
| | | | | | AC | 5PK955 | 38920-P5A-004 |
| LIFE | JA4 | 660 | E07A | 97~98 | FAN+AC | 4PK1105 | 38920-P64-003 |
| | | | | | PS | 3PK690 | 56992-P64-003/4 |
| | JB1, JB2 | 660 | E07Z | 98~03 | FAN+AC | 3PK670 | 31110-PFB-003 |
| | JB3, JB4 | 660 | E07Z | 00~ | FAN+AC | 3PK670 | 31110-PFB-003 |
| | PA1 | 660 | E07Z | 98~02 | FAN | 3PK670 | 31110-PFB-003 |
| | | | | | AC | 3PK670 | 31110-PFB-003 |
| LOGO | GA3 | 1300 | D13B | 96~02 | FAN | 3PK805 | 31110-P7A-003 |
| | | | | | PS | 3PK1050 | 56692-P7A-004 |
| | | | | | AC | 4PK855 | 38920-P7A-004 |
| MOBILIO | LA-GB1 | 1500 | L15A | 02~04 | PS | 5PK1130 | 38920-PYD-003 |
| NSX | NA1(ATM) | 3000 | C30A | 90~93 | FAN | 5PK1110 | 31110-PR7-A12 |
| | | | | | AC | 4PK975 | 38920-PR7-A01/2 |
| | NA1(MTM) | 3000 | C30A | 90~93 | FAN | 5PK1095 | 31110-PR7-A01 |
| | | | | | AC | 4PK975 | 38920-PR7-A01/2 |
| | NA2(ATM) | 3200 | C32B | 97~04 | FAN | 5PK1110 | 31110-PR7-A12 |
| | | | | | AC | 4PK975 | 38920-PR7-A01/2 |
| | NA2(MTM) | 3200 | C32B | 97~04 | FAN | 5PK1095 | 31110-PR7-A01 |
| | | | | | AC | 4PK975 | 38920-PR7-A01/2 |
| ODYSSEY | RA1, RA2 | 2200 | F22B | 94~97 | FAN | 6PK940 | 31110-P08-A01/2 |
| | | | | | FAN+AC | 6PK1085 | 38920-P1E-003/4 |
| | | | | | FAN+AC | 6PK1085 | 38920-P1E-J02 |
| | | | | | PS | 4PK1060 | 56992-PAA-A01 |
| | | | | | PS | 4PK1060 | 56992-P0A-J02/3/4 |
| | RA3, RA4 | 2300 | F23A | 98~99 | FAN | 6PK940 | 31110-P08-A01/2 |
| | | | | | FAN+AC | 6PK1085 | 38920-P1E-003/4 |
| | | | | | FAN+AC | 6PK1085 | 38920-P1E-J02 |
| | | | | | PS | 4PK1060 | 56992-P0A-003/4 |
| | | | | | PS | 4PK1060 | 56992-PAA-A01 |
| | RA6, RA7 | 2300 | F23A | 99~03 | FAN+AC | 6PK1105 | 38920-PAA-A01/2 |
| | | | | | PS | 4PK1085 | 56992-PGM-003/4 |
| | RA5 | 3000 | J30A | 97~99 | FAN+AC | 6PK1175 | 38920-P8A-A02 |
| | | | | | FAN+AC | 6PK1175 | 38920-P8C-A02 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01 |
| | RA8, RA9 | 3000 | J30A | 00~ | FAN+AC | 6PK1190 | 38920-P8F-A02/3 |
| | | | | | PS | 4PK1115 | 56992-P8A-A01 |

# HONDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ORTHIA | EL1 | 1800 | B18B | 96~02 | FAN | 4PK820 | 31110-P3F-004 |
| | | | | | PS | 4PK895 | 56992-P3F-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| | EL2, EL3 | 2000 | B20B | 96~02 | FAN | 4PK820 | 31110-P3F-004 |
| | | | | | PS | 4PK895 | 56992-P3F-003/4 |
| | | | | | AC | 4PK845 | 38920-P3F-003/4 |
| PARTNER | EY6 | 1300 | D13B | 96~04 | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | EY7 | 1500 | D15B | 96~ | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| | EY8, EY9 | 1600 | D16A | 96~ | FAN | 4PK800 | 31110-P2A-003/4 |
| | | | | | PS | 4PK845 | 56992-P2A-003/4 |
| | | | | | AC | 4PK820 | 38920-P2A-003 |
| PRELUDE | BA4, BA5 | 2000 | B20A | 87~91 | FAN | 5PK870 | 31110-PK1-003/4 |
| | | | | | PS | 4PK975 | 56992-PK1-013/014 |
| | | | | | AC | 5PK1050 | 38920-PK1-013/014 |
| | BA4,5(-120,130) | 2000 | B20A | 91~96 | FAN | 5PK945 | 31110-P12-A02 |
| | BA7 | 2100 | B21A | 90~91 | PS | 4PK975 | 56992-PK1-013/014 |
| | | | | | AC | 5PK1005 | 38920-PK1-A01/2 |
| | BA8, BA9 | 2200 | F22B | 91~61 | FAN | 5PK945 | 31110-P12-A01/2 |
| | | | | | FAN+AC | 5PK1105 | 38920-PTO-003/4 |
| | | | | | PS | 4PK1020 | 56992-P13-003 |
| | BB1, BB4 | 2200 | H22A | 91~96 | FAN | 6PK915 | 31110-P13-003 |
| | | | | | FAN+AC | 6PK1045 | 38920-P13-J01 |
| | | | | | PS | 4PK1020 | 56992-P13-003 |
| | BB5, BB7 | 2200 | F22B | 96~00 | FAN+AC | 6PK1075 | 38920-P5L-003/4 |
| | | | | | PS | 4PK1050 | 56992-P5K-003/4 |
| | BB6, BB8 | 2200 | H22A | 96~00 | FAN+AC | 6PK1045 | 38920-P13-J01 |
| | | | | | PS | 4PK1020 | 56992-P13-003 |
| RAFAGA | CE4 | 2000 | G20A | 93~97 | FAN | 5PK820 | 31110-PV3-003/4 |
| | | | | | PS | 4PK700 | 56992-PV3-003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003/4 |
| | CE5 | 2500 | G25A | 93~97 | FAN | 5PK820 | 31110-PV3-003/4 |
| | | | | | PS | 4PK700 | 56992-PV3-003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003/4 |
| S-MX | RH1, RH2 | 2000 | B20B | 96~02 | FAN | 4PK835 | 31110-P3G-003/4 |
| | | | | | PS | 4PK935 | 56992-P3G-003 |
| | | | | | AC | 4PK945 | 38920-P3G-003/4 |
| STEP WGN | RF1, RF2 | 2000 | B20B | 96~01 | FAN | 4PK835 | 31110-P3G-003/4 |
| | | | | | PS | 4PK935 | 56992-P3G-003 |
| | | | | | AC | 4PK945 | 38920-P3G-003/4 |
| STREAM | RN1, RN2 | 1700 | D17A | 00~ | PS | 4PK1025 | 56992-PSA-004 |
| | RN3, RN4 | 2000 | K20A | 00~ | FAN+AC | 7PK1770 | 38920-PNA-004/013 |
| STREET | HH3,4 | 660 | E07A | 88~99 | FAN | 3PK635 | 31110-P36-003 |
| THAT'S | LA-JD1 | 660 | E07Z | 02~04 | FAN+AC | 3PK670 | 31110-PFB-003 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WHIT FAN |
| TODAY | JA2, JA3, JW3, JW4 | 660 | E07A | 90~93 | FAN | 3PK670 | 31110-PZ1-003/4 |
| | JA4,5 | 660 | E07A | 93~98 | FAN | 4PK1105 | 38920-P64-003/4 |
| | | | | | PS | 3PK690 | 56992-P64-003/4 |
| | | | | | AC | | WHIT FAN |
| TORNEO | CF3 | 1800 | F18B | 97~02 | FAN+AC | 6PK1080 | 38920-PCA-003/4 |
| | CF4(SOHC, VTS, LEV) | 2000 | F20B | 97~02 | FAN+AC | 6PK1080 | 38920-PCA-003/4 |
| | CF4(DOHC, SIR) | 2000 | F20B | 97~ | FAN+AC | 6PK1045 | 38920-P13-J01 |
| | CF5 | 2000 | F20B | 97~02 | FAN+AC | 6PK1080 | 38920-PCA-003/4 |
| | CL3 | 2000 | F20B | 00~ | FAN+AC | 6PK1080 | 38920-PCA-003/4 |
| VAMOS | HM1, HM2(HORIZONTAL ENGINE) | 660 | E07Z | 99~ | FAN+AC | 3PK670 | 31110-PFB-003 |
| | HM1, HM2(VERTICAL ENGINE) | 660 | E07Z | 99~ | FAN | 3PK670 | 31110-PFB-003 |
| | | | | | PS | 5PK695 | 38920-PTF-003 |
| VIGOR | CA1 | 1800 | A18A | 85~89 | FAN | 5PK930 | 31110-PH2-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH1-003/4 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | CA2 | 1800 | B18A | 85~89 | FAN | 3PK805 | 31110-PH3-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |

# HONDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| VIGOR | CA3 | 2000 | B20A | 85~89 | FAN | 3PK805 | 31110-PH3-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | | | | | AC | 4PK905 | 38920-PH4-665 |
| | CA5 | 2000 | A20A | 87~89 | FAN | 5PK930 | 31110-PH2-J01/2 |
| | | | | | AC | 4PK910 | 38920-PH3-003/4 |
| | CB5 | 2000 | G20A | 89~91 | FAN | 4PK835 | 31110-PV0-003/4 |
| | | | | | PS | 4PK735 | 56992-PV0-003/4 |
| | | | | | AC | 4PK920 | 38920-PV0-003/4 |
| | CC3 | 2000 | G20A | 92~95 | FAN | 4PK830 | 31110-PV0-003 |
| | | | | | PS | 4PK735 | 56992-PV003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003 |
| | CC2 | 2500 | G25A | 92~95 | FAN | 4PK830 | 31110-PV0-003 |
| | | | | | PS | 4PK735 | 56992-PV003/4 |
| | | | | | AC | 5PK920 | 38920-PV3-003 |
| Z | PA1 | 660 | E07Z | 98~02 | FAN | 3PK670 | 31110-PFB-003 |
| | | | | | AC | 3PK670 | 38920-PFB-004 |

# ISUZU

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ASKA | BCK | 1800 | EJ18 | 90~94 | FAN | 5PK880 | 8092-18140 |
| | BCL, BCM | 2000 | EJ20 | 90~94 | FAN | 5PK880 | 8092-18140 |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | CJ1 | 2000 | F20B | 92~02 | FAN+AC | 6PK1115 | 38920-P0A-003/4 |
| | | | | | PS | 4PK1060 | 56992-P0A-003/4 |
| | | | | | AC | | WITH FAN |
| BIG HORN | UBS25 | 3200 | 6VD1 | 91~98 | FAN | 4PK965 | 8-94382-106-0 |
| | | | | | AC | 4PK805 | 8-94382-107-1 |
| ELF | ASK2F23, ASK4F23 | 2000 | NA20S | 95~99 | FAN | 4PK905 | 5-86122-887-0 |
| | ASH2F23, ASH4F23 | 2000 | KA20DE | 99~ | FAN | 4PK910 | 5-86122-891-0 |
| GEMINI | JT150 | 1500 | 4XC1 | 85~90 | FAN | 4PK685 | 8-84139-067-0 |
| | JT151F(~7100501) | 1500 | 4XC1 | 90~93 | FAN | 6PK965 | 8-94380-159-0 |
| | | | | | PS | 6PK965 | 8-94379-597-0 |
| | | | | | AC | 6PK775 | 8-94379-598-0 |
| | JT151F(7100502~) | 1500 | 4XC1 | 90~92 | FAN | 4PK695 | 8-94137-478-0 |
| | | | | | PS | 6PK965 | 8-94379-597-0 |
| | | | | | AC | 6PK1085 | 8-94380-158-0 |
| | | | | 92~93 | FAN | 4PK695 | 8-94137-478-0 |
| | | | | | PS | 6PK965 | 8-94379-597-0 |
| | | | | | AC | 6PK1095 | 8-97043-866-0 |
| | MJ4 | 1500 | D15B | 97~99 | FAN | 4PK800 | 5-86009-035-0 |
| | | | | | PS | 4PK845 | 5-86010-793-0 |
| | | | | | AC | 4PK820 | 5-86009-141 |
| | JT190 | 1600 | 4XE1 | 88~90 | FAN | 4PK710 | 8-94335-849-0 |
| | | | | | PS | 6PK935 | 8-94441-150-0 |
| | | | | | AC | 6PK1035 | 8-94361-889-0 |
| | JT191F(7100166~) | 1600 | 4XE1 | 90~93 | FAN | 4PK695 | 8-94137-478-0 |
| | | | | | PS | 6PK945 | 8-94364-580 |
| | | | | | AC | 6PK1045 | 8-94362-732-0 |
| | JT191F(~7100165) | 1600 | 4XE1 | 90~93 | FAN | 6PK965 | 8-94380-159-0 |
| | | | | | AC | 6PK1045 | 8-94362-732-0 |
| | MJ1, MJ2 | 1600 | ZC | 93~97 | FAN | 4PK780 | 31110-P01-003/4/5 |
| | | | | | PS | 4PK815 | 56992-P02-003/4 |
| | | | | | AC | 4PK795 | 38920-P01-003/4 |
| PA NERO | JT191F, JT191S | 1600 | 4XE1 (T) | 90~93 | FAN | 4PK695 | 8-94137-478-0 |
| | | | | | PS | 6PK935 | 8-94441-150-0 |
| | | | | | AC | 6PK1045 | 8-94362-732-0 |
| PIAZZA | JT221 | 1800 | 4XF1 | 91~93 | FAN | 6PK1210 | 8-97063-173-0 |

# MAZDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| AZ-3 | EC5SA | 1500 | B5 | 91~93 | FAN | 4PK885 | B587-18-381 |
| | | | | | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | 93~98 | FAN | 4PK885 | B587-18-381 |
| | | | | | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | | PS+AC | 4PK1015 | B588-15-909 |
| | ECPSA | 1800 | K8 | 93~98 | FAN | 5PK885 | K805-18-381B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908B |
| | | | | | PS | 4PK920 | K805-15-907B |
| | | | | | PS | 4PK920 | KF33-15-907 |
| AZ WAGON | CY21S, CZ21S | 660 | F6A | 97~98 | FAN | 4PK840 | 1A62-18-381 |
| | CY52S, CZ51S | 660 | F6A | 97~98 | FAN | 4PK840 | 1A62-18-381 |
| BONGO FRIENDEE · FREEDA | SGE3, SGE3F, SGEW, SGEWF | 2000 | FE | 95~ | FAN | 6PK1185 | FEMJ-18-381 |
| | SG5W, SG5WF | 2500 | J5 | 95~ | FAN | 6PK1400 | J503-18-381A/B |
| | | | | | AC | 4PK1030 | J503-15-908 |
| BONGO · SPECTRON | SE58T | 1500 | D5 | 90~95 | PS | 4PK870 | D530-15-907 |
| | | | | | AC | 4PK1085 | D530-15-909 |
| BONGO VAN · BONGO TRUCK | SK82V, T, M, L | 1800 | F8-E | 99~ | FAN | 4PK930 | F82A-18-381A |
| | | | | | AC | 4PK1105 | F82A-15-907A |
| BONGO BRAWNY VAN · BONGO BRAWNY TRUCK | SKE6V, T | 2000 | FE-E | 99~00 | FAN | 4PK930 | F82A-18-381A |
| | | | | | PS | 4PK975 | F82A-15-909 |
| | | | | | AC | 4PK1105 | F82A-15-907A |
| CAPELLA | CG2PP | 1800 | FP | 94~97 | FAN | 4PK920 | KF33-15-907 |
| | | | | | PS+AC | 5PK1150 | FP01-15-909 |
| | GF8P | 1800 | FP | 97~ | FAN | 4PK920 | FS59-18-381A/B |
| | | | | | FAN | 4PK920 | FS05-18-381 |
| | | | | | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS | 5PK1150 | FP01-15-909 |
| | | | | | PS+AC | 5PK1150 | FP02-15-909A |
| | CG2SP, CG2SR | 2000 | FS | 94~97 | FAN | 4PK920 | FS05-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | GFEP, GFER | 2000 | FS | 97~ | FAN | 4PK920 | FS59-18-381A/B |
| | | | | | FAN | 4PK920 | FS05-18-381 |
| | | | | | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | PS+AC | 5PK1165 | FS12-15-909A |
| CAPELLA CARGO | GV6V | 1600 | B6 | 92~99 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | GV8W | 1800 | F8 | 92~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | GVER | 2000 | FE | 92~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| CAPELLA WAGON | GV8W | 1800 | F8 | 94~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | GW8W | 1800 | FP | 97~01 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | FAN | 4PK920 | FS59-18-381B |
| | | | | | PS+AC | 5PK1150 | FP01-15-909 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | GVER, GVEW | 2000 | FE | 94~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | GWER, GWEW | 2000 | FS | 97~01 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | GW5R | 2500 | KL | 97~01 | FAN+AC | 5PK1010 | K805-15-908B |
| | | | | | PS+AC | 4PK920 | KF33-15-907 |
| CAPELLA · TELSTAR | GD6P, GV6V | 1600 | B6 | 87~91 | PS | 4PK990 | B661-15-909 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | | | | | PS | 4PK875 | B630-15-907A |
| | GD8AF, GD8P, GD8PF GD8RF, GD8S | 1800 | F8 | 87~91 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | | | | | PS+AC | 5PK1070 | FE4N-15-909A |
| | | | | | AC | 5PK950 | F201-15-908A |
| | GD8J, GD8Y, GD8W | 1800 | F8 | 87~92 | FAN | 4PK810 | F8B5-18-381 |

# MAZDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CAPELLA · TELSTAR | GD8J, GD8Y, GD8W | 1800 | F8 | 87~92 | PS | 5PK1010 | F201-15-907A |
| | | | | | FAN | 4PK810 | F8BR-18-381C |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | GD8A, GD8B, GD8PF GD8R, GD8S | 1800 | F8 | 88~91 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1070 | FE4N-15-909A |
| | GE8PF | 1800 | K8 | 91~94 | FAN | 5PK855 | K805-18-381A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | AC | 5PK1010 | K805-15-908A |
| | GDEA, GDEAF, GDEP GDEPF, GDER, GDES | 2000 | FE | 87~91 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | | | | 88~91 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1070 | FE4N-15-909A |
| | | | | | AC | 5PK950 | F201-15-908A |
| | GEEPF | 2000 | KF | 91~96 | FAN | 5PK855 | K805-18-381A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | AC | 5PK1010 | K805-15-908A |
| | GESRF | 2000 | FS | 91~94 | FAN | 4PK920 | FS05-18-381 |
| | | | | | PS | 5PK1030 | F505-15-907 |
| | | | | | PS+AC | 5PK1165 | F505-15-909 |
| | GF-GWER | 2000 | FS-ZE | 97~02 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | AC | | WITH PS |
| | GF-GWERF | 2000 | FS-ZE | 97~99 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | AC | | WITH PS |
| | GF-GFERF | 2000 | FS | 97~99 | FAN | 4PK920 | KF33-15-907 |
| | | | | | PS | 5PK1165 | FS505-15-909 |
| CLEF | GEEPA | 2000 | KF | 92~04 | FAN | 5PK855 | K805-18-981A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | GESRA | 2000 | FS | 92~94 | FAN | 4PK920 | FS05-18-381 |
| | | | | | FAN+AC | 4PK920 | FS05-18-381 |
| | | | | | PS | 5PK1030 | FS05-15-907 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | GE5PA | 2500 | KL | 92~94 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| COSMO | JC3SE | 1300 | RE13B | 90~94 | FAN | 5PK815 | N390-18-981 |
| | JC3S | 1300 | RE13B | 94~95 | FAN | 5PK815 | N390-18-981 |
| | JCESE | 2000 | RE20B | 90~94 | FAN | 5PK815 | N390-18-981 |
| | JCES | 2000 | RE20B | 94~95 | FAN | 5PK815 | N390-18-981 |
| CRONOS · MS-6 | GE8P | 1800 | K8 | 91~94 | FAN | 5PK855 | K805-18-831A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | GESR | 2000 | FS | 91~96 | FAN | 4PK920 | FS05-18-381 |
| | | | | | FAN | 4PK920 | FS59-18-381 |
| | | | | | PS | 5PK1030 | FS05-15-907 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | PS+AC | 5PK1165 | FS12-15-909 |
| | GEEP | 2000 | KF | 91~96 | FAN | 5PK855 | K805-18-831A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | GE5P | 2500 | KL | 91~96 | FAN | 5PK855 | K805-18-831A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| DEMIO | DW3W | 1300 | B3 | 96~02 | FAN | 4PK875 | B3C7-18-381B |
| | | | | | PS | 4PK850 | B3C7-15-907C |
| | | | | | PS+AC | 4PK955 | B5C8-15-909 |
| | | | | | PS+AC | 4PK955 | B5C7-15-909 |
| | DW5W | 1500 | B5 | 96~02 | FAN | 4PK875 | B3C7-18-381B |
| | | | | | PS | 4PK850 | B3C7-15-907C |
| | | | | | PS+AC | 4PK955 | B5C8-15-909 |
| | | | | | PS+AC | 4PK955 | B5C7-15-909 |

# MAZDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ETUDE | BFSP | 1500 | B5 | 88~90 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | AC | 4PK890 | B501-15-908 |
| | | | | | AC | 4PK990 | B660-15-908 |
| | BFMP | 1600 | B6 | 87~90 | PS+AC | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK1000 | B6A9-15-909A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | AC | 4PK905 | B5A9-15-908A |
| | | | | | AC | 4PK890 | B660-15-908 |
| EUNOS 100 | BG8PE | 1800 | BP | 89~93 | PS | 4PK890 | B366-15-907 |
| | | | | | AC | 4PK890 | BP25-15-908 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| EUNOS 300 | MA8PE | 1800 | F8 | 89~92 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | MAEPE | 2000 | FE | 89~92 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| EUNOS 500 | CA8PE | 1800 | K8 | 92~94 | FAN | 5PK855 | K805-18-381A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | PS+AC | 5PK1010 | K805-15-908A |
| | CAEPE | 2000 | KF | 92~94 | FAN | 5PK855 | K805-18-381A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | PS+AC | 5PK1010 | K805-15-908A |
| EUNOS CARGO | SE58TE, SS58VE | 1500 | D5 | 90~93 | PS | 4PK870 | D530-15-907 |
| | | | | | AC | 4PK1085 | D530-15-909 |
| | SSE8WE | 2000 | FE | 90~93 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| EUNOS PRESSO | EC5S | 1500 | B5 | 93~98 | FAN | 4PK885 | B587-18-381 |
| | | | | | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | | PS+AC | 4PK1015 | B588-15-909 |
| | EC8SE | 1800 | K8 | 91~93 | FAN | 5PK885 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | EC8S | 1800 | K8 | 93~98 | FAN | 5PK885 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907B |
| | | | | | PS | 4PK920 | KF33-15-907 |
| EUNOS ROADSTER | E-NA6CE | 1600 | B6 | 89~93 | PS+AC | 4PK955 | B63H-15-909 |
| | | | | | PS | 4PK865 | B61P-15-907 |
| | | | | | AC | 4PK855 | B63H-15-908 |
| FAMILIA · LASER | BF3V, BF3VF | 1300 | E3 | 85~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | PS+AC | 4PK1190 | E331-15-907 |
| | BFTP | 1300 | B3 | 87~88 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | AC | 4PK890 | B501-15-908 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | BG3P, BG3PF, BG3S | 1300 | B3 | 89~90 | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1000 | B366-15-909 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | | | | | AC | 4PK890 | BP25-15-908 |
| | | | | 90~96 | PS | 4PK890 | B366-15-907 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | | | | | PS+AC | 4PK1000 | B366-15-909 |
| | BHA3P, BHA3PF, BHA3S | 1300 | B3 | 96~98 | FAN | 4PK885 | B587-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | ZL01-15-907 |
| | | | | | PS+AC | 4PK1005 | BPE7-15-909 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | BF5P, BF5R, BF5S | 1500 | E5 | 85~87 | PS | 4PK1040 | E561-15-907 |

# MAZDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| FAMILIA · LASER | BF5P, BF5R, BF5S | 1500 | E5 | 85~87 | PS+AC | 4PK1190 | E331-15-907 |
| | BF5V, BF5VF, BF5W | 1500 | E5 | 85~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | PS+AC | 4PK1190 | E331-15-907 |
| | BFSP, BFSR | 1500 | B5 | 87~89 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | | | | | AC | 4PK890 | B501-15-908 |
| | BG5P, BG5PF, BG5S | 1500 | B5 | 89~90 | PS | 4PK890 | B366-15-907 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | | | | | AC | 4PK890 | BP25-15-908 |
| | | | | | PS+AC | 4PK1000 | B366-15-909 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | 90~94 | PS | 4PK890 | B366-15-907 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | | | | | PS+AC | 4PK1000 | B366-15-909 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | BHA5P, BHA5PF, BHA5S, BHA5SF | 1500 | B5 | 94~95 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | AC | 4PK870 | B3P5-15-908 |
| | | | | 95~96 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | | | | | AC | 4PK870 | B3P5-15-908 |
| | BDALP, BHALPF, BDALS, BHALSF | 1500 | Z5 | 94~95 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | AC | 4PK870 | B3P5-15-908 |
| | | | | 95~96 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | | | | | AC | 4PK870 | B3P5-15-908 |
| | | | | 96~98 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK1000 | BPD4-15-909 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | BFMP, BFMR, BFMS | 1600 | B6 | 85~89 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | PS+AC | 4PK1000 | B6A9-15-909A |
| | | | | | AC | 4PK890 | B660-15-908 |
| | | | | | AC | 4PK890 | B501-15-908 |
| | BG6P, BG6PF, BG6S | 1600 | B6 | 89~91 | PS | 4PK890 | B366-15-907 |
| | | | | | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | | AC | 4PK875 | B366-15-908 |
| | | | | | AC | 4PK890 | BP25-15-908 |
| | BG6R, BG6Z | 1600 | B6 | 89~96 | PS | 4PK890 | B366-15-907 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | | | | | PS+AC | 4PK1000 | B6A9-15-909A |
| | BHA6R, BHA6RF | 1600 | B6 | 94~95 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |

# MAZDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| FAMILIA · LASER | BHA6R, BHA6RF | 1600 | B6 | 94~95 | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK995 | B596-15-909 |
| | | | | 95~96 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | BHA6R, BHA6RF | 1600 | B6 | 96~98 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | ZL01-15-907 |
| | | | | | PS+AC | 4PK1000 | BPD4-15-909 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | BJ3P, BJ3PF | 1300 | B3-ME | 98~02 | FAN+AC | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | BVY10 | 1300 | GA13 | 94~99 | FAN | 4PK1110 | IN20-18-381 |
| | BJ5P,PF | 1500 | ZL-DE, ZL-VE | 98~ | FAN+AC | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | BG8Z | 1800 | BP | 89~90 | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1000 | B6A9-15-909A |
| | BG8R | 1800 | BP | 89~94 | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | BG8P,BG8R, BG8S,BG8Z, BG8PF, BG8RF | 1800 | BP | 90~94 | FAN | 4PK885 | B587-18-381 |
| | | | | | PS | 4PK890 | B366-15-907 |
| | | | | | PS+AC | 4PK1015 | B6S7-15-909 |
| | | | | | AC | 4PK885 | B366-15-908A |
| | BHA8P, BHA8PF, BHA8S | 1800 | BP | 94~95 | FAN | 4PK885 | B596-18-281 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | 95~96 | FAN | 4PK885 | B596-18-381 |
| | | | | | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | | | | 96~98 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | ZL01-15-907 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| FAMILIA S WAGON · LASER RIDEMA | BJ5W, BJ5WF | 1500 | ZL-DE | 98~00 | FAN+AC | 4PK885 | B6BF-18-381 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | ZL-VE | | PS+AC | 4PK1005 | BPH7-15-909 |
| | BJ8W, BJ8WF | 1800 | FP-DE | 98~00 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | BJFW, BJFWF | 2000 | FS-ZE | 99~03 | FAN | 4PK920 | FJS2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| FAMILIA VAN · FAMILIA WAGON | BF3V, BW3W | 1300 | E3 | 89~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | PS+AC | 4PK1190 | E331-15-907 |
| | | | E3 | 94~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | AC | 4PK1190 | E331-15-907 |
| | BV10 | 1300 | GA13DS | 94~97 | FAN | 4PK910 | 1N08-18-381 |
| | | | | | FAN | 4PK805 | 1N01-18-381 |
| | | | | | PS | 4PK810 | 1N04-15-909 |
| | | | | | AC | 4PK830 | 1N04-15-908 |
| | | | GA13DE | 97~99 | FAN+AC | 4PK1110 | 1N20-18-381 |
| | | | | | PS+WP | 4PK810 | 1N15-15-909 |
| | BF5V, BW5W | 1500 | E5 | 89~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | PS+AC | 4PK1190 | E331-15-907 |
| | | | | 94~94 | PS | 4PK1040 | E561-15-907 |
| | | | | | AC | 4PK1190 | E331-15-907 |

# MAZDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| FAMILIA VAN<br>· FAMILIA WAGON | BMVFY10, BVFNY10<br>BWFY10, BWFNY10 | 1500 | GA15DS | 94~ | FAN | 4PK910 | 1N08-18-381 |
| | | | | | FAN | 4PK805 | 1N01-18-381 |
| | | | | | FAN+AC | 4PK1110 | 1N07-18-381 |
| | | | | | PS | 4PK810 | 1N04-15-909 |
| | | | | | PS | 4PK830 | 1N04-15-908 |
| | | | | | AC | 4PK830 | 1N04-15-908 |
| | BWFY10, BWFNY10 | 1500 | GA15DE | 95~ | FAN+AC | 4PK1110 | 1N07-18-381 |
| | | | | | PS | 4PK810 | 1N15-15-909 |
| | BVFY10, BVFNY10 | 1500 | GA15DE | 97~ | FAN+AC | 4PK1110 | 1N07-18-381 |
| | | | | | PS+WP | 4PK810 | 1N15-15-909 |
| | BF6M, BWMR | 1600 | B6 | 85~94 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | | | | | PS+AC | 4PK990 | B661-15-909 |
| | | | | | AC | 4PK890 | B501-15-908 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | | | | | AC | 4PK890 | B660-15-908 |
| | | | | 94~94 | PS | 4PK875 | B630-15-907A |
| | | | | | PS+AC | 4PK980 | B612-15-909A |
| | GF-BJ8W | 1800 | FP | 98.06-00.10 | FAN+AC | 4PK920 | FSJ2-18-381 |
| | | | | | PS | 5PK1030 | FS05-15-907 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| FESTIVA | DA1PF | 1100 | B1 | 85~93 | PS | 4PK800 | B301-15-907 |
| | | | | | PS+AC | 4PK945 | B301-15-909 |
| | DA3PF | 1300 | B3 | 85~93 | PS | 4PK800 | B301-15-907 |
| | | | | | PS+AC | 4PK945 | B301-15-909 |
| | D23PF | 1300 | B3 | 92~97 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK850 | B3C7-15-907B/C |
| | | | | | PS+AC | 4PK965 | B3C7-15-909B/C |
| | | | | | PS+AC | 4PK965 | B3J2-15-909 |
| | DAJPF | 1300 | BJ | 86~89 | AC | 4PK875 | B630-15-907A |
| | | | | 89~92 | PS+AC | 4PK875 | B630-15-907A |
| | D25PF | 1500 | B5 | 92~97 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK850 | B3C7-15-907B/C |
| | | | | | PS+AC | 4PK965 | B3C7-15-909B/C |
| | | | | | PS+AC | 4PK965 | B3J2-15-909 |
| FESTIVA MINI WAGON | DW3WF | 1300 | B3 | 96~02 | FAN | 4PK875 | B3C7-18-381B |
| | | | | | PS | 4PK850 | B3C7-15-907C |
| | | | | | PS+AC | 4PK955 | B5C8-15-909 |
| | | | | | PS+AC | 4PK955 | B5C7-15-909 |
| | DW5WF | 1500 | B5 | 96~02 | FAN | 4PK875 | B3C7-18-381B |
| | | | | | PS | 4PK850 | B3C7-15-907C |
| | | | | | PS+AC | 4PK955 | B5C8-15-909 |
| | | | | | PS+AC | 4PK955 | B5C7-15-909 |
| J80 · SPECTRON | SE58TF, SS58VF | 1500 | D5 | 90~93 | PS+AC | 4PK1085 | D530-15-909 |
| | | | | | PS | 4PK870 | D530-15-907 |
| | | | | 93~95 | PS+AC | 4PK1085 | D530-15-909 |
| | | | | | PS | 4PK870 | D530-15-907 |
| LANTIS | CBA8P | 1800 | BP | 93~95 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | FAN | 4PK885 | B596-18-381 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS+AC | 4PK1000 | BPE6-15-909 |
| | | | | | PS+AC | 4PK995 | B595-15-909 |
| | | | | 95~96 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | FAN | 4PK885 | B596-18-381 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS+AC | 4PK1000 | BPE6-45-909 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | | | | 96~97 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | FAN | 4PK885 | B596-18-381 |
| | | | | | PS | 4PK890 | B6BF-15-907 |
| | | | | | PS | 4PK890 | B596-15-907 |
| | | | | | PS+AC | 4PK1005 | BPH7-15-909 |
| | CBAEP | 2000 | KF | 93~97 | FAN | 5PK885 | K805-18-381B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908B |

# MAZDA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| LANTIS | CBAEP | 2000 | KF | 93~97 | PS | 4PK920 | FS05-18-381 |
| | | | | | PS | 4PK920 | K805-15-907B |
| MPV | LWEW | 2000 | FS | 99~2 | FAN | 4PK920 | FSJ2-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| MS-6 | E-GE8P | 1800 | K8-ZE | 91~94 | FAN+AC | 5PK1010 | K805-15-908A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | PS+AC | | WITH FAN |
| | E-GEEP | 2000 | KF-ZE | 91~94 | FAN+AC | 5PK1010 | K805-15-908A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | | | | | PS+AC | | WITH FAN |
| | E-GESR | 2000 | FS-DE | 92~94 | FAN | 4PK920 | FS05-18-381 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | PS | 5PK1030 | FS05-15-907 |
| MS-8 | MBEP | 2000 | KF | 92~98 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | MB5A, MB5P | 2500 | KL | 92~98 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| MS-9 | HD5S | 2500 | J5 | 91~93 | FAN | 4PK1020 | JE48-15-908 |
| | HDES | 3000 | JE | 91~93 | FAN | 4PK1020 | JE48-15-908 |
| MX-6 | GEEB | 2000 | KF | 92~94 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A |
| | | | | | PS | 4PK920 | K805-15-907A |
| | GE5B | 2500 | KL | 92~96 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A |
| | | | | | PS | 4PK920 | K805-15-907A |
| PERSONA | MA8P | 1800 | F8 | 88~92 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | MAEP | 2000 | FE | 88~92 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| PREMACY | GF-CP8W | 1800 | FP-DE | 99.04-05.02 | FAN+AC | 4PK920 | FSJ2-18-381 |
| | | | | | PS | 5PK1165 | FS05-15-909 |
| | | | | | AC | | WITH PS |
| PROBE | BT21, BT22 | 2200 | F2 | 88~89 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F230-15-909 |
| | 1ZVBT21C, 1ZVBT22L | 2200 | F2 | 88~92 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F230-15-909 |
| | | | | | FAN | 3PK765 | F262-18-381A |
| | 1ZVCT22B | 2500 | KL | 92~ | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 4PK1010 | K805-18-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | 1ZVTU(PT21) | 3000 | F3 | 89~92 | FAN | 4PK900 | AS01-15-907C |
| | | | | | PS+AC | 6PK710 | AS03-15-909B |
| REVUE | DB3PA | 1300 | B3 | 90~95 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK845 | B3C7-15-907A |
| | | | | | PS | 4PK850 | B3C7-15-907B/C |
| | | | | | PS+AC | 4PK960 | B3C7-15-909A |
| | | | | | PS+AC | 4PK965 | B3C7-15-909B/C |
| | | | | 95~99 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK850 | B3C7-15-907C |
| | | | | | PS+AC | 4PK965 | B5C8-15-909C |
| | E-DB5PA | 1300 | B5-M1 | 90~99 | FAN | 4PK875 | B3C7-18-381A |
| | | | | | AC | 4PK875 | B3C7-18-381A |
| | DB5PA | 1500 | B5 | 90~95 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK845 | B3C7-15-907A |
| | | | | | PS | 4PK850 | B3C7-15-907B/C |
| | | | | | PS+AC | 4PK960 | B3C7-15-909A |
| | | | | | PS+AC | 4PK965 | B3C7-15-909B/C |
| | | | B5 | 95~99 | FAN | 4PK875 | B3C7-18-381A/B |
| | | | | | PS | 4PK850 | B3C7-15-907B/C |
| | | | | | PS+AC | 4PK960 | B3C7-15-909A |
| ROADSTAR | NB6C | 1600 | B6 | 97~02 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS+AC | 4PK950 | BPF3-15-909A |

# MAZDA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ROADSTAR | NB6C | 1600 | B6 | 97~02 | FAN | 4PK885 | BP4W-18-381 |
| | | | | | PS+AC | P4K950 | BP5A-15-909A |
| | NA8C | 1800 | BP | 93~97 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | PS+AC | 4PK950 | BPF3-15-909A |
| | | | | | AC | 4PK850 | B3C7-15-907C |
| | | | | | FAN | 4PK885 | B596-18-381 |
| | NB8C | 1800 | BP | 97~02 | FAN | 4PK885 | B6BF-18-381 |
| | | | | | FAN | 4PK885 | BP4W-18-381 |
| | | | | | PS | 4PK860 | BP4W-15-907A |
| | | | | | PS+AC | 4PK950 | BPF3-15-909A |
| | | | | | PS+AC | 4PK950 | BP5A-15-909A |
| | | | | | AC | 4PK850 | B3C7-15-907C |
| | | | | | AC | 4PK860 | BP4W-15-907A |
| SAVANNA RX-7 · ∑fini RX-7 | E-FD3S | 1300 | 13BRW | 91~02 | FAN | 5PK1355 | N3A1-18-381 |
| | | | | | FAN | 5PK1310 | N3A2-18-381 |
| | | | | | PS+AC | 6PK1045 | N3A1-15-908 |
| RX-7 | E-FD3F | 1300 | 13B-REW | 91~ | FAN | 5PK1355 | N3A1-18-381 |
| | | | | | FAN | 5PK1310 | N3A2-18-381 |
| | | | | | PS+AC | 6PK1045 | N3A1-15-908 |
| SCRUM | DL51V, DM51V | 660 | F6A | 91~98 | FAN | 4PK640 | ZZS3-18-381 |
| | | | | | FAN+AC | 4PK835 | ZZS6-18-381/A |
| | DJ51T, DK51T, DJ51B, DK51B | 660 | F6A | 91~97 | AC | 4PK685 | ZZS5-18-381 |
| | | | | | AC | 4PK670 | ZZS4-18-381 |
| | | | | 97~98 | AC | 4PK750 | 1A00-18-381 |
| SENTIA | HD5S | 2500 | J5 | 91~96 | FAN | 4PK1020 | JF48-15-908 |
| | HDES | 3000 | JE | 91~96 | FAN | 4PK1020 | JF48-15-908 |
| | HEEA, HEEP | 3000 | JE | 95~00 | FAN | 4PK1005 | JE53-18-381 |
| | | | | | PS | 4PK910 | JE74-15-907 |
| | | | | | AC | 5PK985 | JE74-75-908 |
| TELSTAR | GE8PF | 1800 | K8 | 91~94 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | GEEPF | 2000 | KF | 91~94 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | | | | 94~96 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-18-908A/B |
| | | | | | PS | 4PK920 | K805-18-907A/B |
| | GESRF | 2000 | FS | 91~94 | FAN | 4PK920 | FS59-18-381 |
| | | | | | FAN | 4PK920 | FS05-18-381 |
| | | | | | PS | 5PK1030 | FS05-15-907 |
| | | | | | PS | 5PK1030 | FS11-15-907 |
| | | | | | PS+AC | 5PK1165 | FS05-15-909 |
| | | | | | PS+AC | 5PK1165 | FS12-15-909A |
| | GE5PF | 2500 | KL | 92~94 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-15-908A/B |
| | | | | | PS | 4PK920 | K805-15-907A/B |
| | | | | 94~96 | FAN | 5PK855 | K805-18-381A/B |
| | | | | | FAN+AC | 5PK1010 | K805-18-908A/B |
| | | | | | PS | 4PK920 | K805-18-907A/B |
| TELSTAR WAGON | GV8WF | 1800 | F8 | 92~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | GVWRF, GVEWF | 2000 | FE | 92~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1060 | F201-15-909A |
| | E-GVERF | 2000 | FE | 90~97 | FAN | 3PK760 | F201-18-381A |
| | | | | | PS+AC | 5PK1070 | FE4N-15-909A |
| | | | | | PS | 5PK1010 | F201-15-907A |
| | | | | | AC | 5PK950 | F201-15-908A |
| | GF-GW5RF(DSL) | 2500 | KL-ZE | 97~99 | FAN+AC | 5PK1010 | K805-15-908B |
| | | | | | PS | 4PK920 | KF33-15-907 |

# MITSUBISHI



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ASPIRE | EA1A, EC1A | 1800 | 4G93 | 98~00 | FAN+AC | 4PK775 | MD312400 |
| | | | | | PS | 5PK1305 | MD331884 |
| | | | | | AC | | WITH PS |
| | EA7A, EC7A | 2000 | 4G94 | 00~03 | FAN+AC | 4PK775 | MD312400 |
| | | | | | PS | 5PK1305 | MD331884 |
| | | | | | AC | | WITH PS |
| BRAVO | U41V, U42V(CAB) | 660 | 3G83 | 91~93 | PS | 3PK1030 | MD187353(ATM) |
| | | | | 91~93 | PS | 3PK1030 | MD187353(MTM) |
| | U41V, U42V(TB) | | 3G83T | 91~93 | FAN | 3PK745 | MD173535(ATM) |
| | | | | | PS | 3PK1030 | MD187353 |
| | | | | 91~93 | FAN | 3PK765 | MD173536(MTM) |
| | | | | | PS | 3PK1030 | MD187353 |
| | U43V, U44V | 660 | 4A30 | 94~99 | FAN+AC | 4PK845 | MR116685 |
| | | | | | PS | 3PK1080 | MD311454 |
| CANTER | FA500, FA510 | 2000 | 4G63 | 97~99 | FAN | 4PK975 | MD186123 |
| | | | | | PS | 4PK925 | MD172376 |
| | | | | | AC | 4PK1280 | MC148130 |
| | FA580, FA590 | 2000 | 4G63 | 97~99 | FAN | 4PK975 | MD186123 |
| | | | | | PS | 4PK925 | MD172376 |
| | | | | | AC | 4PK1280 | MC148130 |
| | FA523(LPG) | 2400 | 4G64 | 96~99 | FAN | 4PK975 | MD186123 |
| | | | | | AC | 4PK1280 | MC148130 |
| | FC563(LPG) | 2400 | 4G64 | 96~99 | FAN | 4PK975 | MD186123 |
| | | | | | PS | 4PK925 | MD172376 |
| | | | | | AC | 4PK1280 | MC148130 |
| | FB523BA | 2400 | 4G64 | 99~ | FAN | 4PK975 | MD186123 |
| | | | | | PS | 4PK1055 | MD337658 |
| | FE82DEV | 4900 | 4M50 | 02~ | FAN | 6PK1245 | ME241664 |
| | FE63DCY | 4900 | 4M50T | 02~ | FAN | 6PK1255 | ME241666 |
| | FE50EB | 5200 | 4M51 | 99~02 | FAN | 6PK1245 | ME241664 |
| | FE63EC | 5200 | 4M51 | 99~02 | AC | 6PK1195 | ME241667 |
| CHALLENGER | K94W, K94WG(DSL) | 2500 | 4D56 | 96~97 | PS | 4PK1120 | MD199826 |
| | K96W | 3000 | 6G72 | 96~97 | FAN | 5PK1130 | MD199223 |
| | | | | | PS | 4PK955 | MD308925 |
| | K99W | 3500 | 6G74 | 97~ | FAN | 5PK1120 | MD344842 |
| | | | | | PS | 4PK1090 | MD354423 |
| CHARIOT | D03W | 1800 | G62B | 83~86 | FAN | 4PK975 | MD074521 |
| | D05W | 1800 | G37B | 84~91 | FAN | 4PK935 | MD069672 |
| | D08W | 2000 | G63B | 84~91 | FAN | 4PK975 | MD074251 |
| | N33W, N43W | 2000 | 4G63 | 91~92 | FAN | 4PK985 | MD132479(ATM) |
| | | | | | FAN | 4PK990 | MD122602(MTM) |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK930 | MZ701085 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | | AC | 4PK940 | MB568898 |
| | | | | 92~97 | FAN | 4PK985 | MD132479 |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK930 | MZ701085 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | | AC | 4PK940 | MB568898 |
| | N38W, N48W(DSL) | 2000 | 4D68 | 92~97 | PS | 4PK635 | MD186111 |
| | N34W, N44W | 2400 | 4G64 | 93~97 | FAN | 4PK990 | MD122602 |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK940 | MB568898 |
| CHARIOT GRANDIS | N84W, N94W | 2400 | 4G64 | 97~ | FAN | 5PK980 | MD325262 |
| | | | | | PS+AC | 5PK1390 | MD326781 |
| | N86W, N96W | 3000 | 6G72 | 99~ | PS+AC | 4PK920 | MD355999 |
| COLT | UA-Z26A | 1300 | 4G19 | 02~04 | FAN | 4PK790 | MN137180 |
| | UA-Z27A | 1500 | 4G15 | 02~04 | AC | 4PK790 | MN137180 |
| DEBONAIR | S11A | 2000 | 6G71 | 86~92 | FAN | 5PK1240 | MD134958/187461 |
| | | | | | ALT+PS | | WITH FAN |
| | S12A, S12AG | 3000 | 6G72 | 86~92 | FAN | 5PK1240 | MD134958 |
| | | | | | FAN | 5PK1240 | MD187461 |
| | | | | | FAN | 4PK925 | MD172376 |
| | S22A | 3000 | 6G72 | 92~00 | FAN | 5PK1240 | MD187461 |
| | | | | | FAN+AC | 4PK940 | MB568898 |

# MITSUBISHI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| DEBONAIR | S22A | 3000 | 6G72 | 92~00 | FAN+AC | 4PK950 | MB568899 |
| | | | | | AC | 4PK950 | MB568899 |
| | S26A | 3500 | 6G74 | 95~99 | PS | 4PK925 | MD172376 |
| | S27A | 3500 | 6G74 | 92~95 | FAN+AC | 6PK1150 | MB879764 |
| | | | | | PS | 4PK925 | MD172376 |
| DELICA | P02T | 1600 | 4G92 | 94~99 | FAN | 5PK985 | MD310370 |
| | | | | | PS | 5PK1035 | MD313071 |
| | | | | | AC | 5PK1240 | MB958695 |
| | P06V | 1600 | 4G92 | 94~99 | FAN | 5PK985 | MD310370 |
| | | | | | PS | 5PK1035 | MD310371 |
| | | | | | AC | 5PK1110 | MB917985 |
| | SK82TM, SK82VM | 1800 | F8E | 99~ | PS+AC | 4PK975 | MQ900832 |
| | | | | | AC | 4PK1105 | MQ900831 |
| | P13T | 2000 | 4G63 | 94~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MD310014 |
| | | | | | AC | 4PK950 | MB568899 |
| | P07V | 2000 | 4G63 | 94~96 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MD310014 |
| | | | | | AC | 4PK990 | MB657285 |
| | | | | 96~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1055 | MD337658 |
| | | | | | AC | 4PK990 | MB657285 |
| | P17V | 2000 | 4G63 | 94~96 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MD310014 |
| | | | | | AC | 4PK990 | MB657285 |
| | | | | 96~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1055 | MD337658 |
| | | | | | AC | 4PK990 | MB657285 |
| | P27V | 2000 | 4G63 | 94~96 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MD310014 |
| | | | | | AC | 4PK990 | MB657285 |
| | | | | 96~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1055 | MD337658 |
| | | | | | AC | 4PK990 | MB657285 |
| | PA3V | 2000 | 4G63 | 94~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MD310014 |
| | | | | | AC | 4PK940 | MB958696 |
| | P05T, P15T, P25T(DSL) | 2500 | 4D56 | 94~99 | PS | 4PK1120 | MD199826 |
| | PA5V, PB5V, PD5V(DSL) | 2500 | 4D56T | 94~99 | PS | 4PK1085 | MD311704 |
| | PB6W, PD6W, PF6W | 3000 | 6G72 | 94~04 | FAN | 5PK1130 | MD199223 |
| | | | | | PS | 4PK955 | MD308925 |
| DELICA SPACE GEAR | PA4W, PD4W | 2400 | 4G64 | 94~97 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1045 | MB310014 |
| | | | | | AC | 4PK940 | MB568898 |
| | PB4W, PC4W | 2400 | 4G64 | 99~ | FAN+AC | 4PK985 | MD186125 |
| | | | | | PS | 4PK1055 | MQ337658 |
| | | | | | AC | 4PK940 | MB568898 |
| | PA5W, PB5W(DSL) | 2500 | 4D56T | 94~99 | PS | 4PK1085 | MD311704 |
| | PA5V, PB5V, PD5V(DSL) | 2500 | 4D56T | 94~99 | PS | 4PK1085 | MD311704 |
| | PE8W, PF8W(DSL) | 2800 | 4M40T | 95~ | AC | 4PK930 | MB439494 |
| | PB6W, PD6W, PF6W | 3000 | 6G72 | 94~04 | FAN | 5PK1130 | MD199223 |
| | | | | | PS | 4PK955 | MD308925 |
| DIAMANTE | F11A | 2000 | 6G71 | 90~92 | FAN | 5PK1240 | MD187461 |
| | | | | | AC | 4PK940 | MB5568898 |
| | | | | | FAN | 5PK1240 | MD134958 |
| | F12A | 2000 | 6A12 | 92~94 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1105 | MB946338 |
| | F13A, F15A, F25A | 2500 | 6G73 | 90~91 | FAN+AC | 6PK1150 | MB879764 |
| | | | | | FAN+AC | 6PK1150 | MB813600 |
| | | | | 91~94 | FAN+AC | 6PK1150 | MB879764 |
| | | | | | FAN+AC | 6PK1150 | MB813600 |
| | | | | | PS | 4PK925 | MD172376 |
| | F13A, F13AK | 2500 | 6G73 | 90.~94 | FAN | 6PK1070 | MD187463 |
| | | | | | FAN | 6PK1070 | MD165995 |
| | | | | | PS | 4PK925 | MD172376 |
| | | | | | AC | 6PK1150 | MB897764 |

# MITSUBISHI



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| DIAMANTE | F13A, F13AK | 2500 | 6G73 | 94~95 | FAN+AC | 6PK1200 | MD318874 |
| | | | | | PS+AC | 4PK900 | MD322330 |
| | F13A, F41A | 2500 | 6G73 | 95~02 | FAN | 6PK1200 | MD323573 |
| | | | | | PS | 4PK900 | MD322330 |
| | F17A, F27A | 3000 | 6G72 | 92~ | FAN | 6PK1150 | MB813600 |
| | F36A | 3000 | 6G72 | 95~02 | FAN | 6PK1200 | MD368275 |
| | F36A, F36W, F46A, F47A | 3000 | 6G72 | 95~97 | FAN+AC | 6PK1200 | MD323573 |
| | | | | | FAN+AC | 6PK1220 | MD350259 |
| | | | | | PS | 4PK900 | MD322330 |
| | | | | | PS | 4PK920 | MD355999 |
| DINGO | CQ2A | 1500 | 4G15 | 98~ | FAN+AC | 5PK865 | MD366257 |
| | | | | | PS | 5PK1065 | MD375935 |
| | | | | | PS | 5PK1060 | MD325599 |
| | | | | | AC | | WITH PS |
| DION | CR6W | 2000 | 4G94 | 00~ | FAN+AC | 4PK775 | MD312400 |
| | | | | | PS | 5PK1305 | MD331884 |
| | | | | | AC | | WITH PS |
| ECLIPSE | D22A, D27A | 2000 | 4G63 | 89~00 | FAN | 4PK985 | MD144817(ATM) |
| | | | | | FAN | 4PK990 | MD137594(MTM) |
| | | | | | AC | 4PK940 | MB568898 |
| EMERAUDE | E52A | 1800 | 4G93 | 92~94 | FAN | 4PK780 | MD163032 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | AC | 5PK1115 | MB813272 |
| | E72A | 1800 | 4G93 | 92~96 | FAN | 4PK780 | MD163032 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | AC | 5PK1115 | MB813272 |
| | E53A | 1800 | 6A11 | 92~96 | FAN | 4PK945 | MD184973 |
| | | | | | PS | 5PK925 | MD180106 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E54A, E64A, E84A | 2000 | 6A12 | 92~96 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E74A | 2000 | 6A12 | 94~96 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 5PK1065 | MD946603 |
| FTO | DE2A | 1800 | 4G93 | 94~99 | FAN | 4PK775 | MD312400 |
| | | | | | PS+AC | 5PK1330 | MD317245 |
| | DE3A | 2000 | 6A12 | 94~00 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 6PK1070 | MD318667 |
| GALANT · ETERNA | E31A | 1600 | 4G32 | 87~92 | FAN | 4PK935 | MD069672 |
| | E32A | 1800 | 4G37 | 87~92 | FAN | 4PK935 | MD069672 |
| | E32AR | 1800 | 4G37 | 88~92 | FAN | 4PK935 | MD107671 |
| | E35A | 1800 | 4G67 | 89~92 | FAN | 4PK985 | MD144817(MTM) |
| | | | | | FAN | 4PK995 | MD144639(ATM) |
| | | | | | FAN | 4PK990 | MD137594(ATM) |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E37A | 1800 | 4G37 | 88~92 | FAN | 4PK935 | MD069672 |
| | | | | | AC | 4PK930 | MZ701085 |
| | EA1A, EC1A | 1800 | 4G93 | 96~00 | FAN | 4PK780 | MD334464 |
| | | | | | FAN | 4PK775 | MD312400 |
| | | | | | PS | 5PK1305 | MD331884 |
| | E52A | 1800 | 4G93 | 92~96 | FAN+AC | 4PK780 | MD163032 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | AC | 5PK1115 | MB813272 |
| | E53A | 1800 | 6A11 | 92~95 | FAN+AC | 4PK945 | MD184973 |
| | | | | | PS | 5PK925 | MD180106 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E72A | 1800 | 4G93 | 92~95 | FAN+AC | 5PK950 | MD188026 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | AC | 5PK1115 | MB813272 |
| | EA7A, EC7A | 2000 | 4G94 | 00~ | FAN+AC | 4PK775 | MD312400 |
| | | | | | PS | 5PK1305 | MD331884 |
| | | | | | AC | | WITH PS |
| | E33A | 2000 | 4G63 | 87~92 | FAN | 4PK985 | MD144817 |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E33A(SRG, SRX) | 2000 | 4G63 | 89~92 | FAN | 4PK995 | MD144639 |

# MITSUBISHI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| GALANT · ETERNA | E33A(SRG, SRX) | 2000 | 4G63 | 89~92 | FAN | 4PK990 | MD137594 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E33A(SNG, SNS, SRG, SRS) | 2000 | 4G63 | 89~92 | FAN | 5PK990 | MD159482 |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E33A(SNGM, SNX) | 2000 | 4G63 | 89~92 | FAN | 4PK985 | MD144817 |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E38A | 2000 | 4G63 | 88~92 | FAN | 4PK985 | MD144817 |
| | | | | | FAN | 4PK990 | MD130766 |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK930 | MZ701085 |
| | E39A | 2000 | 4G63 | 87~89 | FAN | 4PK985 | MD144817 |
| | | | | | FAN | 4PK990 | MD130766 |
| | | | | | AC | 4PK930 | MZ701085 |
| | | | | | AC | 4PK920 | MB439336 |
| | | 2000 | | 89~92 | FAN | 4PK990 | MD137594(ATM) |
| | | | | | FAN | 4PK985 | MD144817(MTM) |
| | | | | | AC | 4PK930 | MZ701085 |
| | | | | | AC | 4PK920 | MB439336 |
| | E54A | 2000 | 6A12 | 92~96 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E64A | 2000 | 6A12 | 92~96 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E74A | 2000 | 6A12 | 93~96 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E84A | 2000 | 6A12 | 92~96 | FAN | 4PK945 | MD184973 |
| | | | | | AC | 5PK1065 | MB946603 |
| | E57A(DSL) | 2000 | 4D68 | 93~96 | PS | 4PK635 | MD186111 |
| | E77A(DSL) | 2000 | 4D68 | 92~96 | PS | 4PK635 | MD186111 |
| | EA3A, EC3A | 2400 | 4G64 | 98~ | FAN+AC | 5PK940 | MD349465 |
| | | | | | PS | 5PK1330 | MD317245 |
| | EC5A | 2500 | 6A13 | 96~02 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 6PK1060 | MD317142 |
| GALANT Σ · ETERNA Σ | E12A | 1800 | G37B | 87~96 | FAN | 4PK935 | MD107671 |
| | E19A | 1800 | 4G93 | 96~99 | FAN | 4PK760 | MD180574 |
| | | | | | PS+AC | 5PK1120 | MB813251 |
| | E15A | 2000 | G63BT | 83~90 | FAN | 4PK975 | MD074251 |
| | E15A(ATM) | 2000 | G63B | 86~90 | FAN | 4PK990 | MD122602 |
| | E15A(MTM) | 2000 | G63B | 86~90 | FAN | 4PK980 | MD087546 |
| | E17A | 2000 | 6G71 | 87~90 | FAN | 5PK1240 | MD134958 |
| | | | | | PS | | WITH FAN |
| | E18A | 3000 | E18A | 89~90 | FAN | 5PK1240 | MD134958 |
| | | | | | PS | | WITH FAN |
| GTO | Z15A | 3000 | 6G72 | 90~ | FAN+AC | 6PK1150 | MB813600 |
| | | | | | FAN+AC | 6PK1150 | MB879764 |
| | Z16A | 3000 | 6G72 | 90~ | FAN+AC | 6PK1150 | MB813600 |
| | | | | | FAN+AC | 6PK1150 | MB879764 |
| | | | | | PS | 4PK925 | MD172376 |
| LANCER · MIRAGE | C11A | 1300 | G13B | 83~ | FAN | 4PK865 | MD069671 |
| | C11V | 1300 | G13B | 85~92 | FAN | 4PK865 | MD069671 |
| | C51A, C61A | 1300 | 4G13 | 87~91 | FAN | 4PK875 | MD118572 (ATM) |
| | | | | | FAN | 4PK870 | MD106658 (MTM) |
| | CA1A, CB1A | 1300 | 4G13 | 91~95 | FAN | 4PK870 | MD106658 |
| | | | | | FAN | 4PK880 | MD117356 |
| | | | | | PS | 4PK610 | MD193591 |
| | | | | | PS | 4PK595 | MD314778 |
| | CJ1A | 1300 | 4G13 | 96~00 | FAN | 5PK870 | MD325600 |
| | | | | | PS+AC | 5PK1060 | MD325599 |
| | CK1A | 1300 | 4G13 | 95~96 | FAN | 5PK870 | MD325600 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | 96~00 | FAN | 5PK865 | MD338513 |
| | | | | | PS | 5PK955 | MD344478 |
| | | | | 95~96 | FAN | 5PK870 | MD325600 |
| | | | | | PS+AC | 5PK1060 | MD325599 |
| | | | | 96~00 | FAN | 5PK865 | MD338513 |

# MITSUBISHI



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| LANCER · MIRAGE | CK1A | 1300 | 4G13 | 96~00 | PS+AC | 5PK1070 | MD339525 |
| | C52A, C62A, C72A, C82A | 1500 | 4G15 | 87~89 | FAN | 4PK870 | MD106658 |
| | | | | | FAN | 4PK880 | MD117356 |
| | | | | 89~91 | FAN | 4PK875 | MD118572 (ATM) |
| | | | | | FAN | 4PK870 | MD106658 (MTM) |
| | | | | | FAN | 4PK880 | MD117356 |
| | CA2A, CB2A, CD2A | 1500 | 4G15 | 91~92 | FAN | 4PK880 | MD117356 |
| | | | | | FAN+AC | 4PK870 | MD106658 |
| | | | | 92~95 | FAN | 4PK880 | MD117356 |
| | | | | | FAN+AC | 4PK870 | MD106658 |
| | | | | | PS | 4PK610 | MD193591 |
| | CA3A, CB3A, CC3A, CD3A | 1500 | 4G91 | 91~92 | FAN | 4PK760 | MD180574 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | AC | 5PK1115 | MB813272 |
| | | | | | AC | 5PK1110 | MB917985 |
| | | | | 92~95 | FAN | 4PK780 | MD163032 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | AC | 5PK1115 | MB813272 |
| | | | | | AC | 5PK1110 | MB917985 |
| | CJ2A, CK2A | 1500 | 4G15 | 95~00 | FAN | 5PK865 | MD338513 |
| | | | | | PS+AC | 5PK1070 | MD339525 |
| | CK2A, CL2A, CM2A | 1500 | 4G15 | 95~96 | FAN | 5PK870 | MD325600 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | 96~00 | FAN | 5PK865 | MD338513 |
| | | | | | PS | 5PK955 | MD344478 |
| | | | | 95~96 | FAN | 5PK870 | MD325600 |
| | | | | | PS+AC | 5PK1060 | MD32599 |
| | | | | 96~00 | FAN | 5PK865 | MD338513 |
| | | | | | PS+AC | 5PK1070 | MD339525 |
| | CS2A | 1500 | 4G15 | 00~01 | FAN | 5PK865 | MD366357 |
| | | | | | PS | 5PK1060 | MD325599 |
| | C63A, C73A, C83A | 1600 | 4G61 | 89~91 | FAN | 4PK985 | MD144817 (ATM) |
| | | | | | AC | 4PK910 | MB439714 |
| | | | | | FAN | 4PK980 | MD111147 (MTM) |
| | CA4A, CB4A, CC4A | 1600 | 4G92 | 91~92 | FAN | 4PK755 | MD176786 |
| | | | | | PS | 5PK950 | MD188026 (WITH AC) |
| | | | | | PS | 5PK945 | MD192809 (W/OUT AC) |
| | | | | | AC | 5PK1110 | MB917985 (WITH PS) |
| | | | | | AC | 5PK1120 | MB813251 (W/OUT PS) |
| | | | | 92~95 | FAN | 4PK755 | MD176786 |
| | | | | | FAN | 4PK760 | MD180574 |
| | | | | | PS | 5PK945 | MD192809 (W/OUT AC) |
| | | | | | AC | 5PK1115 | MB813272 |
| | CB6A | 1600 | 6A10 | 91~95 | FAN | 4PK945 | MD184973 |
| | | | | | PS | 5PK925 | MD180106 |
| | | | | | PS+AC | 5PK1065 | MB946603 |
| | CC4A | 1600 | 4G92 | 91~93 | FAN | 4PK755 | MD176786 |
| | | | | | PS | 5PK950 | MD172544 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | AC | 5PK1110 | MB917985 |
| | | | | 93~95 | FAN | 4PK760 | MD180574 (ATM) |
| | | | | | FAN | 4PK755 | MD176786 (MTM) |
| | | | | | PS | 5PK945 | MD192809 (W/OUT AC) |
| | | | | | PS | 5PK950 | MD188026 (WITH AC) |
| | | | | | AC | 5PK1115 | MB813272 |
| | | | | | AC | 5PK1120 | MB813251 (W/OUT PS) |
| | | | | | AC | 5PK1110 | MB917985 (WITH PS) |
| | CJ4A | 1600 | 4G92 | 95~00 | FAN | 4PK775 | MD312400 |
| | | | | | PS | 5PK1080 | MD319917 |
| | | | | | PS | 5PK1330 | MD317245 |
| | CK4A | 1600 | 4G92 | 95~00 | FAN | 4PK775 | MD312400 |
| | | | | | PS+AC | 5PK1330 | MD317245 |
| | C37W | 1800 | G37B | 86~90 | FAN | 4PK935 | MD069672 |
| | CB5AR | 1800 | 4G93 | 92~96 | FAN | 4PK780 | MD163032 |

# MITSUBISHI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| LANCER · MIRAGE | CB5AR | 1800 | 4G93 | 92~96 | AC | 5PK1120 | MB813251 |
| | CD5A | 1800 | 4G93 | 91~93 | FAN | 4PK755 | MD176786 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | AC | 5PK1110 | MB917985 |
| | | | | 93~95 | FAN | 4PK760 | MD180574 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | AC | 5PK1120 | MB813251 |
| | | | | | AC | 5PK1115 | MB813272 |
| | CK6A | 1800 | 6A11 | 95~99 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 6PK1070 | MD318667 |
| | C14W,V( DSL ) | 1800 | 4D65 | 87~92 | FAN | 4PK775 | MD312400 |
| | CK8A, CM8A( DSL ) | 2000 | 4D68 | 95~99 | PS | 4PK885 | MD325263 |
| | | | | | AC | 5PK980 | MD325262 |
| | CB8A, CB8AR, CD8A DSL ) | 2000 | 4D68 | 92~95 | PS | 4PK635 | MD186111 |
| | CD9A | 2000 | 4G63 | 92~93 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK650 | MD186110 |
| | | | | | AC | 4PK920 | MB439336 |
| | CE9A | 2000 | 4G63 | 93~96 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK640 | MD184363 |
| | | | | | AC | 4PK920 | MB439336 |
| | | | | | AC | 4PK950 | MB568899 |
| LANCER CEDIA | CS2A | 1500 | 4G15 | 00~01 | FAN+AC | 5PK865 | MD366357 |
| | | | | | PS | 5PK1065 | MD375935 |
| | | | | | PS | 5PK1060 | MD325599 |
| | | | | | AC | | WITH PS |
| | CS5A,W | 1800 | 4G93 | 00~01 | FAN | 4PK780 | MD373621 |
| | | | | 03~ | FAN | 6PK775 | MD373620 |
| LANCER EVOLUTION | CT9A | 2000 | 4G63 | 00~ | FAN | 6PK1790 | MD377352 |
| LANCER FIORE | C11V | 1300 | G13B | 85~92 | FAN | 4PK865 | MD069671 |
| | C12V, C12W | 1500 | G15B | 85~92 | FAN | 4PK865 | MD069671 |
| | C32V | 1500 | G15B | 86~92 | FAN | 4PK865 | MD069671 |
| | C37W | 1800 | G37B | 86~92 | FAN | 4PK935 | MD186122 |
| LEGNUM | EA1W, EC1W | 1800 | 4G93 | 96~02 | FAN | 4PK780 | MD334464 |
| | | | | | PS | 5PK1305 | MD331884 |
| | EA4W, EC4W | 2000 | 6A12 | 96~98 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 6PK1060 | MD317142 |
| | EA7W, EC7W | 2000 | 4G94 | 00~02 | FAN+AC | 4PK775 | MD312400 |
| | | | | | PS+AC | 5PK1305 | MD331884 |
| | | | | | AC | | WITH PS |
| | EA3W, EC3W | 2400 | 4G64 | 98~02 | FAN | 5PK940 | MD349465 |
| | | | | | PS | 5PK1330 | MD317245 |
| | EA5W, EC5W | 2500 | 6A13 | 96~98 | FAN | 4PK945 | MD184973 |
| | | | | | PS+AC | 6PK1060 | MD317142 |
| LIBERO | CB1V | 1300 | 4G13 | 92~02 | FAN | 4PK875 | MD118572 |
| | CB2W | 1500 | 4G15 | 94~00. | FAN | 4PK875 | MD118572 |
| | | | | | PS | 4PK595 | MD314778 |
| | CB2V, CD2V | 1500 | 4G15 | 92~02 | FAN | 4PK870 | MD106658 |
| | CB4W | 1600 | 4G92 | 96~00 | FAN | 4PK780 | MD163032 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | | PS+AC | 5PK1120 | MB813251 |
| | CB5W | 1800 | 4G93 | 92~96 | FAN | 4PK780 | MD163032 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | PS | 5PK945 | MD192809 |
| | | | | 96~00 | FAN | 4PK780 | MD163032 |
| | | | | | PS+AC | 5PK1120 | MD813251 |
| | CB5W, CD5W | 1800 | 4G93 | 92~00 | FAN | 4PK760 | MD180574 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | PS+AC | 5PK1120 | MD813251 |
| | CB8V, CB8W, CD8V, CD8W | 2000 | 4D68( DSL ) | 92~00 | PS | 4PK635 | MD186111 |
| MINICA | H32A, H32V, H37A, H37V | 660 | 3G83 | 93~98 | PS+AC | 4PK895 | MD303031 |
| | | | | | AC | 4PK895 | MD303031 |
| | | | | | PS | 4PK940 | MB568898 |
| | H31A, H36A | 660 | 4A30 | 93~98 | FAN | 3PK695 | MD303017 |
| | | | | | PS+AC | 4PK1150 | MD303018 |
| MINICAB | U14T, U14TG, U14TP, U14V, U14VG | 550 | 3G81 | 87~91 | FAN | 5PK1010 | MD115677 |

# MITSUBISHI



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| MINICAB | U15T, U15TG, U15V, U15VG | 550 | 3G81 | 87~91 | FAN | 5PK1010 | MD115677 |
| | U41T | 660 | 3G83 | 91~99 | PS | 3PK1030 | MD173537 |
| | U42T, U42TP | 660 | 3G83 | 91~99 | PS | 3PK1030 | MD173537 |
| | U42V | 660 | 3G83 | 91~99 | FAN | 3PK765 | MD173536 |
| | | | | | PS | 3PK1030 | MD173537 |
| | U43V, U44V | 660 | 4A30 | 93~99 | FAN | 4PK640 | MD184363 |
| | | | | | FAN | 3PK1080 | MD311454 |
| | | | | | PS | 3PK1080 | MD311454 |
| | | | | | AC | 4PK845 | MR116685 |
| | U61T, U61TP, U61V, U61W<br>U62T, U62TP, U62V, U62W | 660 | 3G83 | 99~ | FAN+AC | 3PK755 | MD361162 |
| | | | | | PS | 3PK1065 | MD361163 |
| | | | | | AC | 4PK790 | MR460647 |
| OUTLANDER | CW6W | 3000 | 4B1 | 07~ | PS | S4PK910 | 4451A083 |
| PAJERO | V21W | 2400 | 4G64 | 96~99 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK1055 | MD337658 |
| | | | | | AC | 4PK990 | MB657285 |
| | V24C, V24V, V24W, V24WG | 2500 | 4D56 (DSL) | 93~97 | PS | 4PK1120 | MD199826 |
| | V47WG | 2500 | 4D56 (DSL) | 95~98 | PS | 4PK1120 | MD199826 |
| | L141G, L141GW, L146GW | 3000 | 6G72 | 88~91 | FAN | 5PK1340 | MD142117 |
| | | | | | FAN | 5PK1340 | MD187462 |
| | V23C, V23W, V43W | 3000 | 6G72 | 90~99 | FAN | 5PK1340 | MD142117 |
| | | | | | FAN | 5PK1340 | MD187462 |
| | V63W, V73W | 3000 | 6G71 | 00~ | FAN+AC | 7PK2415 | MD366490 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | V25C, V25W, V45W | 3500 | 6G74 | 94~ | FAN | 5PK1130 | MD199223 |
| | | | | | PS | 4PK1065 | MD199224 |
| | V55W | 3500 | 6G74 | 97~99 | FAN | 5PK1130 | MD199223 |
| | | | | | PS | 4PK1110 | MD352140 |
| PAJERO iO | H61W | 1800 | 4G93 | 99~00 | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H66W | 1800 | 4G93 | 98~00 | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H71W | 1800 | 4G93 | 99~00 | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H76W | 1800 | 4G93 | 98~ | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H62W | 2000 | 4G94 | 00~ | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H67W | 2000 | 4G94 | 00~ | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H72W | 2000 | 4G94 | 00~ | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| | H77W | 2000 | 4G94 | 00~ | FAN+AC | 4PK780 | MD334464 |
| | | | | | PS | 5PK1340 | MD187462 |
| | | | | | AC | | WITH PS |
| PAJERO Jr. | H57A | 1100 | 4A31 | 95~96 | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK895 | MD303301 |
| | | | | | AC | 4PK940 | MB568898 |
| | | | | 96~98 | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK895 | MD303301 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | 95~98 | FAN | 3PK695 | MD303017 |
| | | | | | PS+AC | 4PK1130 | MD334647 |
| PAJERO MINI | H51A, H56A | 660 | 4A30 | 95~96 | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK895 | MD303301 |
| | | | | | AC | 4PK940 | MB568898 |
| | | | | 96~ | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK895 | MD303301 |

# MITSUBISHI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| PAJERO MINI | H51A, H56A | 660 | 4A30 | 96~ | AC | 4PK930 | MB439494 |
| | | | | 95~ | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK1130 | MD334647 |
| | H51A, H56A(TB) | 660 | 4A30 | 95 | FAN | 3PK695 | MD303017 |
| | | | | | PS | 4PK1150 | MD303018 |
| RVR | N11W, N21W | 1800 | 4G93 | 91~97 | FAN | 4PK760 | MD180574 |
| | | | | | FAN | 4PK780 | MD103032 |
| | | | | | PS | 5PK950 | MD188026 |
| | | | | | PS | 5PK950 | MD172544 |
| | | | | | AC | 5PK1145 | MB813867 |
| | N61W, N71W | 1800 | 4G93 | 97~ | FAN | 4PK775 | MD312400 |
| | | | | | PS+AC | 5PK1320 | MD349566 |
| | N13W, N23W, N23WG | 2000 | 4G63 | 91~96 | FAN | 4PK990 | MD186126 |
| | | | | | FAN | 4PK990 | MD137594 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | | AC | 4PK930 | MZ701085 |
| | | | | 96~97 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | | AC | 4PK930 | MZ701085 |
| | N23W, N23WG | 2000 | 4G63T | 91~96 | FAN | 4PK985 | MD186125 |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK930 | MB439494 |
| | | | | 96~97 | FAN | 4PK980 | MD186124 |
| | | | | | PS | 4PK645 | MD189129 |
| | | | | | AC | 4PK930 | MB439494 |
| | N28W, N28WG(DSL) | 2000 | 4D68 | 92~97 | PS | 4PK635 | MD186111 |
| | N74WG | 2400 | 4G64 | 97~ | FAN | 5PK980 | MD325262 |
| | N64WG | 2400 | 4G64 | 99~ | FAN+AC | 5PK940 | MD349465 |
| | | | | | AC | | WITH FAN |
| TOPPO · TOPPO BJ WIDE | H42V, H47V | 660 | 3G83 | 98~ | FAN+AC | 3PK755 | MD361162 |
| | | | | | PS | 3PK1065 | MD361163 |
| TOWNBOX | U61W, U62W | 660 | 3G83 | 98~ | FAN+AC | 3PK755 | MD361162 |
| | | | | | PS | 3PK1065 | MD361163 |
| | | | | | AC | 4PK790 | MR460467 |
| | U633W, U64W | 660 | 4A30 | 98~ | FAN+AC | 4PK855 | MD361164 |
| | | | | | PS | 3PK1085 | MD307736 |
| TOWNBOX WIDE | U65W, U66W | 1100 | 4A31 | 99~ | FAN+AC | 4PK720 | MD350607 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| 350Z | | 3500 | | 05~06 | AC | 4PK945 | 11920-AG900 |
| | ENTHUSIAST | 3500 | | 05~06 | AC | 4PK945 | 11920-AG900 |
| | TOURING | 3500 | | 05~06 | AC | 4PK945 | 11920-AG900 |
| | TRACK | 3500 | | 05~06 | AC | 4PK945 | 11920-AG900 |
| AD VAN · NISSAN AD | VB11 | 1300 | E13S | 88~90 | FAN | 4PK995 | 11720-50A00/10 |
| | B12, B13 | 1300 | GA13DS | 90~97 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | VY10, WY10 | 1300 | GA13DS | 90~97 | FAN | 4PK910 | 11720-77A00 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | GA13DE | 97~99 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | VY11 | 1300 | QG13DE | 99~ | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 3PK855 | 11950-42L00/67S00 |
| | | | | | AC | | WITH FAN |
| | VHB11 | 1500 | E15S | 88~90 | FAN | 4PK995 | 11720-50A00/10 |
| | VFY 10, VFG10 | 1500 | GA15DS | 90~97 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | | 90~97 | FAN | 4PK910 | 11720-77A00 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | GA15DE | 95~99 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | VFY11 | 1500 | QG15DE | 99~ | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 3PK855 | 11950-42L00/67S00 |
| | | | | | AC | | WITH FAN |
| | VHNY11 | 1800 | QG18DE | 99~ | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | WPY11 | 2000 | SR20VE | 99~01 | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| ALTIMA | | 2500 | | 05~06 | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS+WP | | WITH FAN |
| | S | 2500 | | 05~06 | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS+WP | | WITH FAN |
| | SL | 2500 | | 6 | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS+WP | | WITH FAN |
| ATLAS | UF22, KUF22, UGF22 | 1600 | NA16S | 90~92 | FAN | 4PK905 | 11720-85G00/10 |
| | SJ2F23 | 1600 | NA16S | 92~95 | FAN | 4PK905 | 11720-85G00/10 |
| | WF22, KWF22, WGF22, KWGF22 | 2000 | NA20S | 90~92 | FAN | 4PK905 | 11720-85G00/10 |
| | SK2F23, SK4F23 | 2000 | NA20S | 92~99 | FAN | 4PK905 | 11720-85G00/10 |
| | SH2F23, SH4F23 | 2000 | KA20DE | 99~ | FAN | 4PK910 | 11720-77A00 |
| AUSTER · STANZA · VIOLET | T12 | 1600 | CA16A | 86~ | FAN | 4PK810 | 11720-D4007 |
| | | | | | FAN | 4PK960 | 11720-D4001 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | WP | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | T12 | 1600 | CA16S | 88~90 | FAN | 4PK730 | 11720-16E02/71E10 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | PS | 4PK920 | 11950-D4201/11 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | PT12, FPT12 | 1800 | CA18ET/I | 88~90 | FAN | 4PK730 | 11720-16E02/71E10 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | PS | 4PK935 | 11950-D4200/10 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | RT12, FRT12 | 1800 | CA18DE/DET | 88~90 | FAN | 4PK730 | 11720-16E02/71E10 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | PS | 4PK935 | 11950-D4200/10 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| AUSTER · STANZA · VIOLET | RT12, FRT12 | 1800 | CA18DE/DET | 88~90 | AC | 6PK880 | 11920-D4201 |
| AVENIR | VEW10, VENW10 | 1600 | GA16DS | 90~93 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | FAN | 4PK910 | 11720-77A00 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | | 93~98 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | W10 | 1800 | SR18DI | 90~93 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | SR18DE | 93~98 | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | W11 | 1800 | QG18DE | 98~ | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-4M500/6J900 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | PW10, PNW10 | 2000 | SR20DE | 90~98 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | PW11, PNW11 | 2000 | SR20DE/DET | 98~02 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| BASSARA | JU30, JNU30 | 2400 | KA24DE | 99~01 | FAN | 6PK1335 | 11720-AD510 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK860 | 11720-67S00 |
| | JU30 | 2500 | QR25DE | 01~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | AC | | WITH FAN |
| | JHU30 | 3000 | VQ30DE | 99~ | FAN+AC | 6PK1095 | 11920-31U00 |
| | | | | | PS | 4PK775 | 11950-31U00 |
| | | | | | AC | | WITH FAN |
| BLUEBIRD | RU11 | 1600 | CA16S | 87~ | FAN | 4PK960 | 11720-D4001 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | WP | 4PK810 | 11720-D4017 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | | | | 85~ | FAN | 6PK730 | 11720-D4201 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | U12 | 1600 | CA16S | 89~91 | FAN | 4PK730 | 11720-16E02 |
| | | | | | PS | 4PK895 | 11950-71E10 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | U13 | 1600 | CA16SDS | 91~96 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | WU11 | 1800 | CA18S | 85~ | FAN | 4PK960 | 11720-D4001 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | WP | 4PK810 | 11720-D4017 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | PJ910 | 1800 | Z18P | 88~93 | FAN | 4PK920 | 11950-D4201 |
| | RN12, RNU12 | 1800 | CA18I | 87~91 | FAN | 4PK730 | 11720-16E02 |
| | | | | | PS | 4PK895 | 11950-71E10 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | EU12, ENU12 | 1800 | SR18DI | 89~91 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| BLUEBIRD | EU12, ENU12 | 1800 | SR18DI | 89~91 | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | EU13,ENU13 | 1800 | SR18DE | 91~96 | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | EU14, ENU14 | 1800 | SR18DE | 96~98 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK830 | 11920-77A00 |
| | | | | | AC | | WITH FAN |
| | EU14, ENU14(4WD) | | | 96~98 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-53J20 |
| | | | | | AC | | WITH FAN |
| | Q14 | 1800 | QG18DD/DE | 98~01 | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | U11 | 2000 | VG20ET | 86~ | FAN | 4PK730 | 11720-16E02 |
| | | | | | FAN | 4PK775 | 11720-26E02/12 |
| | | | | | PS | 4PK1035 | 11950-16E10 |
| | | | | | AC | 6PK1195 | 11920-16E01 |
| | HU12, HNU12 | 2000 | SR20DE/DET | 89~91 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | WU12, WHU12 | 2000 | SR20DE/DET | 91~96 | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | HU13, HNU13 | 2000 | SR20DE/DET | 91~96 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | HU14 | 2000 | SR20DE | 96~01 | FAN+AC | 6PK1030 | 11920-0E00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | HNU14 | 2000 | SR20VE | 97~01 | FAN+AC | 6PK1030 | 11920-0E00/10 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | PU13 | 2400 | KA24DE | 93~96 | FAN | 6PK1335 | 11720-1E400/20 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK855 | 11920-1E400/20 |
| BLUEBIRD SYLPHY | FG10 | 1500 | QG15DE | 00~ | FAN+AC | 6PK1110 | 11920-69J00/10 |
| | | | | | PS | 3PK855 | 11950-67S01 |
| | | | | | AC | | WITH FAN |
| | QG10, QNG10 | 1800 | QG18DE | 00~ | FAN+AC | 6PK1110 | 11920-69J00/10 |
| | | | | | PS | 3PK855 | 11950-67S01 |
| | | | | | AC | | WITH FAN |
| | TG10 | 2000 | QR20DD | 00~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| CARAVAN · HOMY | FANE24 | 2000 | NA20S | 90~93 | FAN | 5PK905 | 11720-03N00 |
| | CTGE24, VTE24, VTGE24 | 2000 | NA20S | 90~99 | FAN | 4PK905 | 11720-85G00/10 |
| | CQGE24 | 2400 | KA24DE | 99~ | FAN | 4PK915 | 11720-VJ200 |
| | AEGE24, KEE24 | 3000 | VG30E | 93~97 | FAN | 4PK1020 | 11720-V5300/27N10 |
| | | | | | PS | 3PK1055 | 11950-27N00/10 |
| | | | | | AC | 4PK1195 | 11920-27N00/10 |
| CEDRIC · GLORIA · CIMA | VNY30 | 2000 | CA20S | 85~95 | FAN | 4PK855 | 11720-V7311 |
| | | | | | PS | 3PK830 | 11950-V7300 |
| | | | | | AC | 4PK845 | 11920-V7311 |
| | Y31, CY31, KY31 | 2000 | VG20E | 87~91 | FAN | 4PK1030 | 11720-V5302 |
| | | | | | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | TY31, YY31 | 2000 | VG20E | 91~97 | FAN | 4PK1020 | 11720-V5300 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CEDRIC · GLORIA · CIMA | TY31, YY31 | 2000 | VG20E | 91~97 | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | EY31, KEY31 | 2000 | VG20DET | 87~91 | FAN | 4PK1110 | 11720-16V11 |
| | | | | | PS | 3PK900 | 11950-16V00/10 |
| | | | | | AC | 4PK915 | 11920-16V00/10 |
| | MJY31(LPG) | 2000 | RB20P | 87~95 | FAN | 4PK860 | 11720-67S00 |
| | | | | | PS | 3PK855 | 11950-42L10 |
| | | | | | AC | 4PK925 | 11920-58S00 |
| | | | | 95~ | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK855 | 11950-42L10 |
| | | | | | AC | 4PK925 | 11920-58S00 |
| | NJY31(LPG) | 2000 | CA20P | 89~91 | FAN | 4PK855 | 11720-V7301 |
| | | | | | PS | 3PK820 | 11950-V7302/12 |
| | | | | | AC | 4PK845 | 11920-V7301/11 |
| | QJY31(LPG) | 2000 | NA20P | 91~ | FAN | 4PK935 | 11950-D4200 |
| | | | | | PS | 4PK1110 | 11720-16V01 |
| | | | | | AC | 4PK885 | 11920-OH600/10 |
| | Y32 | 2000 | VG20E | 91~95 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | Y33 | 2000 | VG20E | 96~99 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | MY33 | 2500 | VQ25DE | 97~99 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01/AG900 |
| | ENY33 | 2500 | RB25DET | 97~99 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 4PK855 | 11950-5P500 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | EN34 | 2500 | RB25DET | 99~ | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 4PK855 | 11950-5P500 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | MY34 | 2500 | VQ25DD | 99~00 | FAN | 6PK1175 | 11720-4AP100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01/AG900 |
| | UY31, UYJ31(DSL) | 2800 | RD28 | 93~99 | PS | 4PK1045 | 11720-F6300 |
| | UY32(DSL) | 2800 | RD28 | 93~95 | PS | 4PK1045 | 11720-F6300 |
| | UY33(DSL) | 2800 | RD28 | 95~99 | PS | 4PK1045 | 11720-F6300 |
| | PY31, PAY31 | 3000 | V30E/ET | 87~02 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | FGY31 | 3000 | VG30DE | 88~93 | FAN | 4PK1050 | 11720-F6501 |
| | | | | | PS | 3PK925 | 11950-F6501 |
| | | | | | AC | 4PK965 | 11920-F6501 |
| | | | VG30DET | 88~93 | FAN | 4PK1135 | 11720-45V11 |
| | | | | | PS | 3PK900 | 11950-16V10 |
| | | | | | AC | 4PK915 | 11920-16V10 |
| | PY32 | 3000 | VG30E | 91~95 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6100/10 |
| | | | VH30DE | 91~95 | FAN | 4PK1015 | 11720-0P500 |
| | | | | | PS | 3PK925 | 11950-F6501 |
| | | | | | AC | 4PK955 | 11920-0P500 |
| | PY32, PAY32, PBY32 | 3000 | VG30DET | 91~94 | FAN | 5PK1170 | 11720-1P600 |
| | | | | | PS | 4PK905 | 11950-0P600/10 |
| | | | | | AC | 4PK945 | 11920-04U00 |
| | | | | 91~94 | FAN | 5PK1180 | 11720-1P665 |
| | | | | | PS | 4PK905 | 11950-0P600/10 |
| | | | | | AC | 4PK945 | 11920-04U00 |
| | | | | 94~95 | FAN | 5PK1170 | 11720-1P600 |
| | | | | | PS | 4PK905 | 11950-0P600/10 |
| | | | | | AC | 4PK945 | 11920-04U00 |
| | FPY32 | 3000 | VG30DET | 93~96 | FAN | 5PK1180 | 11720-1P665 |
| | | | | | PS | 4PK905 | 11950-0P600/10 |
| | | | | | AC | 4PK945 | 11920-04U00 |
| | PY33 | 3000 | VG30E | 95~99 | FAN | 4PK1020 | 11720-V5300 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CEDRIC · GLORIA · CIMA | PY33 | 3000 | VG30E | 95~99 | PS | 3PK1000 | 11950-F6101/11 |
| | | | | | AC | 4PK1420 | 11920-F6110 |
| | HY33, HBY33 | 3000 | VG30DE/DET | 95~99 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | FHY33 | 3000 | VG30DET | 96~01 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | HY34 | 3000 | VQ30DE/DET | 99~ | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | FGY32, FGDY32 | 4100 | VH41DE | 91~96 | FAN | 6PK840 | 11720-1P101 |
| | | | | | PS | 3PK930 | 11950-1P100/10 |
| | | | | | AC | 4PK1015 | 11920-1P100/10 |
| | FGY32, FGDY32(LIMITED L) | 4100 | VH41DE | 91~96 | FAN | 7PK760 | 11720-1P106 |
| | | | | | PS | 3PK930 | 11950-1P100/10 |
| | | | | | AC | 4PK1015 | 11920-1P100/10 |
| | FGY33, FGDY33 | 4100 | VH41DE | 90~01 | FAN | 6PK840 | 11720-1P101 |
| | | | | | PS+AC | 3PK935 | 11950-69000/5 |
| | | | | | WP | 6PK750 | 11720-6P000 |
| | | | | | AC | 4PK1015 | 11920-6P000 |
| CEFIRO | A31 | 2000 | RB20E | 88~92 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK855 | 11950-42L00/10 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31(HICAS CAR) | 2000 | RB20E | 88~90 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK855 | 11950-42L00/10 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31(HICAS CAR) | 2000 | RB20E | 90~92 | FAN | 4PK855 | 11720-V7301 |
| | | | | | PS | 3PK855 | 11950-42L00/10 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31 | 2000 | RB20DE | 92~94 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK855 | 11950-42L00/10 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31 | | RB20DE | 88~92 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31(HICAS CAR) | | RB20DE | 88~92 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK950 | 11950-59S02 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A31 | | RB20DE | 92~94 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | | | RB20DET | 88~92 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | | | | 90~94 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK895 | 11950-86L00 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | | | | 88~92 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK950 | 11950-59S02 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | | | | 92~94 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | A32 | 2000 | VQ20DE | 94~98 | FAN+AC | 6PK1095 | 11920-31U00 |
| | | | | | PS | 4PK775 | 11950-31U00 |
| | | | | | AC | | WITH FAN |
| | A33 | 2000 | VQ20DE | 98~03 | FAN+AC | 6PK1105 | 11920-2Y501 |
| | | | | | PS | 4PK765 | 11950-2Y501 |
| | | | | | AC | | WITH FAN |
| | EA31 | 2500 | RB25DE | 92~94 | FAN | 4PK860 | 11920-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L11 |
| | ECA31 | 2500 | RB25DE | 92~94 | FAN | 4PK860 | 11920-42L02 |
| | | | | | PS | 4PK950 | 11950-59S02 |
| | | | | | AC | 4PK925 | 11920-42L11 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CEFIRO | PA32 | 2500 | VQ25DE | 94~98 | FAN+AC | 6PK1095 | 11920-31U00 |
| | | | | | PS | 4PK775 | 11950-31U00 |
| | | | | | AC | | WITH FAN |
| | PA33 | 2500 | VQ25DE | 98~03 | FAN+AC | 6PK1105 | 11920-2Y501 |
| | | | | | PS | 4PK765 | 11950-2Y501 |
| | | | | | AC | | WITH FAN |
| | HA32 | 3000 | VQ30DE | 94~99 | FAN+AC | 6PK1095 | 11920-31U00 |
| | | | | | PS | 4PK775 | 11950-31U00 |
| | | | | | AC | | WITH FAN |
| | WHA32 | 3000 | VQ30DE | 98~03 | FAN+AC | 6PK1105 | 11920-2Y501 |
| | | | | | PS | 4PK765 | 11950-2Y501 |
| | | | | | AC | | WITH FAN |
| CIMA | HF50 | 3000 | VQ30DET | 01~ | FAN | 6PK1175 | 11720-4P102 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | GF50, GNF50 | 4500 | VK45DD | 01~ | FAN+AC | 6PK1955 | 11720-AR000 |
| | | | | | PS | 4PK945 | 11950-AR000 |
| | | | | | AC | | WITH FAN |
| CREW | QK30(LPG) | 2000 | NA20P | 93~ | AC | 4PK935 | 11950-D4200 |
| | | | | | PS | 4PK1110 | 11720-16V01 |
| | | | | | AC | 4PK885 | 19920-0H600/10 |
| | HK30, THK30, YHK30 | 2000 | RB20E | 94~ | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | SK30, TSK30(DSL) | 2800 | RD28/E | 93 | PS | 4PK1045 | 11720-F6300 |
| CUBE | Z10 | 1300 | CG13DE | 98~01 | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK765 | 11950-41B01/2 |
| | | | | | AC | | WITH FAN |
| DATSUN TRUCK | D21, GD21, VGD21 | 1600 | NA16S | 89~92 | FAN | 4PK905 | 11950-0P610 |
| | QD21, QGD21(2WD) | 2000 | NA20S | 89~97 | FAN | 4PK905 | 11950-0P610 |
| | QD22 | 2000 | NA20S | 97~99 | FAN | 4PK905 | 11950-0P610 |
| | PD22, LPD22 | 2000 | KA20DE | 99~ | FAN | 4PK915 | 11720-VJ200 |
| | LFD22 | 2400 | KA24DE | 99~ | FAN | 4PK915 | 11720-VJ200 |
| ELGRAND | ALE50, ALWE50 | 3300 | VG33E | 97~00 | FAN | 6PK1065 | 11720-0W000 |
| | | | | | AC | 5PK1280 | 11920-0W000 |
| | APE50, APWE50 | 3500 | VQ35DE | 00~02 | FAN | 6PK1175 | 11720-4P102 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | LE50 | | | | FAN | 6PK1060 | 11720-1A901 |
| FAIRLADY Z | Z31 | 2000 | RB20DET | 85~ | FAN | 4PK880 | 11720-59S01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-58S00 |
| | | 3000 | VG30DE | 86~ | FAN | 4PK1050 | 11720-F6501 |
| | | | | | PS | 3PK925 | 11950-F6501 |
| | | | | | AC | 4PK965 | 11920-F6501 |
| | | | VG30ET | 86~ | FAN | 4PK1030 | 11720-V5313 |
| | | | | | PS | 3PK1000 | 11950-F6111 |
| | | | | | AC | 4PK1420 | 11920-F6110 |
| | Z32, GZ32<br>CZ32CZ32, GCZ32, RZ32<br>KRZ32, KRGZ32 | 3000 | VG30DE | 89~00 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK925 | 11950-F6501 |
| | | | | | AC | 4PK965 | 11920-F6501 |
| | | | VG30DETT | 89~00 | FAN | 4PK1010 | 11720-67A00 |
| | | | | | PS | 4PK925 | 11920-42L01 |
| | | | | | AC | 4PK965 | 11920-F6501 |
| | Z33 | 3500 | VQ35DE | 02~ | FAN | 6PK1175 | 11720-41P02 |
| | | | | | AC | 4PK945 | 11920-AG900 |
| FIGARO | FK10 | 1000 | MA10T | 91~91 | FAN | 3PK770 | 11720-01B05 |
| | | | | | PS | 3PK625 | 11750-01B00 |
| | | | | | AC | 4PK815 | 11920-01B10 |
| INFINITI | FX35 | 3500 | | 05~08 | AC | 4PK945 | 11920-AG900 |
| | G35 | 3500 | | 05~07 | AC | 4PK945 | 11920-AG900 |
| | G35X | 3500 | | 06 | AC | 4PK945 | 11920-AG900 |
| | M35 | 3500 | | 06~08 | AC | 4PK945 | 11920-AG900 |
| | M35 SPORT | 3500 | | 06~07 | AC | 4PK945 | 11920-AG900 |
| | M35X | 3500 | | 06~08 | AC | 4PK945 | 11920-AG900 |
| INFINITI Q45 | G50 | 4500 | VH45DE | 89~93 | FAN | 6PK960 | 11720-60U01 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| INFINITI Q45 | G50 | 4500 | VH45DE | 89~93 | PS | 4PK1285 | 11950-60U04 |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | | | | 93~98 | FAN | 6PK960 | 11720-60U01 |
| | | | | | PS | 4PK1285 | 11950-60U04 |
| | | | | | AC | 4PK970 | 11920-66U01 |
| | HG50 | 4500 | VH45DE | 89~93 | FAN | 6PK960 | 11720-60U01 |
| | | | | | PS | 7PK1285 | 11950-60U05 |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | | | | 93~98 | FAN | 6PK960 | 11720-60U01 |
| | | | | | PS | 7PK1285 | 11950-60U05 |
| | | | | | AC | 4PK970 | 11920-66U01 |
| LANGLEY · LIBERTA VILLA | BFN13, BFNN13 | 1500 | GA15S/E | 88~90 | FAN | 4PK810 | 11720-D4007/17 |
| | | | | | FAN | 4PK910 | 11720-77A00 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | BEN13 | 1600 | CA16DE | 86~90 | FAN | 6PK730 | 11720-D4201 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | PS | 4PK935 | 11950-D4200 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| LARGO | WHC22 | 1800 | CA18T | 89~ | FAN | 4PK865 | 11720-V7300/V7310 |
| | | | | | PS | 3PK820 | 11950-V7302 |
| | | | | | AC | 3PK830 | 11950-V7310 |
| | | | | | AC | 3PK840 | 11950-V7311 |
| | WMC22 | 2000 | CA20S | 86~ | FAN | 4PK855 | 11720-V7301/V7311 |
| | | | | | PS | 3PK830 | 11950-V7300/V7310 |
| | | | | | PS | 3PK820 | 11950-V7302 |
| | | | | | AC | 4PK845 | 1192-V7301/V7311 |
| | W30, CW30, NW30, NCW30 | 2400 | KA24DE | 93~99 | FAN | 6PK790 | 11720-5C000 |
| | | | | | PS | 3PK1010 | 11950-5C000 |
| | | | | | PS | 4PK1010 | 11950-5C005 |
| | | | | | AC | 4PK920 | 11920-5C000 |
| LAUREL | KFC33 | 1800 | CA18DI | 89~93 | FAN | 4PK865 | 11720-V7300 |
| | | | | | PS | 3PK820 | 11950-V7302 |
| | | | | | AC | 4PK845 | 11920-V7301 |
| | SJC31, TSJ31(DSL) | 2000 | LD20 | 82~ | AC | 4PK1420 | 11920-F6100 |
| | FHC33, KHC33 | 2000 | RB20E | 88~93 | FAN | 4PK860 | 11720-42L02/12 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | KRC33, KRCC33 | 2000 | RB20E/DET | 88~93 | FAN | 4PK860 | 11720-42L02/12 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | KRC33, KRCC33(HICAS CAR) | 2000 | RB20DET | 88~93 | FAN | 4PK860 | 11720-42L02/12 |
| | | | | | PS | 4PK950 | 11950-58S02 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | HC34 | 2000 | RB20E | 93~97 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | RB20DE | 93~97 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | HC35 | 2000 | RB20DE | 97~99 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | | 99~02 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 4PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | KEC33 | 2500 | RB25DE | 91~93 | FAN | 4PK860 | 11720-42L02/12 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | KECC33 | 2500 | RB25DE | 91~93 | FAN | 4PK860 | 11720-42L02/12 |
| | | | | | PS | 4PK950 | 11950-58S02 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | GC34, GCC34 | 2500 | RB25DE/DET | 93~97 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | GC35, GCC35 | 2500 | RB25DE/DET | 97~98 | FAN | 4PK850 | 11720-42L01 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| LAUREL | GC35, GCC35 | 2500 | RB25DE/DET | 97~98 | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | | 98~02 | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 4PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | SC34(DSL) | 2800 | RD28 | 93~97 | PS | 4PK1045 | 11720-F6300 |
| | SC35(DSL) | 2800 | RD28 | 97~02 | PS | 4PK1045 | 11720-F6300 |
| LEOPARD | GF31 | 2000 | VG20E/ET | 88~92 | FAN | 4PK925 | 11720-F6110 |
| | | | | | PS | 3PK1000 | 11950-F6111 |
| | | | | | AC | 4PK1420 | 11920-F6100 |
| | EF31 | 2000 | VG20DET | 88~92 | FAN | 4PK1110 | 11720-16V01 |
| | | | | | PS | 3PK900 | 11950-16V00 |
| | | | | | AC | 4PK915 | 11920-16V00 |
| | JMY33 | 2500 | VQ25DE | 97~99 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | JENY33 | 2500 | RB25DET | 97~99 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 4PK855 | 11950-5P500 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | UF31 | 3000 | VG30DE | 88~92 | FAN | 4PK1050 | 11720-F6501 |
| | | | | | PS | 3PK900 | 11950-16V00 |
| | | | | | AC | 4PK965 | 11920-F6501 |
| | | | VG30DET | 88~92 | FAN | 4PK1135 | 11720-45V11 |
| | | | | | PS | 3PK900 | 11950-16V00 |
| | | | | | AC | 4PK915 | 11920-16V00 |
| | JPY33 | 3000 | VG30E | 96~97 | FAN | 4PK1020 | 11720-V5300 |
| | | | | | PS | 3PK1000 | 11950-F6101 |
| | | | | | AC | 4PK1420 | 11920-F6110 |
| | JHY33 | 3000 | VQ30DE | 96~97 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | | | VQ30DD | 97~99 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| | | | VG30DET | 96~99 | FAN | 6PK1175 | 11720-4P100/2 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01 |
| LEOPARD J.FERRY | JPY32 | 3000 | VG30DE | 92~96 | FAN | 4PK1015 | 11720-0P500 |
| | | | | | PS | 3PK925 | 11950-F6501 |
| | | | | | AC | 4PK955 | 11920-0P500 |
| | JGBY32 | 4100 | VH41DE | 92~95 | FAN | 6PK840 | 11720-1P101 |
| | | | | | PS | 3PK930 | 11950-1P105/15 |
| | | | | | AC | 4PK1015 | 11920-1P100/10 |
| | | | | 92~95 | FAN | 7PK760 | 11720-1P106 |
| | | | | | PS | 3PK930 | 11950-1P105/15 |
| | | | | | AC | 4PK1015 | 11920-1P100/10 |
| MARCH | K10 | 900 | MA09RT | 88~ | FAN | 3PK770 | 11720-01B05 |
| | | | | | AC | 4PK825 | 11920-21B00/5 |
| | K10 | 1000 | MA10S | 85~91 | FAN+AC | 3PK790 | 11720-01B04 |
| | | | | | PS | 3PK625 | 11750-01B00 |
| | | | | | AC | 4PK815 | 11920-01B10 |
| | | | MA10T | 85~91 | FAN | 3PK880 | 11720-01B00 |
| | | | | | FAN+AC | 3PK770 | 11720-01B05 |
| | | | | | PS | 3PK625 | 11750-01B00 |
| | | | | | AC | 4PK815 | 11920-01B10 |
| | K11 | 1000 | CG10DE | 92~93 | FAN | 6PK680 | 11720-41B00 |
| | | | | | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK765 | 11950-41B00 |
| | | | | | AC | | WITH FAN |
| | | | | 93~97 | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK765 | 11950-41B00 |
| | | | | | AC | | WITH FAN |
| | | | | 97~99 | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK725 | 11950-72B00 |
| | | | | | AC | | WITH FAN |
| | | | | 99~ | FAN+AC | 6PK955 | 11920-41B01/2 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| MARCH | K11 | 1000 | CG10DE | 99~ | PS | 4PK765 | 11950-41B00 |
| | | | | | AC | | WITH FAN |
| | K12 | 1200 | CR12DE | 02~ | FAN | 6PK920 | 11720-AX401 |
| | HK11 | 1300 | CG13DE | 92~97 | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK765 | 11950-41B00 |
| | | | | | AC | | WITH FAN |
| | | | | 97~99 | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK725 | 11950-72B00 |
| | | | | | AC | | WITH FAN |
| | | | | 99~ | FAN+AC | 6PK955 | 11920-41B01/2 |
| | | | | | PS | 4PK765 | 11950-41B00 |
| | | | | | AC | | WITH FAN |
| MAXIMA | J30, HJ30 | 3000 | VG30E | 88~91 | FAN | 4PK775 | 11720-26E02 |
| | | | | | PS | 4PK1035 | 11950-16E10 |
| | | | | | AC | 4PK1185 | 11920-85E01 |
| | PJ30, EJ30 | 3000 | VG30DE | 91~94 | FAN | 5PK855 | 11720-97E00/10 |
| | | | | | PS | 4PK985 | 11950-97E00/10 |
| | | | | | AC | 4PK1185 | 11920-85E01 |
| MURANO | S | 3500 | | 05~07 | PS | 4PK775 | 11950-31U02 |
| | SE | 3500 | | 05~07 | PS | 4PK775 | 11950-31U02 |
| | SL | 3500 | | 05~07 | PS | 4PK775 | 11950-31U02 |
| PAO | PK10 | 1000 | MA10S | 89~90 | FAN | 3PK790 | 11720-01B04 |
| | | | | | PS | 3PK625 | 11750-01B00 |
| | | | | | AC | 4PK815 | 11920-01B10 |
| PRAIRIE | M11, NM11 | 2000 | CA20S | 88~95 | FAN | 4PK730 | 11720-71E10 |
| | | | | | FAN | 6PK730 | 11720-D4201 |
| | | | | | PS | 4PK895 | 11950-71E10 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | PM11, PNM11 | 2000 | SR20DE | 95~98 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | PM12, PNM12 | 2000 | SR20DE/DET | 98~01 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | HM11, HNM11 | 2400 | KA24E | 90~92 | FAN | 6PK1300 | 11720-30R00 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK865 | 11720-V7300 |
| | | | | 92~98 | FAN | 6PK1300 | 11720-30R00 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK880 | 11720-59S01 |
| PRESAGE | U30, NU30 | 2400 | KA24DE | 98~01 | FAN | 6PK1335 | 11720-AD510 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK860 | 11720-67S00 |
| | V30 | 2500 | QR25DE | 01~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | AC | | WITH FAN |
| | U30 | 3000 | VQ30DE | 98~01 | FAN | 6PK1175 | 11720-4P100 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-60U01/AG900 |
| | HU30 | 3000 | VQ30DE | 98~03 | FAN+AC | 6PK1095 | 11920-31U00 |
| | | | | | PS | 4PK775 | 11950-31U00 |
| | | | | | AC | | WITH FAN |
| PRESEA | R10 | 1500 | GA15DS | 90~95 | FAN | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | R11 | 1500 | GA15DE | 95~ | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | PR10 | 1800 | SR18DI | 90~92 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | SR18DE | 92~95 | FAN | 4PK825 | 11720-0E010 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| PRESEA | PR10 | 1800 | SR18DE | 92~95 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | FAN | 4PK825 | 11920-21B00 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | PR11 | 1800 | SR18DE | 95~ | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1020 | 11920-0M800/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | HR10 | 2000 | SR20DE | 90~92 | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | | | | 92~95 | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | HR11 | 2000 | SR20DE | 95 | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN+AC | 6PK1020 | 11920-0M800/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| PRESIDENT | H252 | 4400 | Y44E | 82~90 | FAN | 5PK1070 | 11720-F2705 |
| | | | | | PS | 4PK1345 | 11950-F2705/15 |
| | JG50, JHG50 | 4500 | VH45DE | 90~03 | FAN | 6PK960 | 11720-60U01 |
| | | | | | PS | 4PK1285 | 11950-60U04 |
| | | | | | AC | 4PK970 | 11920-66U01 |
| | PG50, PHG50 | 4500 | VH45DE | 92~93 | FAN | 6PK960 | 11720-60U01 |
| | | | | | PS | 5PK1285 | 11950-91U00 |
| | | | | | AC | 4PK970 | 11920-66U01 |
| PRIMERA | P10 | 1800 | SR18DI | 90~92 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00/10 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | | | SR18DE | 92~95 | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | P11 | 1800 | SR18DE | 95~98 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | QP11 | 1800 | QG18DD/DE | 98~01 | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | HP10, HNP10 | 2000 | SR20DE | 90~92 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11920-77A00 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | | | | 92~95 | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V730 |
| | | | | | AC | | WITH FAN |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| PRIMERA | HP10, HNP10 | 2000 | SR20DE | 92~95 | FAN | 4PK825 | 11920-21B00 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | FHP10, FHP10E | 2000 | SR20DE | 91~97 | FAN+AC | 6PK1035 | 11920-70J00 |
| | | | | | PS | 4PK845 | 11950-70J00 |
| | | | | | AC | | WITH FAN |
| | HP11, HNP11 | 2000 | SR20DE | 95~01 | FAN+AC | 6PK1030 | 11920-0E000/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | HP11, FHP11 | 2000 | SR20VE | 97~01 | FAN+AC | 6PK1030 | 11920-0E000 |
| | | | | | PS | 4PK855 | 11950-5J010/20 |
| | | | | | AC | | WITH FAN |
| | WTP12, WTNP12 | 2000 | QR20DE | 01~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | WHP12 | 2000 | SR20VE | 01~ | FAN+AC | 6PK1030 | 11920-5U011 |
| | | | | | PS | 4PK855 | 11950-5J011 |
| | | | | | AC | | WITH FAN |
| | WRP12 | 2500 | QR25DD | 01~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| PULSAR | N13 | 1300 | E13S | 86~90 | FAN | 4PK995 | 11720-50A00 |
| | N14 | 1300 | GA13DS | 90~92 | FAN | 4PK910 | 11720-77A00 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | | | | 92~95 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | N15 | 1500 | GA13DE | 95~ | FAN | 4PK820 | 11720-0M000 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | FN14 | 1500 | GA15DS | 90~95 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | FN15 | 1500 | GA15DE | 95~00 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | EN13 | 1600 | CA16D | 86~ | FAN | 6PK730 | 11720-D4201 |
| | | | | | PS | 4PK935 | 11950-D4200 |
| | | | | | AV | 6PK880 | 11920-D4201 |
| | EN14 | 1600 | GA16DE | 90~95 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | EN15 | 1600 | GA16DE | 95~95 | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | JN15 | 1600 | SR16VE | 97~00 | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | | | | 97~ | FAN | 4PK825 | 11920-21B00 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | HN14 | 1800 | SR18DE | 90~95 | FAN | 4PK830 | 11920-77A00/10 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | HN15 | 1800 | SR18DE | 95~00 | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1020 | 11920-0M800/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | RNN14 | 2000 | SR20DET | 90~95 | FAN | 4PK830 | 11920-77A00/10 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK920 | 11950-54C00/10 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| PULSAR | RNN14 | 2000 | SR20DET | 90~95 | AC | | WITH FAN |
| RASHEEN | RFNB14 | 1500 | GA15DE | 94~97 | FAN | 4PK820 | 11720-0M000 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | RHNB14 | 1800 | SR18DE | 97~ | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | RKNB14 | 2000 | SR20DE | 98~ | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10 |
| R'NESSA | N30, NN30 | 2000 | SR20DE/DET | 97~ | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN+AC | 6PK1030 | 11920-0E000 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| | ONN30 | 2400 | KA24DE | 97~ | FAN | 6PK1335 | 11720-AD510 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK860 | 11720-67S00 |
| S-CARGO | G20 | 1500 | E15S | 89~90 | FAN | 4PK995 | 11720-50A00/10 |
| SERENA | PC24, PN24 | 2000 | SR20DE | 99~01 | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK830 | 11920-77A10 |
| | | | | | AC | | WITH FAN |
| | C24 | 2000 | Q20DE | 01~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | AC | | WITH FAN |
| SILVIA · 180SX | S13, KS13 | 1800 | CA18DE/DET | 88~91 | FAN | 4PK855 | 11720-V7301 |
| | | | | | PS | 3PK840 | 11950-V7301/11 |
| | | | | | AC | 4PK845 | 11950-53J20 |
| | S13, KS13(HICAS CAR) | | | 88~91 | FAN | 4PK855 | 11720-V7301 |
| | | | | | PS | 4PK840 | 11950-35F00/10 |
| | | | | | AC | 4PK845 | 11950-53J20 |
| | PS13, KPS13 | 2000 | SR20DE/DET | 91~98 | FAN | 5PK935 | 11720-52F00/10 |
| | | | | | FAN+AC | 6PK1300 | 11720-30R10 |
| | | | | | PS | 4PK880 | 11720-59S01 |
| | | | | | AC | 4PK880 | 11920-30R10 |
| | S14, CS14 | 2000 | SR20DE/DET | 93~99 | FAN | 5PK935 | 11720-52F00/10 |
| | | | | | FAN+AC | 6PK1300 | 11720-30R10 |
| | | | | | PS | 3PK875 | 11950-54F10 |
| | | | | | AC | 4PK880 | 11920-30R10 |
| | S15 | 2000 | SR20DE/DET | 99~02 | FAN | 5PK935 | 11720-52F00/10 |
| | | | | | PS | 3PK875 | 11950-54F10 |
| | | | | | AC | 4PK880 | 11920-30R10 |
| SKYLINE | FR32 | 1800 | CA18D/I | 89~93 | FAN | 4PK865 | 11720-V7310 |
| | | | | | PS | 3PK820 | 11950-V7312 |
| | | | | | AC | 4PK845 | 11920-V7301 |
| | HR32, YHR32 | 2000 | RB20E | 89~93 | FAN | 4PK860 | 11720-42L12 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | RCR32, KRCR32, RNR32 KRNR32, RR32, KRR32 | 2000 | RB20DE | 89~93 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | | | RB20DE (HICAS CAR) | 89~93 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK945 | 11950-04U00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | | | RB20DET | 89~93 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK945 | 11950-04U00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | HR33 | 2000 | RB20E | 93~98 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | HR34 | 2000 | RB20DE | 98~01 | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 3PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | ER32, ECR32 | 2500 | RB25DE | 91~93 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 3PK845 | 11950-58S01 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| SKYLINE | ER32, ECR32 | 2500 | RB25DE | 91~93 | AC | 4PK925 | 11920-42L01 |
| | ER32, ECR32(HICAS CAR) | | | 91~93 | FAN | 4PK860 | 11720-42L02 |
| | | | | | PS | 4PK945 | 11950-04U00 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | ER33, ECR33, ENR33 | 2500 | RB25DE/DET | 93~98 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | ER34, ENR34 | 2500 | RB25DE/DET | 98~01 | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 4PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | V35 | 2500 | VQ25DD | 01~ | FAN | 6PK1175 | 11720-4P102 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-AG900 |
| | BNR32 | 2600 | RB26DETT | 89~95 | FAN | 4PK880 | 11720-59S01 |
| | | | | | PS | 4PK950 | 11950-58S02 |
| | | | | | AC | 4PK925 | 11920-42L01 |
| | BCNR33 | 2600 | RB26DETT | 95~99 | FAN | 4PK875 | 11720-24U00 |
| | | | | | PS | 4PK970 | 11950-24U05 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | BCNR34 | 2600 | RB26DETT | 99~02 | FAN | 4PK875 | 11720-24U00 |
| | | | | | PS | 4PK970 | 11950-24U05 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | HV35 | 3000 | VQ30DD | 01.06- | FAN | 6PK1175 | 11720-4P102/100 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK945 | 11920-AG900 |
| STAGEA | WHC34 | 2000 | RB20E | 96~07 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK855 | 11950-42L00 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | RB20DE | 97~98 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | | 98~01 | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 4PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | WGC34, WGNC34 | 2500 | RB25DE/DET | 96~98 | FAN | 4PK850 | 11720-42L01 |
| | | | | | PS | 3PK845 | 11950-58S01 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | | | | 98~01 | FAN | 4PK890 | 11720-AA000 |
| | | | | | PS | 4PK865 | 11720-V7300 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| | WGNC34 | 2600 | RB26DETT | 97~01 | FAN | 4PK875 | 11720-24U00 |
| | | | | | PS | 4PK970 | 11950-24U05 |
| | | | | | AC | 4PK910 | 11720-77A00 |
| SUNNY | B12, RB12 | 1300 | | 85~ | FAN | 4PK995 | 11720-50A00/10 |
| | B13 | 1300 | GA13DS | 90~92 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | FAN | 4PK910 | 11720-77A00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | | 92~94 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | B14 | 1300 | GA13DE | 94~98 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | B15 | 1300 | QG13DE | 98~ | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 3PK855 | 11950-42L00/67S00 |
| | | | | | AC | | WITH FAN |
| | FB13 | 1500 | GA15DS | 90~92 | FAN | 4PK910 | 11720-77A00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | FNB13 | 1500 | GA15DS | 92~94 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |

# NISSAN

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| SUNNY | FNB13 | 1500 | GA15DS | 92~94 | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | FB14, FNB14 | 1500 | GA15DE | 94~98 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | FB15, FNB15 | 1500 | QG15DE | 98~04 | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-4M500/6J900 |
| | | | | | PS | 3PK855 | 11950-42L00/67S00 |
| | | | | | AC | | WITH FAN |
| | EB12, KEB12, REB12 | 1600 | CA16D(E) | 89~90 | FAN | 4PK705 | 11720-D4202 |
| | | | | | FAN | 6PK730 | 11720-D4201 |
| | | | | | PS | 4PK935 | 11950-D4200 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| | EB13 | 1600 | GA16DE | 90~92 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | FAN+AC | 4PK910 | 11720-77A00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | | 92~94 | FAN | 4PK805 | 11720-53Y00/10/20 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | EB14 | 1600 | GA16DE | 94~98 | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | JB14 | 1600 | SR16VE | 97~98 | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| | JB15 | 1600 | QG16DE | 98~04 | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 3PK855 | 11950-42L00/67S00 |
| | | | | | AC | | WITH FAN |
| | HB13, HNB13 | 1800 | SR18DE | 90~92 | FAN | 4PK830 | 11720-53J10 |
| | | | | | FAN | 4PK830 | 11720-77A00/10 |
| | | | | | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | 92~94 | FAN+AC | 6PK1035 | 11920-53J00/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | AC | | WITH FAN |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | HB14 | 1800 | SR18DE | 94~98 | FAN | 4PK825 | 11920-21B00 |
| | | | | | FAN | 4PK825 | 11720-0E010 |
| | | | | | FAN+AC | 6PK1020 | 11920-0M800/10 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK845 | 11950-53J10/20 |
| | | | | | AC | | WITH FAN |
| | QB15 | 1800 | QG18DD | 98~04 | FAN | 6PK820 | 11720-4M510 |
| | | | | | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| SUNNY CALIFORNIA | WFN12 | 1500 | GA15S/E | 87~ | FAN | 4PK910 | 11720-77A00 |
| | | | | | FAN | 4PK810 | 11720-D4007 |
| | | | | | PS | 4PK810 | 11720-D4007 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | WFY10, WFNY10 | 1500 | GA15DS | 90~95 | FB | 4PK805 | 11720-53Y00/10 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | | | GA25DE | 95~96 | FAN | 4PK820 | 11720-0M000/10 |
| | | | | | FAN+AC | 4PK1110 | 11720-0M313 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | | WITH FAN |
| | CY10 | 1800 | SR18DE | 96~ | FAN+AC | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK845 | 11950-53J10 |
| | | | | | AC | | WITH FAN |
| SONNY · LAUREL SPIRIT | B12, RB12 | 1300 | E13S | 85~90 | FAN | 4PK995 | 11720-50A00 |
| | FB12, FNB12, WFB12 | 1500 | GA15S | 87~90 | FAN | 4PK910 | 11720-77A00/10 |

# NISSAN



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| SONNY · LAUREL SPIRIT | FB12, FNB12, WFB12 | 1500 | GA15S | 87~90 | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | FB12, FNB12, KFB12, RFB12, WFB12, WFNB12 | 1500 | GA15E | 98~90 | FAN | 4PK810 | 11720-D4007/17 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | EB12, KEB12, REB12 | 1600 | CA16DE | 86~90 | FAN | 6PK730 | 11720-D4201 |
| | | | | | FAN+AC | 4PK705 | 11720-D4202 |
| | | | | | PS | 4PK935 | 11950-D4200 |
| | | | | | AC | 6PK880 | 11920-D4201 |
| TERRANO | TR50, JTR50(DSL) | 3000 | ZD30DI | 99~02 | FAN+AC | 7PK1680 | 11720-2W202 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | LR50, JLR50 | 3300 | VG33E | 95~02 | FAN | 6PK1065 | 11720-0W000 |
| | | | | | AC | 5PK1280 | 11920-0W000 |
| TINO | V10 | 1800 | QG18DE | 99~ | FAN+AC | 6PK1110 | 11920-6J900/10 |
| | | | | | PS | 4PK855 | 11720-V7301 |
| | | | | | AC | | WITH FAN |
| | HV10 | 2000 | SR20DE | 99~ | FAN+AC | 6PK1030 | 11920-5U011 |
| | | | | | PS | 4PK830 | 11920-77A10 |
| | | | | | AC | | WITH FAN |
| VANETTE | SE58TN, SS58TN, SS58VN | 1500 | D5 | 94~95 | PS | 4PK870 | 11950-HC000 |
| | | | | | AC | 4PK1085 | 11920-HC000 |
| | SK82LN, SK82MN SK82TN, SK82VN | 1800 | F8E | 99~ | FAN | 4PK930 | 11720-HA001 |
| | | | | | FAN | 4PK930 | 11720-HA001 |
| | | | | | PS | 4PK1105 | 11920-HA011 |
| | | | | | PS | 4PK975 | 11920-HA010 |
| | | | | | AC | | WITH PS |
| | KMGC22, KMGNC22 | 2000 | CA20S | 89~91 | FAN | 4PK855 | 11720-V7311 |
| | | | | | PS | 3PK820 | 11950-V7312 |
| | | | | | AC | 4PK845 | 11920-V7301/11 |
| VANETTE SERENA | KAJC23, VAJC23 | 1600 | GA16DE/DS | 91~ | FAN | 4PK810 | 11720-D4007/17 |
| | | | | | FAN | 4PK915 | 11920-16V00 |
| | | | | | PS | 4PK810 | 11720-D4007/17 |
| | | | | | AC | 4PK830 | 11920-77A00/10 |
| | KBC23, KBCC23 | 2000 | SR20DE | 91~99 | FAN | 5PK950 | 11720-0C800/5 |
| | | | | | PS | 4PK880 | 11720-59S01 |
| | | | | | AC | 4PK880 | 11720-59S01 |
| | KBNC23 | 2000 | SR20DE | 91~99 | FAN | 5PK950 | 11720-0C800/5 |
| | | | | | PS | 4PK905 | 11720-0C810/5 |
| | | | | | AC | 4PK880 | 11720-59S01 |
| | C23 | 2000 | SR20DE | 93~ | FAN | 5PK935 | 11720-52F00/10 |
| | | | | | PS | 5PK1170 | 11720-0P610 |
| | | | | | AC | 6PK1300 | 11720-30R10 |
| WINGROAD | WFY11 | 1500 | QG15DE | 99~ | FAN | 6PK1110 | 11920-6J900 |
| | | | | | PS | 3PK855 | 11950-67S00 |
| | | | | | AC | | WITH FAN |
| | WHY11, WHNY11 | 1800 | QG18DE | 99~ | FAN | 6PK1110 | 11920-6J900 |
| | | | | | PS | 3PK855 | 11950-67S00 |
| | | | | | AC | | WITH FAN |
| | WPY11 | 2000 | SR20VE | 99~01 | FAN | 6PK1020 | 11920-0M800 |
| | | | | | PS | 4PK845 | 11920-V7301 |
| | | | | | PS | 4PK855 | 11950-5J000/10 |
| | | | | | AC | | WITH FAN |
| X-TRAIL | T30, NT30 | 2000 | QR20DE | 00~ | FAN+AC | 6PK2245 | 11720-6N200 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | PNT30 | 2000 | SR20VET | 01~ | FAN+AC | 6PK1030 | 11920-5U011 |
| | | | | | PS | 4PK830 | 11920-77A12 |
| | | | | | AC | | WITH FAN |

# SUBARU

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ALCYONE | AX4, AX7 | 1800 | EA82 | 85~91 | FAN | 4PK955 | 8092-13040 |
| ALCYONE SVX | CXD, CXW | 3300 | EG33 | 91~96 | FAN+AC | 5PK880 | 8092-18150 |
| | | | | | AC | 4PK855 | 73013-PA000 |
| DOMINGO | KJ5, KJ6 | 1000 | EF10 | 83~94 | AC | 4PK900 | 73013-TA020 |
| | KJ8 | 1200 | EF12 | 86~94 | AC | 5PK970 | G3031-FA613(TWIN) |
| | FA7, FA8 | 1200 | EF12 | 94~98 | FAN | 4PK710 | 8092-14320 |
| | | | | | FAN+AC | 4PK970 | 8092-14340 |
| EXIGA | YA5 | 2000 | EJ20 | 08~ | FAN+AC | S4PK806 | 23979-AA000 |
| FORESTER | SF5 | 2000 | EJ20 | 97~02 | FAN | 5PK880 | 8092-18140/18250 |
| | | | | | AC | 4PK895 | 73323-AA010/AC010 |
| | SG5 | 2000 | EJ20 | 02~ | FAN | 5PK880 | 8092-18300/10 |
| | SF9 | 2500 | EJ25 | 98~02 | FAN | 5PK880 | 8092-18140/18250 |
| | | | | | AC | 4PK895 | 73323-AA010/AC010 |
| | SF5, SG5, SH5 | 2000 | EJ20 | 08~ | FAN+AC | S4PK806 | 23979-AA000 |
| | SF9, SG9 | 2500 | EJ25 | 08~ | FAN+AC | S4PK806 | 23979-AA000 |
| IMPREZA | GC1, GF1 | 1500 | EJ15E | 92~00 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK855 | 73013-PA000 |
| | GG3 | 1500 | EJ15E | 00~ | FAN | 5PK880 | 8092-18250 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK895 | 73323-AA010 |
| | GC4, GF3, GF4 | 1600 | EJ16E | 92~98 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK855 | 73013-PA000 |
| | GC6, GF6 | 1800 | EJ18E | 92~00 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK855 | 73013-PA000 |
| | GF5 | 1800 | EJ18E | 96~00 | FAN | 5PK880 | 8092-18160 |
| | GC8, GF8 | 2000 | EJ20E/T | 92~00 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK855 | 73013-PA000 |
| | GD9, GG9 | 2000 | EJ20E/T | 00~04 | FAN | 5PK880 | 8092-18250 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK895 | 73323-AA010 |
| | GDA, GGA | 2000 | EJ20T | 00~02 | FAN | 5PK880 | 8092-18250 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK895 | 73323-AA010 |
| | GE, GH, GR, GV | 1500 | EL15, EJ20/25 | | FAN+AC | S4PK806 | 23979-AA000 |
| | GE, GH, GR, GV | 2000 | EL15, EJ20/25 | | FAN+AC | S4PK806 | 23979-AA000 |
| | GE, GH, GR, GV | 2500 | EL15, EJ20/25 | | FAN+AC | S4PK806 | 23979-AA000 |
| JUSTY | KA7 | 1200 | EF12 | 88~91 | FAN | 4PK730 | 8092-14070 |
| | | | | | PS | 3PK660 | 7310-56030 |
| | KA8 | 1200 | EF12 | 88~94 | FAN | 4PK730 | 8092-14070 |
| | | | | | PS | 3PK660 | 7310-56030 |
| LANCASTER | BH9 | 2500 | EJ25 | 99~ | FAN | 5PK885 | 8092-18240 |
| | | | | | FAN | 5PK880 | 8092-18300 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BHE | 3000 | EZ30 | 00~03 | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| LEGACY | BC2, BC3 | 1800 | EJ18 | 92~93 | FAN | 5PK880 | 8092-18140/18250 |
| | | | | | FAN | 5PK685 | 8092-18010 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BD2, BD3, BG2, BG3 | 1800 | EJ18 | 93~99 | FAN | 5PK880 | 8092-18140/18250 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BF3 | 1800 | EJ18 | 89~93 | FAN | 5PK880 | 8092-18140/18250 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BD4, BD5, BG4, BG5 | 2000 | EJ20 | 93~99 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BC4, BC5 | 2000 | EJ20 | 88~93 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |

# SUBARU



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| LEGACY | BC4, BC5 | 2000 | EJ20 | 88~93 | FAN | 5PK685 | 8092-18010 |
| | BCA, BFA | 2000 | EJ20 | 90~93 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BF5 | 2000 | EJ20 | 89~93 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BH5 | 2000 | EJ20 | 98~03 | FAN | 5PK880 | 8092-18160 |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | | | EJ20T | 98~03 | FAN | 5PK885 | 8092-18240 |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BE5 | 2000 | EJ20 | 98~03 | FAN | 5PK880 | 8092-18250 |
| | | | EJ20T | 98~03 | FAN | 5PK885 | 8092-18240 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BG7 | 2200 | EJ22 | 93~96 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73323-FA000 |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BD9, BG9 | 2500 | EJ25 | 93~99 | FAN | 5PK880 | 8092-18160 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK885 | 73013-AA000 |
| | BL, BP | 2000 | EL15, EJ20/25 | | FAN+AC | S4PK806 | 23979-AA000 |
| | BL, BP | 2500 | EL15, EJ20/25 | | FAN+AC | S4PK806 | 23979-AA000 |
| | BP5 | 2000 | EJ20 | | FAN+AC | S4PK826 | 23979-AA020 |
| | BP9 | 2500 | EJ25 | | FAN+AC | S4PK826 | 23979-AA020 |
| LEONE · LEONE VAN | CVFY10, CVFNY10 | 1500 | GA15DE/DS | 94~99 | FAN | 4PK805 | 11720-53Y20 |
| | | | | | PS | 4PK810 | 11720-D4007 |
| | | | | | AC | 4PK830 | 11920-77A00 |
| | AA4, AA5 | 1800 | EA82 | 84~89 | FAN | 4PK975 | 8092-13010 |
| PLEO | RA1(SC) | 660 | EN07 | 98~ | FAN+AC | 4PK900 | 8092-14430 |
| | | | | | PS+SC | 4PK1195 | 8092-14160 |
| | RA1, RV1 | 660 | EN07 | 98~ | FAN+AC | 4PK900 | 8092-14430 |
| | | | | | PS | 4PK1090 | 8092-14380 |
| REX | KH3,4 | 660 | EN07 | 90~92 | SC | 4PK635 | 8092-14140 |
| | | | | | FAN | 4PK620 | 8092-14240(PS) |
| | | | | | FAN | 4PK775 | 8092-14120 |
| | | | | | FAN | 4PK575 | 8092-14230 |
| | | | | | PS | 4PK1195 | 8092-14160 |
| | | | | | PS | 4PK1015 | 8092-14150 |
| | KP3 | 660 | EN07 | 90~92 | FAN | 4PK860 | 8092-14220 |
| | KP4 | 660 | EN07 | 90~92 | FAN | 4PK860 | 8092-14220 |
| REX COMBI | KN1 | 550 | EK23 | 88~89 | FAN | 4PK745 | 8092-14040 |
| | | | | | SC | 4PK665 | 8092-14050 |
| SAMBAR | KS3,KS4,KV3,KV4 | 660 | EN07 | 90~99 | AC | 4PK895 | 73013-TA000 |
| | | | | 90~99 | FAN | 4PK670 | 8092-14130 |
| | | | | | SC | 4PK735 | 8092-14200 |
| | | | | | AC | 4PK940 | 73013-TA010 |
| | | | | | AC | 4PK900 | 73013-TA020 |
| SAMBAR DIAS | TT1, TT2 | 660 | EN07V | 99~02 | FAN | 4PK650 | 8092-14310 |
| | | | | | FAN+AC | 4PK825 | 73013-TA130 |
| | | | EN07Y | 99~02 | FAN | 4PK650 | 8092-14310 |
| | | | | | FAN+AC | 4PK915 | 73013-TA140 |
| | | | | | SC | 4PK725 | 8092-14400 |
| VIVIO | KK3, KK4, KW3, KW4 | 660 | EN07 | 92~98 | FAN | 4PK575 | 8092-14230 |
| | | | | | FAN+AC | 4PK1035 | 8092-14250 |
| | | | | | FAN+AC | 4PK880 | 8092-14300 |
| | | | | | PS | 4PK1165 | 8092-14260 |
| | | | | | AC | 3PK730 | 8092-11020 |
| | | | | | AC | 3PK730 | 8092-11020 |
| | KY3(MPI) | 660 | EN07 | 93~94 | FAN | 4PK1035 | 8092-14250 |
| | | | | | AC | 3PK730 | 8092-11020 |
| | KY3(SC, ATM) | | | 94~95 | FAN | 4PK880 | 8092-14300 |
| | | | | | PS | 4PK1165 | 8092-14260 |
| | | | | | | | |
| | | | | | | | |

# SUZUKI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| AERIO | RB21S | 1500 | M15A | 01~04 | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK1010 | 17521-85300 |
| ALTO | HA22S | 660 | K6A | 98~02 | FAN | 4PK810 | 49181-56B10 |
| | | | | | FAN | 4PK840 | 95141-60G50 |
| | | | | | WP | | WITH FAN |
| ALTO LAPIN | HF21S | 660 | K6A | 02~ | FAN | 4PK840 | 95141-60G50 |
| ALTO WORKS | HA21S, HB21S | 660 | K6A | 94~98 | FAN | 4PK840 | 95141-60G50 |
| | HA22S(ATM) | 660 | K6A | 98~02 | FAN | 4PK810 | 49181-56B10 |
| | | | | 99~00 | FAN | 4PK840 | 95141-60G50 |
| | HA22S(MTM) | 660 | K6A | 98~99 | FAN | 4PK810 | 49181-56B10 |
| | | | | 99~00 | FAN | 4PK840 | 95141-60G50 |
| CAPPUCCINO | EA21R | 660 | K6A | 95~98 | FAN | 4PK1040 | 17521-80F50 |
| | | | | | AC | 4PK620 | 95141-80F60 |
| CARRY | DA51B, DA51T, DB51T | 660 | F6A | 90~91 | FAN | 4PK670 | 95141-51F10 |
| | | | | | FAN | 4PK685 | 95141-51F11 |
| | | | | | FAN+AC | 4PK640 | 17521-50F00 |
| | | | | | AC | 4PK835 | 95141-50F00 |
| | | | | | AC | 4PK685 | 95141-51F11(2WD) |
| | DC51B, DC51T<br>DD51B, DD51T | 660 | F6A | 91~99 | FAN | 4PK670 | 95141-51F10 |
| | | | | | FAN | 4PK685 | 95141-51F11 |
| | | | | | FAN | 4PK690 | 95141-58D30 |
| | | | | | FAN+AC | 4PK640 | 17521-50F00 |
| | | | | | AC | 4PK835 | 95141-50F00 |
| | DE51V, DF51V | 660 | F6A | 91~98 | FAN | 4PK640 | 17521-50F00 |
| | | | | | AC | 4PK835 | 95141-50F00/01 |
| | DA52T, DB52T | 660 | F6A | 99~ | AC | 4PK720 | 95141-58H30 |
| | DA52T | 660 | F6A | 99~01 | FAN | 4PK880 | 17521-65H00 |
| | DA63T | 660 | K6A | 01~05 | FAN | 4PK870 | 17521-65H10 |
| | DA62V | 660 | K6A | 01~05 | FAN | 4PK870 | 17521-65H10 |
| CERVO | CN31S | 660 | F6B | 90~91 | FAN | 4PK950 | 17521-52E00 |
| | | | | | AC | 4PK1250 | 95141-52E00 |
| | CN32S | 660 | F6B | 91~97 | FAN | 4PK950 | 17521-52E00 |
| | | | | | AC | 4PK1250 | 95141-52E00 |
| | CP21S | 660 | F6A | 90~91 | AC | 4PK1250 | 95141-52E00 |
| | CP22S | 660 | F6A | 91~98 | AC | 4PK1250 | 95141-52E00 |
| | CP31S | 660 | F6B | 90~91 | FAN | 4PK950 | 17521-52E00 |
| | | | | | AC | 4PK1250 | 95141-52E00 |
| | CP32S | 660 | F6B | 91~98 | FAN | 4PK950 | 17521-52E00 |
| | | | | | AC | 4PK1250 | 95141-52E00 |
| CULTUS | AA44S, AB44S | 1000 | G10 | 88~ | FAN | 3PK815 | 17521-60B00/1 |
| | | | | | AC | 4PK760 | 95141-60B50 |
| | | | | 88~ | FAN | 3PK815 | 17521-60B00/1 |
| | | | | | PS | 4PK950 | 49180-60B10 |
| | | | | | AC | 4PK920 | 49180-63B10 |
| | AA44S | 1000 | G10 | 88~99 | FAN | 4PK815 | 17521-86500 |
| | | | | | ALT+PS | | WITH FAN |
| | | | | | AC | 4PK920 | 49180-63B10 |
| | AA34S(OHC) | 1300 | G13B | 88~00 | FAN | 3PK815 | 17521-60B00/10 |
| | | | | | PS | 4PK950 | 49180-60B10 |
| | | | | | AC | 4PK760 | 95141-60B50 |
| | AA34S(DOHC) | | | 88~00 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK920 | 49180-63B10 |
| | | | | | PS | 4PK825 | 49180-63B20 |
| | | | | | AC | 4PK950 | 17521-52E00 |
| | AB34S (EXCL. XL · ~130000)<br>(1310001~135609)<br>(135610 ~ )<br>(XL · ~ 130000)<br>(130001 ~ ) | 1300 | G13B | 88~00 | FAN | 3PK815 | 17521-60B00/10 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 3PK815 | 17521-60B00/10 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | PS+AC | 4PK950 | 49180-60B10 |
| | | | | | PS+AC | 4PK950 | 49180-60B10 |
| | | | | | PS | 4PK920 | 49180-63B10 |
| | | | | | PS | 4PK850 | 49180-60B20 |
| | | | | | PS | 4PK850 | 49180-60B20 |
| | | | | | AC | 4PK760 | 95141-60B50 |
| | | | | | AC | 4PK950 | 17521-52E00 |
| | AB53S(ATM) | 1300 | G13A | 86~88 | PS | 4PK940 | 49180-86000 |

# SUZUKI



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CULTUS | AB53S(MTM) | 1300 | G13A | 86~88 | PS | 4PK940 | 49180-86000 |
| | | | | | PS | 4PK950 | 49180-60B10 |
| | AF34S (SOHC · ~130000) (130001 ~ 130298) (130299 ~ ) (DOHC) | 1300 | G13B | 89~00 | FAN | 3PK815 | 17521-60B00/10 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | PS+AC | 4PK950 | 49180-60B10 |
| | | | | | PS+AC | 4PK950 | 49180-63B10 |
| | | | | | PS+AC | 4PK920 | 49180-63B10 |
| | | | | | PS | 4PK825 | 49180-63B20 |
| | | | | | AC | 4PK760 | 95141-60B50 |
| | AK34S | 1300 | G13B | 92~93 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK920 | 49180-63B10 |
| | | | | | AC | 4PK760 | 95141-60B50 |
| | AH64S, AJ64S | 1500 | G15A | 91~95 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK920 | 49180-63B10 |
| | | | | | | 4PK950 | 49180-60B10 |
| | AH14S(XE) (XG · ~ 132286) (132287 ~ ) | 1600 | G16A | 89~91 | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK850 | 49180-60B20 |
| | | | | | PS+AC | 4PK950 | 49180-60B10 |
| | | | | | PS+AC | 4PK920 | 49180-63B10 |
| | AJ14S( ~ 130119) ( 130120~) | 1600 | G16A | 89~91 | FAN | 4PK815 | 17521-86500 |
| | | | | | FAN | 4PK815 | 17521-86500 |
| | | | | | PS+AC | 4PK950 | 49180-60B10 |
| | | | | | PS+AC | 4PK920 | 49180-63B10 |
| CULTUS CRECENT | GA11S | 1300 | G13B | 94~01 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK900 | 49180-60G10 |
| | | | | | AC | 4PK995 | 95141-60G40(WITH PS) |
| | GA21S, GB21S, GC21S, GD21S | 1500 | G15A | 95~ | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK900 | 49180-60G10 |
| | | | | | AC | 4PK995 | 95141-60G40(WITH PS) |
| | GB31S | 1600 | G16A | 96~00 | FAN | 4PK815 | 17521-86500 |
| | | | | | AC | 4PK1005 | 95141-60G60 |
| CULTUS WAGON | GC21W | 1500 | G15A | 96~02 | FAN | 4PK815 | 17521-86500 |
| | | | | | AC | 4PK1005 | 95141-60G60 |
| | GD31W | 1600 | G16A | 96~02 | FAN | 4PK815 | 17521-86500 |
| | | | | | AC | 4PK1005 | 95141-60G60 |
| | GC41W | 1800 | J18A | 96~97 | FAN | 5PK1650 | 95141-60G90 |
| | | | | | AC | 4PK1005 | 95141-60G60 |
| ESCUDO | TA01R, TA01V | 1600 | G16A | 88~90 | FAN | 4PK800 | 17521-61A00/10 |
| | | | | | PS | 4PK810 | 17521-60A00 |
| | | | | | PS | 4PK790 | 49181-60A00 |
| | | | | | AC | 4PK925 | 95141-60A20 |
| | | | | | AC | 4PK840 | 95141-64A00 |
| | TA01W | 1600 | G16A | 88~97 | FAN | 4PK800 | 17521-61A00/10 |
| | | | | | PS | 4PK810 | 17521-60A00 |
| | | | | | PS | 4PK790 | 49181-60A00 |
| | | | | | AC | 4PK925 | 95141-60A20 |
| | | | | | AC | 4PK840 | 95141-64A00 |
| | TD01W | 1600 | G16A | 90~97 | FAN | 4PK800 | 17521-61A00 |
| | | | | | PS | 4PK810 | 17521-60A00 |
| | | | | | AC | 4PK950 | 49180-60B10 |
| | | | | | AC | 4PK950 | 95141-64A10 |
| | TA02W, TD02W | 1600 | G16A | 97~99 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK950 | 17521-52E00 |
| | | | | | AC | 4PK950 | 95141-64A10 |
| | TA11W, TD11W | 2000 | H20A | 94~96 | FAN | 4PK930 | 17521-85FA0 |
| | | | | | PS | 4PK1080 | 17521-85090 |
| | TA51W, TD51W | 2000 | J20A | 96~97 | PS | 5PK1650 | 95141-60G90 |
| | | | | | AC | | WITH PS |
| | TA52W, TD52W | 2000 | J20A | 97~00 | PS | 5PK1650 | 95141-60G90 |
| | | | | | AC | | WITH PS |
| | TL52W | 2000 | J20A | 98~ | PS | 5PK1650 | 95141-60G90 |
| | | | | | AC | | WITH PS |

# SUZUKI

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ESCUDO | TD61W | 2500 | H25A | 96~97 | FAN | 4PK930 | 17521-85FA0 |
| | | | | | PS | 4PK1080 | 17521-85090 |
| | TD62W | 2500 | H25A | 98~05 | FAN | 4PK930 | 17521-85FA0 |
| | | | | | PS | 4PK1080 | 17521-85090 |
| | TX92W | 2700 | H27A | 00~05 | FAN | 4PK930 | 17521-85FA0 |
| | | | | | AC | 4PK1090 | 95141-65D00 |
| EVERY | DE51V, DF51V | 660 | F6AT | 91~99 | FAN | 4PK640 | 17521-50F00 |
| | | | | | AC | 4PK835 | 95141-50F00 |
| | | | | | AC | 4PK685 | 95141-51F11 |
| | DA52V | 660 | G6A | 99~01 | AC | 4PK765 | 95141-86H00 |
| | DA62V | 660 | K6A | 01~05 | FAN | 4PK870 | 17521-65H10 |
| EVERY PLUS | DA32W | 1300 | G13B | 99~01 | FAN | 4PK800 | 17521-61A00 |
| GRAND VITARA | | 2500 | | 05 | AC | 4PK1090 | 95141-65D00 |
| JIMNY | JA11C, JA11V | 660 | F6A | 90~95 | PS | 4PK710 | 49180-70A10 |
| | | | | | PS | 4PK710 | 49180-82C00 |
| | | | | | AC | 4PK750 | 95141-55C00 |
| | | | | | AC | 4PK855 | 95141-55C10 |
| | JA12C, JA12V | 660 | F6A | 95~98 | AC | 4PK750 | 95141-55C00 |
| | JA12W | 660 | F6A | 95~98 | PS | 4PK710 | 49180-70A10 |
| | | | | | AC | 4PK855 | 95141-55C10 |
| | JA22W | 660 | K6A | 95~98 | FAN | 4PK1035 | 17521-80F51 |
| | JB23W | 660 | K6A | 98~04 | FAN | 4PK985 | 17521-81AA0 |
| JIMNY SIERRA · JIMMY WIDE | JB31W | 1300 | G13B | 93~95 | PS | 4PK710 | 49180-70A10 |
| | | | | | AC | 4PK900 | 95141-80C00 |
| | JB32W | 1300 | G13B | 95~97 | FAN | 4PK800 | 17521-61A00 |
| | | | | | AC | 4PK855 | 95141-55C10 |
| | JB33W | 1300 | G13B | 95~00 | FAN | 4PK815 | 17521-86500 |
| | | | | | PS | 4PK900 | 49180-60G10 |
| | | | | | AC | | WITH PS |
| | JB43W | 1300 | M13A | 00~ | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK950 | 17521-52E00 |
| KEI | HN21S | 660 | K6A | 98~01 | FAN | 4PK810 | 49181-56B10 |
| MR WAGON X | MF21S | 660 | K6A | 01~06 | FAN | 4PK840 | 95141-60G50 |
| | | | | | FAN | 4PK820 | 17521-73H00 |
| SOLIO | MA34S | 1300 | M13A | 04~ | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK815 | 17521-86500 |
| SWIFT | HT51S | 1300 | M13A | 00~04 | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK810 | 95141-56B10 |
| | ZC11S | 1300 | M13A | 04~ | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK815 | 17521-86500 |
| SX4 | YA11S | 1500 | M15A | 06~ | AC | 4PK815 | 17521-86500 |
| WAGON R | MC21S | 660 | K6A | 98~01 | FAN | 4PK810 | 49181-56B10 |
| | | | | | PS | | WITH FAN |
| | CT51S, CV51S | 660 | K6A | 98~99 | FAN | 4PK840 | 95141-60G50 |
| WAGON R WIDE | MA61S, MB61S | 1000 | K10A | 97~99 | FAN | 4PK855 | 95141-55C10 |
| · PLUS · SOLIO | MA63S | 1000 | K10A | 99~00 | FAN | 4PK810 | 17521-78F00 |
| | MA64S | 1000 | K10A | 00~02 | FAN | 4PK810 | 17521-78F00 |
| | MA34S | 1300 | M13A | 00~05 | FAN | 4PK835 | 95141-50F01 |
| | | | | | AC | 4PK810 | 49181-56B10 |
| X-90 | LB11S | 1600 | G16A | 95~98 | FAN | 4PK800 | 17521-61A00 |
| | | | | | AC | 4PK950 | 49180-60B10 |
| | | | | | AC | 4PK950 | 17521-52E00 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| ALLEX | NZE121, NZE124 | 1500 | 1NZ-FE | 00~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | ZZE123 | 1800 | 2ZZ-GE | 00~ | FAN | 6K1870 | 90916-02504 |
| | | | | | PS | | WITH FAN |
| ALLION | NZT240 | 1500 | 1NZ-FE | 01~ | PS | 3PK850 | 90916-02575 |
| ALPHARD | TA-MNH10W | 3000 | 1MZ-FE | 02~ | FAN | 6PK1040 | 99366-81040 |
| | | | | | PS | 4PK880 | 99364-20880 |
| ALTEZZA | SXE10 | 2000 | 3S-GE | 98~05 | FAN | 4PK780 | 99364-30780/90780 |
| | | | | | PS+AC | 4PK1220 | 99364-31220 |
| | GXE10 | 2000 | 1G-FE | 95~05 | FAN | 4PK1070 | 90916-02471 |
| | | | | | FAN | 4PK1070 | 99364-21070 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK900 | 99364-30900/90900 |
| | TA-JCE10W | 3000 | 2JZ-GE | 01~05 | FAN | 6PK1930 | 90916-02412 |
| ARISTO | JZS160 | 3000 | 2JZ-GE | 97~05 | FAN | 6PK1930 | 90916-02412 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS161 | 3000 | 2JZ-GTE | 97~05 | FAN | 6PK1930 | 90080-91168 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS147 | 3000 | 2JZ-GE | 91~97 | FAN | 6PK1940 | 90916-02310/02309 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | | | 2JZ-GTE | 91~97 | FAN | 6PK1955 | 90916-02305 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UZS143 | 4000 | 1UZ-FE | 92~97 | FAN | 7PK2275 | 90916-02380 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| AVALON | MCX10 | 3000 | 1MZ-FE | 95~00 | FAN+AC | 6PK1050 | 90080-91094 |
| | | | | | PS | 4PK880 | 90080-91088 |
| bB | NCP30 | 1300 | 2NZ-FE | 00~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | NCP31, 35 | 1500 | 1NZ-FE | 00~05 | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| BELTA | NCP96 | 1300 | 2NZ-FE | 05~ | FAN | 4PK1180 | 90916-02500/90916-02501 |
| | | | | | PS | 3PK850 | 90916-02575 |
| BREVIS | JCG10 | 2500 | 1JZ-FSE | 01~ | FAN | 6PK1940 | 90916-02310 |
| | JCG11 | 3000 | 2JZ-FSE | 01~ | FAN | 6PK1940 | 90916-02310 |
| CALDINA | ET196V | 1500 | 5E-FE | 92~02 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK930 | 99364-00930 |
| | | | | | AC | 4PK1080 | 99364-21080 |
| | ST190G | 1800 | 4S-FE | 92~96 | FAN+AC | 5PK1115 | 90916-02345 |
| | | | | | PS | 3PK760 | 99363-20760 |
| | AT191G | 1800 | 7A-FE | 96~97 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 99363-90630 |
| | | | | | AC | 4PK865 | 90916-02423/02433 |
| | AT211G | 1800 | 7A-FE | 97~02 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 99363-30630/90630 |
| | | | | | AC | 4PK865 | 90916-02423/02433 |
| | ST191G, ST195G | 2000 | 3S-FE | 92~97 | FAN+AC | 5PK1115 | 90916-02344 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | 3S-GE | 95~97 | FAN+AC | 5PK1100 | 90916-02382 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | ST210G, ST215G | 2000 | 3S-FE | 97~02 | FAN+AC | 5PK1110 | 99365-21110/91110 |
| | | | | | PS | 3PK760 | 99363-90760 |
| | ST215W | 2000 | 3S-FE | 97~02 | FAN+AC | 5PK1130 | 90916-02995 (ATM) |
| | | | | | FAN+AC | 5PK1120 | 90916-02422 (MTM) |
| | | | | | PS | 3PK760 | 99363-20760 |
| | | | | | PS | 3PK760 | 90080-91089 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CALDINA | CT190G, CT196V(DSL)CT198V | 2000 | 2C | 92~98 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1210 | 99365-21210 |
| | CT216G(DSL) | 2200 | 3C-TE | 97~02 | PS | 5PK1110 | 99365-21110 |
| | | | | | AC | 5PK1210 | 99365-91120 |
| | | | | | AC | 5PK1210 | 99365-21210 |
| | CT197V, CT199V(DSL) | 2200 | 3C-E | 98~02 | PS | 5PK1110 | 99365-81110 |
| | | | | | AC | 5PK1210 | 99365-21210 |
| CAMI | J100E | 1300 | HCEJ | 99~00 | FAN | 4PK780 | 90048-31017 |
| CAMRY · VISTA | SV30 | 1800 | 4SFE | 90~94 | FAN | 5PK995 | 90916-02995(MTM) |
| | | | | | FAN | 5PK1010 | 90916-02293(ATM) |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | SV40 | 1800 | 4S-FE | 94~98 | FAN | 5PK1090 | 99365-81090 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | SV41, 43 | 2000 | 3S-FE | 94~98 | FAN | 5PK1090 | 99365-81090 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | SV42 | 2000 | 3S-FE | 94~98 | FAN | 5PK1090 | 99365-81090 |
| | | | | | PS | 3PK740 | 99363-80740 |
| | VZV30, 31 | 2000 | 1VZ-FE | 90~92 | FAN+AC | 6PK1050 | 99366-01050 |
| | | | | | PS | 4PK805 | 90916-02298/9 |
| | CV40, 43(DSL) | 2200 | 3C-T | 94~98 | PS | 6PK1235 | 90916-02346 |
| | VZV32, 33 | 2500 | 4VZ-FE | 91~94 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK805 | 90916-02298/9 |
| | CV20(DSL) | 2000 | 2C-T | 86~89 | PS | 5PK1120 | 99365-51120 |
| | | | | | AC | 5PK1210 | 99365-51210 |
| | | | | 89~92 | PS | 5PK1120 | 99365-51120 |
| | | | | | AC | 5PK1210 | 99365-51210 |
| | CV30(DSL) | 2000 | 2C-T | 90~94 | PS | 6PK1140 | 99366-11140 |
| | | | | | AC | 6PK1235 | 90916-02346 |
| | | | | | PS | 6PK1235 | 90916-02346 |
| | SV32 | 2000 | 3S-FE | 90~94 | FAN | 5PK995 | 90916-02995(MTM) |
| | | | | | FAN | 5PK995 | 90916-02355 |
| | | | | | FAN | 5PK1010 | 90916-02293(ATM) |
| | | | | | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 5PK750 | 90916-02317 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | | | | | PS | 3PK750 | 99363-20750 |
| | | | 3S-GE | 90~92 | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK750 | 99363-20750 |
| | | | | | AC | 5PK1100 | 99365-21100 |
| | SV33 | 2000 | 3S-FE | 90~94 | FAN | 5PK995 | 90916-02995(MTM) |
| | | | | | FAN | 5PK995 | 90916-02355 |
| | | | | | FAN | 5PK1010 | 90916-02293(ATM) |
| | | | | | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 5PK750 | 90916-02317 |
| | | | | | PS | 3PK750 | 99363-20750 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | | | 3S-GE | 90~92 | FAN | 5PK1010 | 90916-02293 |
| | | | | | PS | 3PK735 | 90916-02314 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | SV35 | 2000 | 3S-FE | 90~94 | FAN | 5PK995 | 90916-02295(MTM) |
| | | | | | FAN | 5PK995 | 90916-02355 |
| | | | | | FAN | 5PK1010 | 90916-02293(ATM) |
| | | | | | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 3PK750 | 90916-02318 |
| | | | | | PS | 3PK750 | 99363-20750 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| CAMRY GRACIA | SXV20, W | 2200 | 5S-FE | 96~01 | FAN+AC | 5PK1100 | 99365-21100 |
| | | | | | PS | 3PK750 | 99363-30750 |
| | SXV25, W | 2200 | 5S-FE | 97~01 | FAN+AC | 5PK1100 | 99365-21100 |
| | | | | | PS | 3PK750 | 99363-30750 |
| | MCV21, W | 2500 | 2MZ-FE | 96~01 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| | MCV25W | 2500 | 2MZ-FE | 97~01 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK880 | 99364-30880 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CAMRY GRACIA | MCV25W | 2500 | 2MZ-FE | 97~01 | PS | 4PK880 | 90080-91088 |
| CARINA | ET176V | 1500 | 3E | 88~92 | FAN | 4PK815 | 90916-02135 (MTM) |
| | | | | | FAN | 4PK815 | 90916-02332 |
| | | | | | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | PS | 5PK920 | 99365-50920 |
| | | | | | PS+AC | 5PK1080 | 99365-01080 |
| | | | | | AC | 5PK880 | 99365-00880 |
| | | | | | AC | 5PK870 | 99365-50870 |
| | | | | | AC | 5PK890 | 99365-70890 |
| | AT170(ATM) | 1500 | 5A-F | 88~99 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | AT170(MTM) | 1500 | 5A-F | 88~99 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | AT192 | 1500 | 5A-F | 92~96 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 99363-20630 |
| | | | | | AC | 4PK860 | 99364-20860 |
| | | | | | AC | 4PK870 | 99364-20870 |
| | AT212 | 1500 | 5A-F | 96~01 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 99363-30630 |
| | | | | | AC | 4PK865 | 90916-02433 |
| | AT171, 175(ATM) | 1600 | 4A-FE | 88~99 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | AT171, 175(MTM) | 1600 | 4A-FE | 88~99 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | AT190 | 1600 | 4A-FE | 92~96 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-20870 |
| | AT171 | 1600 | 4A-GE | 88~92 | FAN | 5PK825 | 90916-02148 |
| | | | | | PS | 5PK920 | 99365-50630 |
| | | | | | AC | 5PK1070 | 99365-71070 |
| | AT210 | 1600 | 4A-GE | 96~01 | FAN | 5PK840 | 99365-80840 |
| | | | | | PS+AC | 5PK1075 | 90916-02430 |
| | ST150 | 1800 | 1SILU | 84~ | FAN | 5PK1000 | 99365-01000 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST170, G(ATM) | 1800 | 4S-FI/FE | 88~92 | FAN | 5PK1010 | 90916-0235718 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02270/1 |
| | ST170, G(MTM) | 1800 | 4S-FI/FE | 88~92 | FAN | 5PK995 | 90916-0235516 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1120 | 99365-51120 |
| | AT191 | 1800 | 7A-FE | 94~96 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-80630 |
| | | | | | AC | 4PK870 | 99364-20870 |
| | AT211 | 1800 | 7A-FE | 96~01 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 99363-30630 |
| | | | | | AC | 4PK865 | 90916-02433 |
| | ST190(ATM) | 1800 | 4S-FE | 92~96 | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | ST190(MTM) | 1800 | 4S-FE | 92~96 | FAN | 5PK995 | 90916-02355/6 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | ST195(ATM) | 2000 | 3S-FE | 92~96 | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | ST195(MTM) | 2000 | 3S-FE | 92~96 | FAN | 5PK995 | 90916-02355/6 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | CT170(DSL) (ATM) | 2000 | 2C | 88~89 | PS | 5PK1120 | 99365-51120 |
| | | | | | AC | 5PK1210 | 90916-02203 |
| | CT170(DSL) (MTM) | 2000 | 2C | 88~89 | PS | 5PK1110 | 90916-02256 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CARINA | CT170(DSL) (MTM) | 2000 | 2C | 88~89 | AC | 5PK1210 | 90916-02203 |
| | CT176V(DSL) | 2000 | 2C | 89~90 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1210 | 90916-02203 |
| | CT170G(DSL) | 2000 | 2C | 90~92 | PS | 5PK1110 | 90916-02256 |
| | | | | | PS+AC | 5PK1120 | 90916-02203 |
| | | | | | AC | 5PK1140 | 99365-61140 |
| | CT190, 195(DSL) | 2000 | 2C | 92~96 | PS+AC | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1210 | 99365-21210 |
| | | | | | AC | 5PK1140 | 99365-61140 |
| CARINA ED | ST163 | 1800 | 4S-FI | 88~89 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST180, ST181 | 1800 | 4S-FI | 89~90 | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1100 | 99365-51100(~90.08) |
| | | | 4S-FE | 90~93 | PS | 3PK760 | 99363-80760 |
| | | | | | AC | 5PK1110 | 99365-11110(90.08~) |
| | ST200, ST201 | 1800 | 4S-FE | 93~98 | FAN | 5PK1110 | 90080-91099 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | | | FAN | 5PK1110 | 99365-81110 |
| | ST162 | 2000 | 3S-FE | 87~88 | FAN | 5PK1000 | 99365-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | | | | 88~88 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ST162, ST163(ATM) | 2000 | 3S-FE/GELU | 88~89 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ST162, ST163(MTM) | 2000 | 3S-FE/GELU | 88~89 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ST182, ST183 | 2000 | 3S-FE/GE | 89~90 | FAN+AC | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 99365-51100 |
| | ST195 | 2000 | 3S-FE | 92~96 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | FAN | 5PK1010 | 90916-02357/8 |
| | ST202, ST203 | 2000 | 3S-FE | 93~98 | FAN | 5PK1110 | 90080-91099/99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | | | FAN | 5PK1120 | 99365-81120 |
| | ST205 | 2000 | 3S-FE | 94~98 | FAN+AC | 5PK1120 | 99365-21120 |
| | | | | | PS | 3PK760 | 99363-30760 |
| | ST215 | 2000 | 3S-FE | 96~01 | FAN+AC | 5PK1120 | 99365-21120 |
| | | | | | PS | 3PK760 | 99363-30760 |
| CAVALIER | TJG00 | 2400 | T2 (LD9) | 96~00 | FAN+AC | 5PK1205 | 2457751 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| CELICA | ST163 | 1800 | 4S-FI | 88~89 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ZZT231 | 1800 | 2ZZGE | 99~06 | FAN | 6PK1940 | 90916-02310 |
| | ST162 | 2000 | 3S-GELU | 85~88 | FAN | 5PK1000 | 99365-01000 |
| | | | | | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1100 | 90916-02116/02197 |
| | ST162, ST162C | 2000 | 3S-FE | 87~88 | FAN | 5PK1000 | 99365-01000 |
| | | | | | FAN | 5PK995 | 90916-02219/02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST152, ST162C(ATM) | 2000 | 3S-FE | 88~89 | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST152, ST162C(MTM) | 2000 | 3S-FE | 88~89 | FAN | 5PK995 | 90916-02219 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CELICA | ST182, ST183 | 2000 | 3S-FE/GE | 89~91 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ST183C | 2000 | 3S-GE | 89~93 | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK880 | 90916-02241 |
| | | | | | PS | 3PK760 | 90916-02205/99363-80760 |
| | | | | | AC | 5PK1100 | 90916-02116/02340 |
| | | | | | AC | 5PK1100 | 99365-21100 |
| | ST185H | 2000 | 3SGTE | 89~93 | FAN | 5PK1010 | 90916-02293/02357 |
| | | | | | PS | 3PK760 | 90916-02205/99363-80760 |
| | | | | | AC | 5PK1110 | 90916-02116/02340 |
| | ST185 | 2000 | 3S-GTE | 89~93 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1110 | 90916-02116 |
| | ST202, ST202C | 2000 | 3S-GE | 93~99 | FAN | 5PK1120 | 99365-81120 |
| | | | | | FAN | 5PK1110 | 90080-91099 |
| | | | | | FAN | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | ST203 | 2000 | 3S-FE | 93~99 | FAN | 5PK1110 | 90080-91099 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | | | FAN | 5PK1110 | 99365-81110 |
| | ST205 | 2000 | 3S-GTE | 94~99 | FAN | 5PK1120 | 90916-02396 |
| | | | | | PS | 3PK760 | 99363-80760 |
| CELSIOR | UCF10, UCF11 | 4000 | 1UZ-FE | 89~94 | FAN | 6PK2275 | 90916-02361/02253 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UCF20, UCF21 | 4000 | 1UZ-FE | 94~00 | FAN | 6PK2260 | 90916-02462 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UCF30, UCF31 | 4300 | 3UZ-FE | 00~ | FAN | 6PK2260 | 90916-02421/02462 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| COROLLA · SPRINTER | EE90 | 1300 | 2E | 87~89 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | PS+AC | 5PK1060 | 99365-01060 |
| | | | | | PS+AC | 5PK1055 | 90099-82018 |
| | | | | | AC | 5PK870 | 99365-20870/50870 |
| | | | | 89~91 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | PS+AC | 5PK1055 | 90099-82018 |
| | | | | | AC | 5PK870 | 99365-20870/50870 |
| | EE96V | 1300 | 2E | 87~91 | FAN | 4PK820 | 90916-02311 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | PS+AC | 5PK1055 | 90099-82018 |
| | | | | | PS+AC | 4PK840 | 99364-50840 |
| | | | | | AC | 5PK870 | 99365-20870/50870 |
| | EE97G | 1300 | 2E | 87~91 | FAN | 4PK815 | 90916-02135/02332 |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | PS+AC | 5PK1055 | 90099-82018 |
| | | | | | AC | 5PK870 | 99365-50870 |
| | EE106V | 1300 | 2E | 91~92 | FAN | 4PK820 | 90916-02431 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | AC | 5PK880 | 99365-20880 |
| | | | | | AC | 5PK1055 | 90916-02362 (W/PS) |
| | | | | | AC | 5PK1050 | 99365-21050 (W/PS) |
| | | | | | AC | 5PK1080 | 99365-21080 (W/PS) |
| | | | | | AC | 5PK870 | 99365-20870 |
| | EE102V | 1300 | 4E-FE | 92~02 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 5PK890 | 99365-80890 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | | | AC | 5PK880 | 99365-20880 |
| | EE101 | 1300 | 4E-FE | 91~95 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 5PK890 | 99365-50890 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| COROLLA · SPRINTER | EE101 | 1300 | 4E-FE | 91~95 | PS+AC | 5PK1055 | 90099-82018 |
| | | | | | AC | 5PK870 | 99365-50870 |
| | EE111 | 1300 | 4E-FE | 95~00 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 5PK890 | 99365-80890 |
| | | | | | AC | 5PK880 | 99365-20880 |
| | | | | | PS+AC | 5PK1050 | 99365-21050 |
| | NZE-FE | 1300 | 2NZ-FE | 00~ | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | EE107V, EE108G | 1500 | 3E | 91~92 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 5PK890 | 99365-50890 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | | | AC | 5PK1055 | 90916-02362 |
| | AE91(ATM) | 1500 | 5A-FE | 88~89 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | AE91(MTM) | 1500 | 5A-FE | 88~89 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | AE91 | 1500 | 5A-FE | 89~91 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | EE103V, EE104G | 1500 | 5E-FE | 94~02 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 5PK910 | 99365-80910 |
| | | | | | AC | 5PK1070 | 99365-21070 |
| | AE110 | 1500 | 5A-FE | 95~00 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-80630 |
| | | | | | AC | 4PK850 | 99364-20850 |
| | NZE121, NZE124 | 1500 | 1NZ-FE | 00~04 | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | AE92 | 1600 | 4A-GE | 88~91 | FAN | 5PK825 | 90916-02148 |
| | | | | | PS+AC | 5PK1050 | 90916-02201 |
| | | | | | AC | 5PK880 | 90916-02186 |
| | | | | | PS | 5PK920 | 99365-50920 |
| | AE95(ATM) | 1600 | 4A-FE | 88~90 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | AE95(MTM) | 1600 | 4A-FE | 88~90 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | AE101, AE101G | 1600 | 4A-FE | 91~00 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 9016-02364 |
| | | | 4A-GE | 91~00 | FAN | 5PK840 | 99365-70840 |
| | | | | | PS | 3PK630 | 99363-50630/80630 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | | | AC | 5PK1060 | 99365-21060/81060 |
| | AE104G | 1600 | 4A-FE | 91~00 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630/80630 |
| | | | | | AC | 4PK845 | 90916-02364 |
| | AE109V | 1600 | 4A-FE | 96~02 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 90080-91051 |
| | | | | | AC | 4PK850 | 99364-20850/80850 |
| | AE111, AE114 | 1600 | 4A-FE | 95~00 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-80630 |
| | | | | | AC | 4PK850 | 99364-20850 |
| | | | | | AC | 5PK1060 | 99365-21060 |
| | | | 4A-GE | 95~00 | FAN | 5PK840 | 99365-80840 |
| | | | | | PS | 3PK630 | 99363-80630 |
| | | | | | AC | 4PK850 | 99364-20850 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| COROLLA · SPRINTER | AE111, AE114 | 1600 | 4A-GE | 95~00 | PS+AC | 5PK1060 | 99365-21060 |
| | CE90(DSL) | 1800 | 1C | 89~89 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1140 | 90916-02246 |
| | | | | | PS+AC | 5PK1210 | 90916-02203 |
| | CE96V, CE97G(DSL) | 1800 | 1C | 89~89 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1140 | 90916-02246 |
| | | | | | PS+AC | 5PK1210 | 90916-02203 |
| | ZZE124 | 1800 | 1ZZFE | 00~06 | FAN | 6PK1810 | 90916-02511 |
| | ZZE122 | 1800 | 1ZZGE | 00~06 | FAN | 6PK1810 | 90916-02511 |
| | | | | | AC | | WITH FAN |
| | CE95(DSL) | 2000 | 2C | 89~91 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1140 | 90916-02246 |
| | | | | | PS+AC | 5PK1210 | 90916-02203 |
| | CE100, CE104(DSL) | 2000 | 2C | 91~95 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1120 | 99365-81120 |
| | | | | | PS+AC | 5PK1190 | 90365-21190 |
| | CE106V, CE108G(DSL)CE109V | 2000 | 2C | 91~98 | PS | 5PK1110 | 99365-21110 |
| | | | | | PS+AC | 5PK1190 | 90365-21190 |
| | | | | | AC | 5PK1190 | 99365-81190 |
| | | | | | AC | 5PK1120 | 99365-81120 |
| | CE110, CE114(DSL) | 2000 | 2C | 95~98 | PS | 5PK1110 | 99365-81110 |
| | | | | | AC | 5PK1120 | 99365-81120 |
| | | | | | PS+AC | 5PK1190 | 90365-21190 |
| | CE110G,CE102G(DSL) CE105V,CE107V | 2200 | 3C-E | 98~ | PS+AC | 5PK1190 | 90365-21190 |
| | CE113, CE116(DSL) | 2200 | 3C-E | 98~00 | PS | 5PK1120 | 99365-81120 |
| | | | | | PS+AC | 5PK1190 | 90365-21190 |
| COROLLA CERES | AE100 | 1500 | 5A-FE | 92~99 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-90630 |
| | | | | | AC | 4PK845 | 90916-02364 |
| COROLLA CERES · SPRINTER MARINO | AE101 | 1600 | 4A-FE | 92~98 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200/02364 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | | | AC | 4PK850 | 99364-20850 |
| | | | | | AC | 5PK850 | 99365-80850 |
| | | | | | AC | 5PK1060 | 99365-21060/81060 |
| | | | 4A-GE | 92~98 | FAN | 5PK945 | 90916-02232 |
| | | | | | FAN | 5PK840 | 99365-70840 |
| | | | | | PS | 5PK910 | 99365-80910 |
| | | | | | PS | 4PK625 | 90916-02179 |
| | | | | | PS | 4PK610 | 99364-20610 |
| | | | | | AC | 4PK845 | 90916-02364/02200 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | | | AC | 4PK850 | 99364-20850 |
| | | | | | AC | 5PK850 | 99365-80850 |
| | | | | | AC | 5PK1060 | 99265-21060 |
| COROLLA FIELDER | ZZE120G | 1300 | 2NZ-FE | 00~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | NZE121G, NZE124G | 1500 | 1NZ-FE | 00~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | ZZE122G, ZZE124G | 1800 | 1ZZ-FE | 00~ | FAN | 6PK1810 | 90916-02506 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | ZZE123G | 1800 | 2ZZ-GE | 00~ | FAN | 6PK1870 | 90916-02504 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| COROLLA LEVIN · SPRINTER TRUENO | AE91 | 1500 | 5A-F | 87~89 | FAN | 5PK980 | 99365-20980(ATM) |
| | | | | | FAN | 5PK970 | 99365-20970(MTM) |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | | | 5A-F/FE/FHE | 89~91 | FAN | 5PK970 | 99365-20970 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| COROLLA LEVIN · SPRINTER TRUENO | AE91 | 1500 | 5A-F/FE/FHE | 89~91 | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | AE100 | 1500 | 5A-FE | 91~95 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | AE92 | 1600 | 4A-GE | 88~92 | FAN | 5PK825 | 90916-02148 |
| | | | | | PS | 5PK920 | 99365-50920 |
| | | | | | AC | 5PK880 | 90916-02186/7 |
| | | | | | PS+AC | 5PK1050 | 90916-02201 |
| | | | 4A-GZE | 87~89 | FAN | 5PK880 | 90916-02186 |
| | | | | | PS | 5PK950 | 90916-02157 |
| | | | | | AC | 4PK625 | 90916-02179 |
| | | | | 89~91 | FAN | 5PK880 | 90916-02186 |
| | | | | | PS | 5PK945 | 90916-02232 |
| | | | | | AC | 4PK625 | 90916-02179 |
| | AE101 | 1600 | 4A-FE | 91~95 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02364 |
| | | | 4A-GE | 91~95 | FAN | 5PK980 | 90916-02173 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02364 |
| | | | | | AC | 5PK1050 | 99365-21050 |
| | | | 4A-GZE | 91~95 | FAN+AC | 5PK980 | 90916-02173 |
| | | | | | PS | 4PK625 | 90916-02179 |
| | | | | | SC | 5PK945 | 90916-02232 |
| COROLLA SPACIO | AE111N | 1600 | 4A-FE | 97~01 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 90080-91051 |
| | | | | | AC | 4PK850 | 99364-80850 |
| | AE115N | 1800 | 7A-FE | 97~01 | FAN | 5PK970 | 90080-91055 |
| | | | | | PS | 3PK630 | 90080-91051 |
| | | | | | AC | 4PK850 | 99364-20850/80850 |
| | ZZE122N | 1800 | 1ZZ-FE | 01~ | FAN | 6PK1810 | 90916-02551 |
| CORONA | ET176V | 1500 | 3E | 87~89 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 5PK920 | 99365-50920 |
| | | | | | AC | 5PK880 | 99365-00880 |
| | ET176V(ATM) | 1500 | 3E | 89~92 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 5PK1080 | 99365-51080 |
| | ET176V(MTM) | 1500 | 3E | 89~92 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS+AC | 5PK1080 | 99365-51080 |
| | AT170(ATM) | 1500 | 5A-FE | 89~92 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | AT170(MTM) | 1500 | 5A-FE | 88~89 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | AT175(ATM) | 1600 | 4A-FE | 88~92 | FAN | 5PK980 | 99365-20980 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK870 | 99365-00870 |
| | AT175(MTM) | 1600 | 4A-FE | 88~92 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | AT190 | 1600 | 4A-FE | 92~96 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK800 | 99364-20800 |
| | AT210 | 1600 | 4A-FE | 96~01 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | ST170(MTM) | 1800 | 4S-FE | 87~92 | FAN | 5PK995 | 90916-02295 |
| | | | | | FAN | 5PK1010 | 90916-02293 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1115 | 90916-02270/02271/02345 |
| | ST180, 181 | 1800 | 4SFE | 89~93 | FAN | 5PK1010 | 90916-02293 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1110 | 99365-11110 |
| | YT140(LPG) | 1800 | 2Y-PU | 82~90 | FAN | 4PK830 | 99364-50830 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CORONA | YT140(LPG) | 1800 | 2Y-PU | 90~98 | FAN | 4PK830 | 99364-50830 |
| | ST190, ST190Y(ATM) | 1800 | 4S-FE | 92~93 | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 3PK760 | 99363-70760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | ST190, ST190Y(MTM) | 1800 | 4S-FE | 92~93 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK760 | 99363-70760 |
| | | | | | AC | 5PK1115 | 90916-02344/5 |
| | ST200, ST201 | 1800 | 4S-FE | 92~98 | FAN | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | AT211 | 1800 | 7A-FE | 96~01 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-90630 |
| | | | | | AC | 4PK865 | 90916-02433 |
| | ST171(ATM) | 2000 | 3S-FE | 88~92 | FAN | 5PK1010 | 90916-02216/02357 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST171(ATM) | 2000 | 3S-GE | 88~92 | FAN | 5PK1010 | 90916-02216/02357 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST171(MTM) | 2000 | 3S-FE | 88~92 | FAN | 5PK995 | 90916-02216/02355 |
| | | | | | PS | 3PK760 | 99363-50760 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | ST182, ST183 | 2000 | 3S-FE | 89~93 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1110 | 99365-51110 |
| | | | 3S-GE | 89~93 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK760 | 90916-02205 |
| | | | | | AC | 5PK1100 | 90916-02116 |
| | ST191, ST195 | 2000 | 3S-FE | 92~96 | FAN | 5PK995 | 90916-02355 |
| | | | | | FAN | 5PK1010 | 90916-02357/8 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | | | AC | 5PK1115 | 90916-02345 |
| | ST202, ST203, ST205 | 2000 | 3S-FE | 95~98 | FAN | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | 3S-GE | 93~98 | FAN | 5PK1120 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | ST210, ST215 | 2000 | 3S-FE | 96~01 | FAN | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | CT190, CT195(DSL) | 2000 | 2C | 92~93 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1210 | 99365-21210 |
| | CT170, CT176V(DSL) | 2000 | 2C | 87~92 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1140 | 99365-61140 |
| | | | | | PS+AC | 5PK1210 | 99365-21210 |
| | CT190, CT190Y(DSL)CT195 | 2000 | 2C | 92~96 | PS | 5PK1110 | 90916-02256 |
| | | | | | AC | 5PK1140 | 99365-61140 |
| | | | | | PS+AC | 5PK1210 | 99365-21210 |
| | CT210, CT215(DSL) | 2000 | 2C | 96~97 | AC | 5PK1210 | 99365-21210 |
| | CT211, CT216(DSL) | 2200 | 3C-T/TE | 98~01 | AC | 5PK1210 | 99365-21210 |
| CROWN | GS130, GS131, GS136V | 2000 | 1G-E | 87~89 | FAN | 4PK1100 | 99364-81100 |
| | | | | | AC | 4PK840 | 99364-80840 |
| | | | 1G-FE | 88~ | FAN | 4PK1080 | 99364-91080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS131, GS131G, GS131H | 2000 | 1G-GZE | 87~91 | FAN | 4PK1260 | 90916-02146 |
| | | | | | PS | 3PK1285 | 90916-02181 |
| | | | | | AC | 4PK940 | 99364-20940 |
| | | | | | SC | 5PK940 | 90916-02147 |
| | GS131 | 2000 | 1G-GE | 88~91 | FAN | 4PK1160 | 99364-51160 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS130, GS130H | 2000 | 1G-GP | 89~91 | FAN | 4PK1140 | 90916-02343 |
| | | | | | PS | 3PK950 | 99363-00950 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS130, GS130G, GS130W<br>GS131, GS131H, GS136V | 2000 | 1G-FE | 91~ | FAN | 4PK1080 | 99364-91080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS130, GS130H | 2000 | 1G-GP | 91~95 | FAN | 4PK1140 | 90916-02343 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CROWN | GS130, GS130H | 2000 | 1G-GP | 91~95 | PS | 3PK950 | 99363-00950 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS141 | 2000 | 1G-FE | 93~05 | FAN | 4PK1080 | 99364-91080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS171 | 2000 | 1G-FE | 99~03 | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK880 | 99364-90880 |
| | GS151, GS151H | 2000 | 1G-FE | 95~99 | FAN | 4PK1080 | 99364-31080/91080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | GS151, GS151H(LPG) | 2000 | 1G-GPE | 95~99 | FAN | 4PK1140 | 90916-02343 |
| | | | | | PS | 3PK950 | 99363-00950(~98.01) |
| | | | | | PS | 3PK920 | 90916-02460(98.01~) |
| | | | | | AC | 4PK860 | 90916-02354 |
| | YS130(LPG) | 2000 | 3Y-PE | 90~96 | FAN | 4PK830 | 99364-80830 |
| | JZS130G, JZS131 | 2500 | 1JZ-GE | 90~99 | FAN | 6PK1940 | 90916-02310 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS141 | 2500 | 1JZ-GE | 91~95 | FAN | 6PK1940 | 90916-02310 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS151 | 2500 | 1JZ-GE | 95~01 | FAN | 6PK1930 | 90916-02412 |
| | | | | | FAN | 6PK1930 | 90080-91168 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS153 | 2500 | 1JZ-GE | 95~01 | FAN | 6PK1930 | 90916-02412 |
| | | | | | FAN | 6PK1930 | 90080-91168 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS171, JZS173 | 2500 | 1JZ-GE | 99~00 | FAN | 6PK1930 | 90916-02412 |
| | | | | | FAN | 6PK1930 | 90080-91168 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS171 | 2500 | 1JZ-GTE | 99~03 | FAN | 6PK1940 | 90916-02310 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | MS135, MS137 | 3000 | 7M-GE | 87~91 | FAN | 5PK1290 | 99365-21290 |
| | | | | | PS | 4PK850 | 99364-20850(~89.08) |
| | | | | | PS | 4PK845 | 90916-02364(89.08~) |
| | | | | | AC | 4PK930 | 99364-80930 |
| | JZS133, JZS135, JZS143, | 3000 | 2JZ-GE | 91~95 | FAN | 6PK1940 | 90916-02309/10 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS155 | 3000 | 2JZ-GE | 95~01 | FAN | 6PK1930 | 90916-02412 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS175, JZS177 | 3000 | 2JZ-FSE | 99~04 | FAN | 6PK1920 | 90916-02485 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZS179 | 3000 | 2JZ-GE | 99~03 | FAN | 6PK1930 | 90916-02412 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UZS131 | 4000 | 1UZ-FE | 89~91 | FAN | 6PK2245 | 90916-02463 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UZS141, UZS147 | 4000 | 1UZ-FE | 91~95 | FAN | 6PK2275 | 90916-02361 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UZS151, UZS157 | 4000 | 1UZ-FE | 96~99 | FAN | 6PK2245 | 90916-02360 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | UZS143, UZS145 | 4000 | 1UZ-FE | 92~97 | FAN | 7PK2275 | 90916-02380 |
| | UZS171, UZS173, UZS175 | 4000 | 1UZ-FE | 99~04 | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| CROWN COMFORT | GXS10(LPG) | 2000 | 1G-GPE | 95~01 | FAN | 4PK1140 | 90916-02343 |
| | | | | | PS | 3PK950 | 99363-00950(~98.01) |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| CROWN COMFORT | GXS10(LPG) | 2000 | 1G-GPE | 95~01 | PS | 3PK920 | 90916-02460(98.01~) |
| | | | | | AC | 4PK850 | 99364-20850 |
| | YXS10, YXS11(LPG) | 2000 | 3Y-PE | 95~04 | FAN | 5PK820 | 99365-80820 |
| | | | | | PS | 3PK1050 | 99363-21050 |
| | | | | | AC | 4PK820 | 99364-20820 |
| CURREN | ST208 | 1800 | 4S-FE | 95~98 | FAN+AC | 5PK1120 | 99365-81120 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | ST206, ST207, ST208 | 2000 | 3S-FE | 94~98 | FAN | 5PK1025 | 90916-02403 |
| | | | | | FAN+AC | 5PK1110 | 99365-21110 |
| | | | | | PS | 3PK760 | 99363-80760 |
| | | | 3S-GE | 94~98 | FAN+AC | 5PK1120 | 99365-81120 |
| | | | | | PS | 3PK760 | 99363-80760 |
| CYNOS | EL52, EL52C | 1300 | 4E-FE | 95~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK930 | 99364-80930 |
| | | | | | AC | 4PK1080 | 99364-91080(~96.08) |
| | | | | | AC | 4PK1090 | 99364-21090(96.08~) |
| | EL44 | 1500 | 5E-FE/FHE | 91~95 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK940 | 99364-00940 |
| | | | | | AC | 4PK1090 | 99364-21090/71090 |
| | EL54, EL54C | 1500 | 5E-FE/FHE | 95~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK1100 | 99364-81100 |
| | | | | | PS | 4PK1100 | 90080-91101 |
| DELIBOY | CXC10V(DSL) | 2000 | 2C | 91~94 | PS | 3PK800 | 99363-00800 |
| DUET | M100A, M110A | 1000 | EJ-DE | 98~04 | FAN | 4PK715 | 90048-31020 |
| DYNA · TOYOACE | YY51 | 1800 | 2Y | 87~93 | FAN | 5PK820 | 99365-50820 |
| | YH52, 61 | 2000 | 3Y | 84~89 | FAN | 5PK820 | 99365-50820 |
| | YU60, YU61D, YU70V | 2000 | 3Y/3Y-P | 88~93 | FAN | 4PK830 | 99364-80830 |
| | YU60 | 2000 | 3Y | 93~95 | FAN | 4PK830 | 99364-80830 |
| | YY201, YY211 | 2000 | 3Y/3Y-P | 95~01 | FAN | 5PK820 | 99365-80820 |
| | RZU100, RZU100A | 2700 | 3RZ-FE | 95~00 | FAN | 5PK890 | 99365-80890(~97.04) |
| | | | | | FAN | 5PK865 | 90916-02336(97.04~) |
| | | | | | PS | 4PK1100 | 99364-81100 |
| | | | | | AC | 4PK870 | 99364-20870 |
| ECHO | | 1500 | | 0 5 | PS | 3PK850 | 90916-02575 |
| EMINA · LUCIDA | CXR10G, CXR11G(DSL) | 2200 | 3C-T | 92~93 | FAN | 6PK730 | 99366-80730 |
| | | | | | PS | 4PK810 | 99364-80810 |
| | | | | | AC | 4PK770 | 99364-20770 |
| | CXR20G, CXR21G | | 3C-TE | 93~95 | FAN | 6PK730 | 99366-80730 |
| | | | | | PS | 4PK810 | 99364-80810 |
| | | | | | AC | 4PK790 | 99364-20790 |
| | | | | 95~99 | FAN | 6PK730 | 99366-80730 |
| | | | | | PS | 4PK810 | 99364-80810 |
| | | | | | AC | 4PK750 | 99364-80750 |
| | TCR10G,TCR11G,TCR20G,TCR21G | 2400 | 2TZ-FE | 92~98 | FAN | 6PK820 | 99366-80820 |
| | | | | | AC | 4PK720 | 99364-20720 |
| | | | | | AC | 4PK770 | 99364-70770 |
| ESTIMA | TCR11W, TCR21W | 2400 | 2TZ-FE | 92~98 | FAN | 6PK820 | 99366-70820 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | 4PK720 | 99364-70720 |
| | | | 2TZ-FZE | 94~99 | FAN | 6PK1140 | 90916-02392 |
| | | | | | SC | 7PK810 | 90916-02393 |
| | | | | | AC | 4PK890 | 99364-20890 |
| | ACR30W, ACR40W | 2400 | 2AZ-FE | 00~ | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | MCR30W, MCR40W | 3000 | 1MZ-FE | 00~05 | FAN | 6PK1040 | 99366-31040 |
| | | | | | PS | 4PK800 | 99364-20880 |
| | | | | | AC | | WITH FAN |
| FUN CARGO | NCP20 | 1300 | 2NZ-FE | 99~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | NCP21, NCP25 | 1500 | 1NZ-FE | 99~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| GAIA | SXM10G, SXM15G | 2000 | 3S-FE | 98~01 | FAN+AC | 5PK1080 | 99365-31080 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| GAIA | CXM10(DSL) | 2200 | 3C-TE | 97~01 | AC | | WITH FAN |
| | | | | | PS | 5PK1220 | 99365-81220 |
| GRANVIA | RCH11W | 2700 | 3RZ-FE | 95~98 | FAN | 5PK890 | 99365-80890(~97.04) |
| | | | | | FAN | 5PK865 | 90916-02336(97.04~) |
| | | | | | PS | 4PK1110 | 99364-21110 |
| | | | | | AC | 4PK920 | 99364-20920(~97.08) |
| | | | | | AC | 4PK940 | 99364-20940(97.08~) |
| HARRIER | SXU10W, SXU15W | 2200 | 5S-FE | 97~00 | FAN+AC | 5PK1090 | 99365-21090 |
| | | | | | FAN+AC | 5PK1090 | 90080-91098 |
| | | | | | PS | 3PK750 | 90080-91054 |
| | MCU10W, MCU15W | 3000 | 1MZ-FE | 97~03 | FAN+AC | 6PK1050 | 90080-91094 |
| | | | | | PS | 4PK880 | 99364-20880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| HIACE | YH80 | 1600 | 1Y-J | 85~90 | FAN | 5PK820 | 99365-50820 |
| | YH81 | 1800 | 2Y | 87~95 | FAN | 5PK820 | 99365-50820 |
| | LH107G, LH107W(DSL) | 2000 | 2L | 89~93 | PS | 4PK830 | 99364-50830 |
| | RZH100G, RZH110G<br>RZH102V, RZH112V | 2000 | 2RZ-1RZ-E | 89~93 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | | | | | AC | 4PK860 | 99364-00860 |
| | | | | | AC | 4PK885 | 90916-02287 |
| | YY101 | 2000 | 3Y | 95~96 | FAN | 5PK820 | 99365-80820 |
| | RZH101G | 2400 | 2RZ-E | 89~02 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | RZH111G | 2400 | 2RZ-E | 95~02 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | RZH133S, RZH133V | 2400 | 2RZ-E | 95~99 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | LH103V(DSL) | 2800 | 3L | 93~98 | PS | 4PK770 | 99364-20770 |
| | LH109V(DSL) | 2800 | 3L | 89~98 | PS | 4PK830 | 99364-50830 |
| | LH119V(DSL) | 2800 | 3L | 95~99 | PS | 4PK830 | 99364-50830 |
| | LH129V(DSL) | 2800 | 3L | 90~98 | PS | 4PK830 | 99364-50830 |
| | LH113K, LH113V(DSL)LH123V | 2800 | 3L | 93~98 | PS | 4PK770 | 99364-20770 |
| | LH117G(DSL) | 2800 | 3L | 90~93 | PS | 4PK830 | 99364-50830 |
| | LH129V(DSL) | 2800 | 3L | 90~98 | PS | 4PK830 | 99364-50830 |
| | LH162V, LH168V(DSL), LH172V, LH172K, LH178V, LH182K, LH188K | 3000 | 5L | 98~ | PS | 4PK770 | 99364-20770 |
| HIACE REGIUS | RCH42V | 2000 | 1RZ-FE | 97~02 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK860 | 90916-02354 |
| | RCH41W, RCH47W | 2700 | 3RZ-FE | 97~02 | FAN | 5PK865 | 90916-02336 |
| | | | | | PS | 4PK1110 | 99364-21110 |
| | | | | | AC | 4PK940 | 99364-20940 |
| | LXH43V, LXH49V(DSL) | 3000 | 5L | 97~02 | PS | 4PK770 | 99364-20770 |
| HIGHLANDER | | 3300 | | 05~07 | FAN+AC | 6PK1040 | 99366-31040 |
| HILUX | YN80, YN85 | 1800 | 2Y | 88~94 | FAN | 4PK830 | 99364-50830 |
| | YN100, YN105, YN107 | 2000 | 3Y | 88~94 | FAN | 4PK830 | 99364-50830 |
| | YN81, YN86, YN107 | 2000 | 3Y-E | 94~97 | FAN | 5PK820 | 99365-80820 |
| | YN130G | 2000 | 3Y-E | 89~91 | FAN | 5PK820 | 99365-50820 |
| | RZN147, RZN167 | 2000 | 1RZ-FE | 97~03 | FAN | 5PK865 | 90916-02336 |
| | | | | | AC | 4PK930 | 99364-90930 |
| | RZN180W, RZN185W | 2700 | 3RZ-FE | 95~02 | FAN | 5PK890 | 99365-80890 |
| | | | | | PS | 4PK1110 | 99364-21110 |
| | | | | | AC | 4PK900 | 99364-20900 |
| | VZN130G | 3000 | 3VZ-E | 90~95 | FAN | 4PK1185 | 90916-02384/02194 |
| | VZN180W, VZN185W | 3400 | 5VZ-FE | 95~02 | FAN | 4PK1050 | 90080-91090 |
| | | | | | PS | 4PK1070 | 99364-81070 |
| | | | | | AC | 4PK870 | 99364-20870 |
| IPSUM | CXM10G(DSL) | 2000 | 3C-TE | 97~01 | PS | 5PK1110 | 99365-91110 |
| | | | | | PS+AC | 5PK1220 | 99365-81220 |
| | SXM10G, SXM15G | 2000 | 3S-FE | 96~01 | FAN | 5PK995 | 90916-02356 |
| | | | | | FAN | 5PK1080 | 99365-31080 |
| | | | | | FAN+AC | 5PK1090 | 99365-31090 |
| | | | | | PS+AC | 3PK760 | 99363-30760 |
| | ACM21W, ACM26W | 2400 | 2AZ-FE | 0 1~ | FAN+AC | 7PK1930 | 90916-02513 |
| IST | UA-NCP60 | 1300 | 2NZ-FE | 0 2~ | FAN | 4PK1210 | 90916-02556 |
| | | | | | PS | 3PK850 | 99363-90850 |
| | UA-NCP61 | 1500 | 1NZ-FE | 02~04 | FAN | 4PK1210 | 90916-02556 |
| | | | | | PS | 3PK850 | 99363-90850 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| KLUGER | MCU20W | 3000 | 1MZ-FE | 03~ | PS | 4PK880 | 99364-30880 |
| | MCU25W | 3000 | 1MZ-FE | 03~ | PS | 4PK880 | 99364-30880 |
| LAND CRUISER | RZJ90W, RZJ95W | 2700 | 3RZ-FE | 97~02 | FAN | 5PK865 | 90916-02337 |
| | | | | | PS | 4PK1110 | 99364-21110 |
| | | | | | AC | 4PK910 | 99364-20910 |
| | VZJ90W, VZJ95W | 3400 | 5VZ-FE | 96~ | FAN | 4PK1050 | 90080-91090 |
| | | | | | PS | 4PK1070 | 99364-21070 |
| | | | | | AC | 4PK870 | 99364-20870 |
| | UZJ100W | 4700 | 2UZ-FE | 98~ | FAN | 6PK2245 | 90916-02231 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| MARK II · CHASER · CRESTA | SX80, SX80Y(ATM) | 1800 | 4S-FE/FI | 88~93 | FAN | 5PK1010 | 90916-02357 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | | | | | AC | 5PK1110 | 99365-21110/51110 |
| | | | | | AC | 5PK1110 | 99364-71110 |
| | SX80, SX80Y(MTM) | 1800 | 4S-FE/FI | 88~93 | FAN | 5PK995 | 90916-02355 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | | | | | AC | 5PK1110 | 99365-21110/51110 |
| | | | | | AC | 5PK1110 | 99364-71110 |
| | | 1800 | 4S-FE | 93~95 | FAN | 5PK995 | 90916-02355/6 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | | | | | AC | 5PK1110 | 99365-21110/51110 |
| | SX80, SX80Y(ATM) | 1800 | 4S-FI/FE | 88~95 | FAN | 5PK1010 | 90916-02216 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | | | | | AC | 5PK1110 | 99365-21110/51110 |
| | SX80, SX80Y (TRAINING CAR)(MTM) | 1800 | 4S-FI/FE | 88~95 | FAN | 5PK995 | 90916-02219 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | | | | | AC | 5PK1110 | 99365-21110/51110 |
| | YX76V | 1800 | 2YJ | 88~93 | FAN | 4PK830 | 99364-50830 |
| | SX90 | 1800 | 4S-FE | 92~96 | FAN | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | SX100 | 1800 | 4S-FE | 97~00 | FAN+AC | 5PK1110 | 99365-31110 |
| | | | | | PS | 3PK750 | 99363-00750 |
| | GX70, GX70G | 2000 | 1G-FE | 88~97 | FAN | 4PK1080 | 99364-01080/21080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 99364-00860/70860 |
| | | | | | AC | 4PK860 | 99364-20860 |
| | GX71 | 2000 | 1G-EU | 84~88 | FAN | 4PK1100 | 99364-01100 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | | | 1G-GEU | 84~88 | FAN | 4PK1160 | 99364-51160 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK860 | 99364-00860 |
| | | | 1G-GTEU | 86~88 | FAN | 4PK1170 | 99364-51170 |
| | | | | | PS | 3PK950 | 99363-00950 |
| | | | | | AC | 4PK860 | 99364-00860 |
| | GX81 | 2000 | 1G-FE | 88~95 | FAN | 4PK1080 | 99364-21080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK925 | 90916-02221 |
| | | | | | AC | 4PK925 | 90916-02348/9 |
| | | | 1G-GE | 88~93 | FAN | 4PK1160 | 99364-51160 |
| | | | | | PS | 3PK950 | 99363-00950 |
| | | | | | AC | 4PK925 | 90916-02221 |
| | | | | | AC | 4PK925 | 90916-02348/9 |
| | | | 1G-GTE | 88~90 | FAN | 4PK1200 | 99364-51200(ATM) |
| | | | | | FAN | 4PK1170 | 99364-51170(MTM) |
| | | | | | PS | 3PK950 | 99363-00950 |
| | | | | | AC | 4PK925 | 90916-02221 |
| | | | | | AC | 4PK925 | 90916-02348/9 |
| | GX81 | 2000 | 1G-GZE | 88~90 | FAN | 4PK1260 | 90916-02146 |
| | | | | | SC | 5PK940 | 90916-02147 |
| | | | | | AC | 4PK950 | 90916-02223 |
| | YX72Y | 2000 | 3YPU | 87~ | FAN | 4PK830 | 99364-50830 |
| | YX80Y | 2000 | 3YP | 88~95 | FAN | 5PK820 | 99365-50820 |
| | | | | | FAN | 4PK830 | 99364-80830 |
| | GX90 | 2000 | 1G-FE | 92~96 | FAN | 4PK1080 | 99364-21080 |
| | | | | | PS | 3PK890 | 99363-00890 |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| MARK II · CHASER · CRESTA | GX90 | 2000 | 1G-FE | 92~96 | AC | 4PK925 | 90916-02348 |
| | GX100 | 2000 | 1G-FE | 96~98 | FAN | 4PK1080 | 99364-31080/91080 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 99364-30860 |
| | GX110, GX115 | 2000 | 1G-FE | 00~04 | FAN | 4PK1070 | 90916-02471 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK860 | 99364-30860 |
| | JZX81 | 2500 | 1JZ-GE | 90~93 | FAN | 6PK1955 | 90916-02305 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | | | 1JZ-GTE | 90~93 | FAN | 6PK1970 | 90916-02308 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZX90 | 2500 | 1JZ-GTE | 92~96 | FAN | 6PK1970 | 90916-02308 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZX90, JZX93 | 2500 | 1JZ-GE | 92~96 | FAN | 6PK1955 | 90916-02305 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZX100, JZX105 | 2500 | 1JZ-GE | 96~00 | FAN | 6PK1940 | 90916-02310 |
| | | | | | FAN | 6PK1940 | 90080-91121 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | | | 1JZ-GTE | 96~00 | FAN | 6PK1940 | 90916-02310 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZX110, JZX115 | 2500 | 1JZ-FE<br>1JZ-GE/GTE | 00~04 | FAN | 6PK1940 | 90916-02310 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | MX83 | 3000 | 7M-GE | 89~93 | FAN | 5PK1290 | 99365-01290 |
| | | | | | PS | 4PK845 | 90916-02200/02364 |
| | JZX91 | 3000 | 2JZ-GE | 92~96 | FAN | 6PK1955 | 90916-02305 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | JZX101 | 3000 | 2JZ-GE | 96~00 | FAN | 6PK1940 | 90916-02310 |
| | | | | | FAN | 6PK1940 | 90080-91121 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| MARK II QUALIS | SXV20W, SXV25W | 2200 | 5S-FE | 97~02 | FAN+AC | 5PK1100 | 99365-31100 |
| | | | | | PS | 3PK750 | 99363-30750 |
| MCV21W, MCV25W | 2500 | 2MZ-FE | 97~02 | FAN+AC | 6PK1050 | 90916-02373/4 | |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| | MCV20W | 3000 | 1MZ-FE | 97~02 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| MASTERACE SURF | YR20G(DX) | 1800 | 2Y-U | 82~92 | FAN | 5PK820 | 99365-50820 |
| | YR28G | 1800 | 2Y-U | 85~92 | FAN | 5PK820 | 99365-50820 |
| | YR21G, 30G, 36G | 2000 | 3Y-EU | 85~ | FAN | 5PK820 | 99365-50820 |
| | CR21G | 2000 | 2C-T | 83~93 | PS | 3PK805 | 90916-02122 |
| | CR28G, 37G | 2000 | 2C-T | 85~92 | PS | 3PK805 | 90916-02122 |
| | CR30G(MTM) | 2000 | 2C-T | 90~93 | PS | 3PK805 | 90916-02122 |
| MR2 | SW20 | 2000 | 3S-GE | 89~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | FAN | 4PK830 | 99364-80830 |
| | | | | | AC | 4PK875 | 90916-02365/02269 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | | | 3S-GTE | 89~99 | FAN | 4PK830 | 99364-80830 |
| | | | | | AC | 4PK880 | 99364-80880 |
| MR-S | ZZW30 | 1800 | 1ZZ-FE | 99~ | FAN | 6PK1400 | 90916-02487 |
| | | | | | FAN+AC | 6PK1695 | 90916-02486 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| NADIA | SXN10, SXN10H<br>SXN15, SXN15H | 2000 | 3S-FE/FSE | 98~01 | FAN+AC | 5PK1080 | 99365-31080 |
| | | | | | PS | 3PK760 | 99363-30760 |
| PLATZ | NCP16 | 1300 | 2NZ-FE | 99~04 | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| PLATZ | NCP16 | 1300 | 2NZ-FE | 99~04 | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | NCP12 | 1500 | 1NZ-FE | 99~04 | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| PORTE | NNP10 | 1300 | 2NZ-FE | 04~ | PS | 3PK850 | 90916-02575 |
| | NNP11 | 1500 | 1NZ-FE | 04~ | PS | 3PK850 | 90916-02575 |
| PRIUS | NHW10A | 1500 | 1NZ-FXE | 97~00 | WP | 3PK1150 | 99363-31150 |
| | NHW11A | 1500 | 1NZ-FXE | 00~03 | WP | 3PK1120 | 99363-31120 |
| PROBOX, SUCCED | NLP51V | 1400 | 1ND-TV | 0 2~ | FAN | 5PK1190 | 99365-A1190 |
| | | 1500 | 1NZ-FE | | PS | 3PK850 | 99363-30850 |
| PROGRES | JCG10 | 2500 | 1JZ-GE | 98~01 | FAN | 6PK1930 | 90916-02412 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| PRONARD | MCX20L | 3000 | 1MZ-FE | 00~ | FAN+AC | 6PK1035 | 90080-91087 |
| | | | | | PS | 4PK875 | 90080-91093 |
| | | | | | AC | | WITH FAN |
| QUICK DELIVERY | BU280K | 2700 | 3RZFPE | 98~04 | FAN | 5PK865 | 90916-02336 |
| | | | | | PS | 4PK1100 | 99364-21100 |
| | | | | | AC | 5PK1060 | 99365-21060 |
| RACTIS | NCP100 | 1500 | 1NZ-FE | 05~ | PS | 3PK850 | 90916-02575 |
| | NCP105 | 1500 | 1NZ-FE | 05~ | PS | 3PK850 | 90916-02575 |
| RAUM | EXZ10, EXZ15 | 1500 | 5E-FE | 97~03 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK940 | 99364-20940 |
| | | | | | AC | 4PK1100 | 99364-21100(W/PS) |
| | | | | | AC | 4PK940 | 99364-20940(W/0 PS) |
| RAV4 | SXA10, SXA10G, SXA11, SXA11G | 2000 | 3S-FE | 94~00 | FAN | 5PK995 | 90916-02356 |
| | | | | | FAN+AC | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-20760 |
| | SXA15G, SXA16G | 2000 | 3S-FE | 97~00 | FAN | 5PK995 | 90916-02356 |
| | | | | | FAN+AC | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK760 | 99363-20760 |
| | ACA20W, ACA21W | 2000 | 1AZ-FSE | 00~ | FAN | 5PK995 | 90916-02356 |
| | | | | | FAN+AC | 5PK1090 | 99365-91090 |
| | | | | | PS | 3PK760 | 99363-20760 |
| REGIUS ACE | TRH112K | 2000 | 1TR-FE | 03~04 | FAN | 5PK930 | 99365-C0930 |
| RUNX | NZE121, NZE124 | 1500 | 1NZ-FE | 00~ | FAN | 4PK920 | 90916-02498/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | ZZE123 | 1800 | 2ZZ-GE | 00~ | FAN | 6PK1870 | 90916-02504 |
| | | | | | PS | | WITH FAN |
| SCEPTER | SXV10, SXV15, SXV15W | 2200 | 5S-FE | 93~96 | FAN+AC | 5PK1110 | 99365-81110 |
| | | | | | PS | 3PK750 | 99363-20750 |
| | VCV10, VCV15, VCV15W | 3000 | 3VZ-FE | 92~96 | FAN+AC | 6PK1050 | 90916-02373 |
| | | | | | PS | 4PK805 | 909160-02352 |
| SERA | EXY10 | 1500 | 5E-FHE | 90~95 | FAN | 4PK820 | 90916-02341 |
| | | | | | AC | 4PK1080 | 99364-01080 |
| SIENTA | NCP81G | 1500 | 1NZ-FE | 03~ | FAN | 4PK1210 | 90916-02556 |
| | | | | | PS | 3PK850 | 90916-02575 |
| | NCP85G | 1500 | 1NZ-FE | 03~ | FAN | 4PK1210 | 90916-02556 |
| | | | | | PS | 3PK850 | 90916-02575 |
| SOARER | GZ20 | 2000 | 1G-EU | 89~89 | FAN | 4PK1100 | 99364-01100 |
| | | | | | AC | 4PK840 | 99364-50840 |
| | | | 1G-GEU | 86~91 | FAN | 4PK1160 | 99364-51160 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | GZ20 | 2000 | 1G-GTEU | 88~91 | FAN | 4PK1170 | 99364-51170 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | | | 1G-FE | 89~91 | FAN | 4PK1080 | 99364-01080/21080 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | JZZ30 | 2500 | 1JZ-GTE | 91~00 | FAN | 6PK1940 | 90916-02309 |
| | | | | | PS | | WITH FAN |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| SOARER | MZ20, MZ21 | 3000 | 7M-GTEU | 86~91 | FAN | 5PK1290 | 99365-01290 |
| | | | | | PS | 4PK860 | 99364-00860 |
| | | | | | AC | 4PK920 | 99364-00920 |
| | UZZ30, UZZ31 | 4000 | 1UZ-FE | 91~97 | FAN | 6PK2275 | 90916-02361 |
| | | | | | PS | | WITH FAN |
| | UZZ32 | 4000 | 1UZ-FE | 91~96 | PS | 6PK1170 | 90916-02326 |
| | | | | | AC | | WITH FAN |
| SPRINTER CARIB | AE95G | 1600 | 4A-FHE | 90~95 | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | AE115G | 1800 | 7A-FE | 95~ | FAN | 5PK970 | 99365-20970 |
| | | | | | PS | 3PK630 | 99363-50630 |
| | | | | | AC | 4PK850 | 99364-20850 |
| STARLET | EP71, EP76V | 1300 | 2E-LU/LJ2E-ELU | 84~89 | FAN | 4PK815 | 90916-02135/02332 |
| | | | | | PS | 4PK910 | 99364-00910 |
| | | | | | PS+AC | 4PK1070 | 99364-51070 |
| | | | | | AC | 4PK840 | 99364-40840 |
| | EP71 | 1300 | 2E-TELU | 86~89 | FAN | 4PK820 | 90916-02341 |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 4PK910 | 99364-00910 |
| | | | | | PS+AC | 4PK1090 | 99364-01090 |
| | | | | | AC | 4PK870 | 99364-00870 |
| | EP82(ATM) | 1300 | 4E-F | 89~92 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1080 | 99364-01080 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | EP82(MTM) | 1300 | 4E-F | 89~92 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1070 | 99364-51070/01070 |
| | | | | | AC | 4PK840 | 99364-50840/00840 |
| | EP82(ATM) | 1300 | 4E-FE | 89~92 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1080 | 99364-01080 |
| | | | | | AC | 4PK845 | 90916-02200 |
| | EP82(MTM) | 1300 | 4E-FE | 89~92 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1080 | 99364-01080 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | EP82(ATM) | 1300 | 4E-FTE | 89~92 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1090 | 99364-01090 |
| | | | | | AC | 4PK885 | 90916-02287 |
| | EP82(MTM) | 1300 | 4E-FTE | 89~92 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1095 | 90916-02289 |
| | | | | | AC | 4PK900 | 99364-00900/50900 |
| | EP85(ATM) | 1300 | 4E-F/FE | 90~960 | FAN | 4PK820 | 90916-02341 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | AC | 4PK1080 | 99364-01080/21080 |
| | | | | | AC | 4PK1070 | 99364-51070 |
| | EP85(MTM) | 1300 | 4E-F/FE | 90~96 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | AC | 4PK1080 | 99364-21080/51080 |
| | | | | | AC | 4PK1070 | 99364-51070 |
| | EP91, EP95 | 1300 | 4E-FE/FTE | 96~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK920 | 99364-00920 |
| | | | | | PS+AC | 4PK1090 | 99364-21090 |
| | | | | | AC | 4PK880 | 99364-80880 |
| | NP70, NP76V(DSL) | 1500 | 1N | 86~89 | PS | 5PK870 | 99365-50870 |
| | | | | | PS+AC | 5PK995 | 99365-50995 |
| | | | | | PS+AC | 5PK995 | 90916-02295/02355 |
| | | | | | PS+AC | 5PK995 | 90916-02369 |
| | | | | | AC | 5PK895 | 99365-50895 |
| | | | | | AC | 5PK895 | 90916-02367 |
| | NP80(DSL) | 1500 | 1N | 89~96 | PS | 5PK870 | 99365-50870 |
| | | | | | PS+AC | 5PK910 | 99365-80910 |

# TOYOTA



| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| STARLET | NP80(DSL) | 1500 | 1N | 89~96 | PS+AC | 5PK995 | 90916-02355 |
| | | | | | PS+AC | 5PK1000 | 99365-01000 |
| | | | | | AC | 5PK900 | 99365-00900(MTM) |
| | | | | | AC | 5PK905 | 99365-00905(MTM) |
| | | | | | AC | 5PK895 | 99365-00895(ATM) |
| | NP90(DSL) | 1500 | 1N | 96~99 | PS | 5PK870 | 99365-50870 |
| | | | | | AC | 5PK980 | 99365-20980 |
| | | | | | PS+AC | 5PK830 | 99365-80830 |
| SUPRA | GA70, GA70H | 2000 | 1G-FE | 88~91 | FAN | 4PK1080 | 99364-01080 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | | | 1G-GEU | 86~93 | FAN | 4PK1160 | 99364-51160 |
| | | | | | PS | 3PK960 | 99363-00960 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | | | 1G-GTEU | 86~93 | FAN | 4PK1170 | 99364-51170 |
| | | | | | PS | 3PK970 | 99363-00970 |
| | | | | | AC | 4PK850 | 99364-00850 |
| | JZA70 | 2500 | 1JZ-GTE | 90~93 | FAN | 6PK1955 | 90916-02305 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| | MA70 | 3000 | 7MG-GTEU | 86~90 | FAN | 5PK1290 | 99365-01290 |
| | | | | | PS | 4PK860 | 99364-00860 |
| | | | | | AC | 4PK920 | 99364-00920 |
| | JZA80 | 3000 | 2JZ-GE/GTE | 93~02 | FAN | 6PK1940 | 90916-02309 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| TERCEL · CORSA · COROLLA II | EL30 | 1300 | 2E | 88~90 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 5PK900 | 99365-00900 |
| | | | | | PS+AC | 5PK1060 | 99365-01060 |
| | | | | | AC | 5PK880 | 99365-00880 |
| | EL41(ATM) | 1300 | 4E-FE | 90~94 | FAN | 4PK820 | 90916-02341 |
| | | | | | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK930 | 99364-00930/50930 |
| | | | | | PS+AC | 4PK1100 | 99364-01100/71100 |
| | | | | | AC | 4K845 | 90916-02200 |
| | | | | | AC | 4PK1080 | 99364-21080(W/PS) |
| | | | | | AC | 4PK1080 | 99364-71080(W/PS) |
| | EL41(MTM) | 1300 | 4E-FE | 90~94 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS+AC | 4PK930 | 99364-00930/50930 |
| | | | | | PS+AC | 4PK1090 | 99364-01090 |
| | | | | | AC | 4PK850 | 99364-00850/20850 |
| | | | | | AC | 4PK1070 | 99364-21070(W/PS) |
| | | | | | AC | 4PK1070 | 99364-71070(W/PS) |
| | EL51 | 1300 | 4E-FE | 94~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | AC | 4PK1080 | 99364-21080(W/PS) |
| | | | | | AC | 4PK930 | 99364-80930(W/0 PS) |
| | EL31(ATM) | 1500 | 3E | 88~90 | FAN | 4PK820 | 90916-02341 |
| | | | | | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 5PK940 | 99365-50940 |
| | | | | | PS+AC | 5PK1100 | 99365-01100 |
| | | | | | AC | 5PK890 | 99365-50890 |
| | EL31(MTM) | 1500 | 3E | 88~90 | FAN | 4PK815 | 90916-02332 |
| | | | | | PS | 5PK930 | 99365-00930 |
| | | | | | PS+AC | 5PK1100 | 99365-01100 |
| | | | | | AC | 5PK890 | 99365-50890 |
| | | 1500 | 3E | 88~90 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | FAN | 4PK820 | 99364-20820 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02332 (MTM) |
| | | | | | PS | 5PK940 | 99365-50940 |
| | | | | | PS+AC | 5PK1100 | 99365-01100 |
| | | | | | PS+AC | 5PK1110 | 99365-81110 |
| | | | | | AC | 5PK890 | 99365-50890 |
| | | | | | AC | 5PK900 | 99365-00900 |
| | EL31(TB) | 1500 | 3E-TE | 86~88 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | FAN | 4PK815 | 90916-02135 (MTM) |

# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| TERCEL · CORSA · COROLLA II | EL31(TB) | 1500 | 3E-TE | 86~88 | PS | 5PK950 | 99365-50950 |
| | | | | | PS+AC | 5PK1110 | 90916-02116 |
| | | | | | AC | 5PK890 | 99365-50890 |
| | | | | 88~90 | FAN | 4PK820 | 90916-02212 |
| | | | | | PS | 5PK940 | 99365-50940 |
| | | | | | PS+AC | 5PK1120 | 99365-51120 |
| | | | | | AC | 5PK910 | 99365-50910 |
| | | | | 88~90 | FAN | 4PK820 | 90916-02341 (ATM) |
| | | | | | PS | 5PK940 | 99365-50940 |
| | | | | | AC | 5PK1110 | 99365-51110(W/PS) |
| | EL43, EL45 | 1500 | 5E-FE/FHE | 90~94 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS | 4PK940 | 99365-00940 |
| | | | | | AC | 4PK1090 | 99364-01090/21090 |
| | EL53, EL55 | 1500 | 5E-FE/FHE | 94~99 | FAN | 4PK820 | 99364-20820 |
| | | | | | PS+AC | 4PK940 | 99364-20940 |
| | | | | | PS+AC | 4PK1000 | 99364-81000(~96/11) |
| | | | | | PS+AC | 4PK1110 | 99364-21110(96/11~) |
| | NL30(DSL) | 1500 | 1N-T | 86~89 | PS | 5PK870 | 99365-50870 |
| | | | | | AC | 5PK970 | 90916-02163(W/PS) |
| | | | | | AC | 5PK855 | 90916-02164 |
| | | | | 88~90 | PS | 5PK870 | 99365-50870 |
| | | | | | AC | 5PK975 | 90916-02225(W/PS) |
| | | | | | AC | 5PK870 | 90916-02226 |
| | NL40(DSL) | 1500 | 1N-T | 90~94 | PS | 5PK870 | 99365-50870 |
| | | | | | AC | 5PK970 | 99365-00970(ATM) |
| | | | | | AC | 5PK980 | 99365-20980(MTM) |
| | NL50(DSL) | 1500 | 1N-T | 94~99 | PS | 5PK870 | 99365-80870 |
| | | | | | AC | 5PK980 | 99365-20980 |
| TOWNACE · LITEACE | YR26V | 1600 | 1Y-J | 82~88 | FAN | 5PK820 | 99365-50820 |
| | YR25V, YR28G | 1800 | 2Y-U | 85~96 | FAN | 5PK820 | 99365-80820 |
| | YM55, YM60 | 1800 | 2Y-U | 86~99 | FAN | 5PK820 | 99365-50820 |
| | YR21G, YR30G, YG36G | 2000 | 3Y-EU | 83~96 | FAN | 5PK820 | 99365-80820 |
| | CM30G, CM31V(DSL) | 2000 | 2C/2C-T | 90~92 | PS | 3PK800 | 99363-00800 |
| | CR27V, CR36V(DSL) | 2000 | 2C/2C-T | 92~93 | PS | 3PK795 | 90916-02363 |
| | CM36V, CM40G, CM41V | | | 93~96 | PS | 3PK835 | 90916-02399 |
| | CR21G, CR27V(DSL) CR30G, CR36V | 2000 | 2C-T | 90~92 | PS | 3PK800 | 99363-00800 |
| | CR21G, CR28G(DSL) CR30G, CR37G | 2000 | 2C-T | 92~93 | PS | 3PK795 | 90916-02363 |
| | CM51, CM52(DSL) CM55,CM60 | 2000 | 2C | 90~99 | PS | 3PK1090 | 99363-21090 |
| | CR22G, CR29G(DSL) CR31G, CR39G | 2000 | 3C-T | 93~96 | PS | 3PK835 | 90916-02399 |
| TOWNACE NOAH | CR41V, CR51V(DSL) | 2000 | 2C | 96~98 | PS | 3PK810 | 99363-30810 |
| · LITEACE NOAH | SR40G, SR50G | 2000 | 3S-FE | 96~01 | FAN | 5PK995 | 90916-02355/6 |
| | | | | | PS | 4PK960 | 99364-30960 |
| | | | | | AC | 5PK1100 | 99365-31100 |
| | CR40G, CR50G(DSL) | 2200 | 3C-T/TE | 96~01 | PS | 3PK810 | 99363-30810 |
| VEROSSA | | 2000 | 1G-FE | 01~04 | FAN | 4PK1070 | 90916-02471 |
| | | | | | PS | 3PK890 | 99363-00890 |
| | | | | | AC | 4PK880 | 99364-90880 |
| VITZ | SCP10 | 1000 | 1SZ-FE | 99~04 | FAN+AC | 4PK1770 | 90916-02471/6 |
| | | | | | ALT | 6PK780 | 99366-20780/80780 |
| | NCP10, NCP15 | 1300 | 2NZ-FE | 99~04 | FAN | 4PK920 | 90916-02489/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| | NCP95 | 1300 | 2NZ-FE | 05~ | FAN | 4PK1180 | 90916-02500/02501 |
| | | | | | PS | 3PK850 | 90916-02575 |
| | NCP13 | 1500 | 1NZ-FE | 00~05 | PS | 3PK850 | 90916-02575 |
| | NCP91 | 1500 | 1NZ-FE | 05~ | FAN | 4PK1180 | 90916-02500/02501 |
| | | | | | PS | 3PK850 | 90916-02575 |
| WILL CYPHA | NCP70 | 1300 | 2NZ-FE | 02~05 | FAN | 4PK1180 | 90916-02501 |
| | | | | | AC | | WITH FAN |
| WiLL Vi | NCP19 | 1300 | 2NZ-FE | 00~ | FAN | 4PK920 | 90916-02489/9 |
| | | | | | FAN+AC | 4PK1180 | 90916-02500/1 |
| | | | | | PS | 3PK850 | 99363-30850/90850 |
| | | | | | AC | | WITH FAN |
| WiLL Vs | ZZE127, ZZE129 | 1800 | 1ZZ-FE | 01~ | FAN | 6PK1810 | 90916-02506 |
| | | | | | PS | | WITH FAN |

# TOYOTA





| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| WiLL Vs | ZZE127, ZZE129 | 1800 | 1ZZ-FE | 01~ | AC | | WITH FAN |
| | ZZE128 | 1800 | 2ZZ-FE | 01~04 | FAN | 6PK1870 | 90916-02504 |
| | | | | | PS | | WITH FAN |
| | | | | | AC | | WITH FAN |
| WINDOM | MCV21 | 2500 | 2MZ-FE | 96~01 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| | VCV11 | 2500 | 4VZ-FE | 93~96 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK805 | 90916-02352 |
| | VCV10 | 3000 | 3VZ-FE | 91~96 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK805 | 90916-02352 |
| | | | | | AC | 6PK1050 | 90916-02373/4 |
| | MCV20 | 3000 | 1MZ-FE | 96~01 | FAN+AC | 6PK1050 | 90916-02373/4 |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |
| | | | | 01~ | FAN+AC | 6PK1040 | 99366-81040 |
| | | | | | PS | 4PK880 | 99364-30880 |
| | | | | | PS | 4PK880 | 90080-91088 |



# TOYOTA

| Car Name | Car Model | ENGINE | | Year | Application | DRB No. | OEM No. |
|---|---|---|---|---|---|---|---|
| | | Displacement | Model | | | | |
| | | | | | | | |
| | | | | | | | |
| | | |

# Troubleshooting for
# RAW EDGE BELTS & V-RIBBED Belt

| SYMPTOMS | | PROBABLE CAUSE | SOLUTIONS |
|---|---|---|---|
| CRACKS |  | - Pulleys too small<br>- Excessively hot drive environment<br>- Dust or chemicals in drive | - Increase pulley diameter, check drive design<br>- Improve ventilation<br>- Use adequate guard |
| |  | - Belt used for too long | - Replace belt |
| |  | - Excessive load or shock load<br>- Foreign materials in drive<br>- Damaged tension members | - Check drive design, redesign<br>- Use adequate guard<br>- Follow correct installation procedures |
| |  | - Oil contamination<br>- Belt slip | - Clean oil contamination<br>- Readjust tension |
| |  | - Oil contamination<br>- Belt slip or insufficient tension<br>- Misalignment<br>- Small pulley diameter | - Clean oil contamination<br>- Readjust tension<br>- Check alignment and correct<br>- Increase pulley diameter, check drive design |
| TURNOVER OR TWIST |  | - Misalignment<br>- Foreign materials in pulley<br>- Insufficient tension<br>- Damaged cord<br>- Mismatched belt set | - Check alignment<br>- Clean pulley<br>- Readjust tension<br>- Replace belt, follow correct installation<br>- Replace with a new matched set of belts |
| |  | - Worn or damaged pulley<br>- Insufficient tension<br>- Poor drive design | - Replace pulley<br>- Readjust tension<br>- Redesign drive load |

# Troubleshooting for **TIMING BELT**

| SYMPTOMS | | PROBABLE CAUSE | SOLUTIONS |
|---|---|---|---|
| **CRACKS** |  | - Misalignment<br>- Bent, rough or damaged flange<br>- Improper tension<br>- Belt too wide | - Check alignment and correct<br>- Straighten or replace flange<br>- Readjust tension<br>- Replace with correct belt |
| |  | - Excessive load<br>- Insufficient tension<br>- Misalignment<br>- Incorrect belt<br>- Worn, damaged or rough sprocket | - Excessive load<br>- Insufficient tension<br>- Misalignment<br>- Incorrect belt<br>- Worn, damaged or rough sprocket |
| |  | - Excessive load<br>- Less than 6 teeth in mesh<br>- Misalignment<br>- Incorrect belt<br>- Worn sprocket<br>- Insufficient tension | - Increase drive load<br>- Redesign drive<br>- Check alignment and correct<br>- Replace with correct belt for sprocket<br>- Readjust tension |
| |  | - Diameter too small<br>- Improper ambient temperature<br>- Backside idler | - Increase diameter or redesign drive load<br>- Eliminate cause and change the blet<br>- Use inside idler |
| |  | - Excessive shock load<br>- Diameter too small<br>- Damaged belt<br>- Foreign materials in drive | - Redesign drive load<br>- Increase diameter or redesign<br>- Follow correct installation procedures<br>- Use adequate guard |
| |  | - Misalignment<br>- Excessive tension<br>- Incorrect belt | - Check alignment and correct<br>- Readjust tension<br>- Replace with correct belt for sprocket |
| | Tension loss | - Excessive load<br>- Diameter too small<br>- Worn sprocket<br>- Excessive temperature | - Adjust drive load<br>- Increase diameter or redesign<br>- Replace sprocket<br>- Check tension or conductive heat transfer |
| | Noise | - Improper tension<br>- Misalignment<br>- Incorrect belt<br>- Diameter too small<br>- Worn sprocket<br>- Bent guide flange | - Readjust tension<br>- Check alignment and correct<br>- Replace with correct belt for sprocket<br>- Increase diameter or redesign<br>- Replace sprocket<br>- Replace guide flange |
| | Vibration | - Improper tension<br>- Incorrect belt<br>- Bushing or key loose | - Readjust tension<br>- Replace with correct belt for sprocket<br>- Check and tighten |

# WARNING / CAUTION

**WARNING**

- DRB automotive belts are for use in cars only.
- Be sure that operators have no loose articles of clothing, or loose hair, as there is a danger that they may be pulled into the rotating part of the pulley belt.
- When proceeding with repair, check or exchange of a belt, be sure that the belt is stopped after switching it off.
- Be sure that no one switches on the machine in the middle of repair, check and exchange of a belt.

**WARNING**


- When replacing a belt or pulley, use one with the same specifications as the original one.
- Do not attempt to cut part of a belt with a knife or a scissors when tension is applied to the belt. It may cause the belt to bounce and hurt someone nearby.
- Align a belt along the center of the pulley. Otherwise, the surface of the belt will wear unevenly, causing reduced durability.



**GOOD** **BAD** **BAD**

**WARNING**

- Do not touch a belt or pulley immediately after operation. It is hot and you may get burned.
- Any attempt to change a belt should be made with no tension applied to the belt otherwise belt life may be reduced.
- Always maintain specified tension applied to a belt or noise or damage may result.
- In case more than one belt is used with a pulley, be sure to exchange all belts at the same time. Otherwise, the belts may have reduced durability.




Install and maintain DRB automotive belts in accordance with the vehicle manufactur's maintenance manual. Failure to follow the manual could result in personal injury, property damage or early belt failure. DRB is not liable for any damage caused by failure follow recommended installation or maintenance.

Should you have any questions concerning safety or proper procedure, refer to the vehicle manufacturer's recommended maintenance manual or contact us, our distributor, or a qualified technician.

MEMO

MEMO

MEMO

www.drbworld.com


**DRB Industrial Co., Ltd.**

**Sales Office**

**DRB HQ / Overseas Sales Team**
28, Gongdandong-ro 55beon-gil, Geumjeong-gu, Busan, Korea
Tel. +82-51-520-9104 Fax. +82-51-523-2537

**DRB America**
16811 Knott Ave. La Mirada, CA 90638, USA
Tel. +1-714-739-2922 Toll Free. +1-888-860-4450 Fax. +1-714-739-2925

**DRB Japan**
7F, CR Hakata Bldg., 1-8-6, Hakataeki-minami, Hakata-ku, Fukuoka-city, 812-0016, Japan
Tel. +81-92-481-7303 Fax. +81-92-481-7307

**DRB China**
Room 503, Zhidi Building, No 3217, Hongmei Rd, Shanghai, 201103, China
Tel. +86-21-5422-5691 Fax. +86-21-5422-5697

**DRB Indonesia**
Graha Pratama Lt.3, Jl. Letjen M. T. Haryono Kav.15, Tebet Barat, Jakarta 12810 Indonesia
Tel. +62-21-8379-7800 Fax. +62-21-8379-7799

**DRB Vietnam**
Tang4. No.17, 172/1 Nguyen Tuan Street, Nhan Chinh Ward, Thanh Xuan District, Hanoi, Vietnam
Tel. +84-4-6285-4028 Fax. +84-4-6285-4029



※ No content in this catalog may be copied without our prior consent under the intellectual Property Protection Law.
※ Please be sure to check the current specifications of a product as those stated in this catalog may be changed without a prior notice.



PT-C-160725-EN